

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20012203/EGA3Q2

Date:

28/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100491517

Claimant Vehicle No : SH7142K**Insured Vehicle No :**

SLF9169P

Date of Loss: 05/11/2020

Nature of Claim:

TP

Claim No:

2070482601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SH7142K

Make & Model:

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDGU669985

Reg. Date:

14/04/2016 (Man. Year: 2015)

Chassis No:

KMHLB41UMGU087062

Colour:

Blue

Odometer:

890098 km

Engine Capacity:

1685 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

Goodyear 5 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side:

Goodyear 5 mm

Rear Right Side:

Goodyear 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,129.96	2,112.36	17.60	0.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	480.00	120.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,729.96	2,592.36	137.60	5.04
Approved Total (Overridden) (S\$)		2,050.00		

(S\$)	2,729.96	2,050.00	679.96	24.91
+ GST 7.00/7.00% (S\$)	191.10	143.50	47.60	24.91
Nett Amount (S\$)	2,921.06	2,193.50	727.56	24.91
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$114.95/day) (S\$)		229.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,525.40		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 06/11/2020

Estimated Period of Repair: 2.0 days

Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG	Damaged	1,052.20 FL	*1,052.20 FL
2	2		*HYUNDAI BUMPER COVER CLIP	Not Necessary	22.00 FL	*- FL
3	1		*GRILLE ASSY -RADIATOR	Broken	1,480.00 FL	*1,480.00 FL
4	1		*SYMBOL MARK -H	Necessary	39.50 FL	*39.50 FL
5	1		*NO PLATE (S) WITH TRIM COV	Broken	55.00 FS	*55.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,648.70	2,626.70
- List Item Discount on L Items 20.00/20.00% (\$\$)					518.74	514.34
Total Parts (\$\$)					2,129.96	2,112.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	280.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
Gross Labour Cost (S\$)			600.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >