

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012216/QQF3E2

Date: 19/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900131113
Claimant Vehicle No : SCY1116B	Insured Vehicle No : SMN2321H
Date of Loss: 05/11/2020	Nature of Claim: TP Claim No: 9264528811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY1116B		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5081699
Reg. Date:	19/05/2016 (Man. Year: 2016)	Chassis No:	RU31131675
Colour:	Black	Odometer:	121656 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/11/2020	
Date Inspected:	09/11/2020 Inspected At:	Wei Car Spray Painting (HQ) 1017 YISHUN INDUSTRIAL PARK A #01-242 Singapore 768759
Estimated Period of Repair:	6.0 days	

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	0.00 F	*- F
2	1		*REAR BUMPER SIDE LH	Crumpled	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
8	1		*REAR END PANEL INNER TRIM BOX	Crumpled	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*TAILGATE	Dented	0.00 F	*- F
11	1		*TAILGATE LAMP	Cracked	0.00 F	*- F
12	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
14	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
15	1		*TAILGATE RUBBER	Crumpled	0.00 F	*- F
16	1		*TAILGATE INNER BOARD TRIM	Crumpled	0.00 F	*- F
17	1		*SPARE TYRE BOARD TOP	Crumpled	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Crumpled	0.00 F	*- F
19	1		*SPARE TYRE COVER OUTER UNDER	Crumpled	0.00 F	*- F
20	1		*REAR LH FENDER PROTECTOR	Deformed	0.00 F	*- F
21	2		*REAR FLOOR PANEL LH / RH	Crumpled	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >