

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012218/ETF3E2

Date: 20/11/2020

REFERENCE

| | |
|--|--|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 2100330000 |
| Claimant Vehicle No : FBQ8700Y | Insured Vehicle No : SKJ451Z |
| Date of Loss: 28/10/2020 | Nature of Claim: TP Claim No: 8007828942SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | FBQ8700Y | | |
| Make & Model: | HONDA CBR150R, 150cc | Engine No: | KC92E1026565 |
| Reg. Date: | 26/12/2019 (Man. Year: 2019) | Chassis No: | MH1KC9219KK028939 |
| Colour: | Red | Odometer: | 8541 km |
| Engine Capacity: | 149 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 100/80-17 | Rear Tyre Size: | 140/60-17 |
| Front Left Side: | Pirelli 5 mm | Rear Left Side: | Pirelli 5 mm |
| Front Right Side: | 0 mm | Rear Right Side: | 0 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 09/11/2020 | |
| Date Inspected: | 09/11/2020 Inspected At: | 149 KAKI BUKIT AVE 1 SOON LEE INDUSTRIAL PARK |
| | | Repairer : Garage 13 Pte. Ltd. (HQ) |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|------------------------------|-----------|--------------------------|------------------|
| 1 | 1 | | *FRONT NUMBER PLATE | Necessary | 0.00 F | *- F |
| 2 | 1 | | *FRONT RIM | Cut | 0.00 F | *- F |
| 3 | 1 | | *FRONT FENDER WHEEL GUARD | Cut | 0.00 F | *- F |
| 4 | 1 | | *FRONT FORK ASSY | * Check | 0.00 F | *- F |
| 5 | 1 | | *FRONT HEADLAMP | Cut | 0.00 F | *- F |
| 6 | 1 | | *FRONT WINDSHIELD | Cut | 0.00 F | *- F |
| 7 | 2 | | *FRONT WING MIRROR | Cut | 0.00 F | *- F |
| 8 | 1 | | *FRONT LH SIGNAL LAMP | Cut | 0.00 F | *- F |
| 9 | 1 | | *FRONT RH SIGNAL LAMP | Broken | 0.00 F | *- F |
| 10 | 1 | | *ERP BRACKET | Missing | 0.00 F | *- F |
| 11 | 1 | | *ERP UNIT | Cut | 0.00 F | *- F |
| 12 | 1 | | *STEERING CONE | * Check | 0.00 F | *- F |
| 13 | 2 | | *HANDLE BAR | Bent | 0.00 F | *- F |
| 14 | 1 | | *HANDLE BAR BALANCER RH | Cut | 0.00 F | *- F |
| 15 | 1 | | *CLUTCH LEVER | Cut | 0.00 F | *- F |
| 16 | 1 | | *HAND BRAKE LEVER | Cut | 0.00 F | *- F |
| 17 | 2 | | *SIDE FAIRING | Cut | 0.00 F | *- F |
| 18 | 2 | | *SIDE FAIRING INNER GARNISH | Cut | 0.00 F | *- F |
| 19 | 2 | | *FAIRING LOWER | Cut | 0.00 F | *- F |
| 20 | 1 | | *FOOT BRAKE | Bent | 0.00 F | *- F |
| 21 | 2 | | *FRONT FOOT REST | Cut | 0.00 F | *- F |
| 22 | 1 | | *FOOT GEAR SHIFTER | Bent | 0.00 F | *- F |
| 23 | 2 | | *EXHAUST MUFFLER HEAT SHIELD | Cut | 0.00 F | *- F |
| 24 | 1 | | *EXHAUST MUFFLER ASSY | Bent | 0.00 F | *- F |
| F=Franchise part. | | | | | | |
| | | | | | Total Parts (S\$) | 0.00 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >