



Your Ref : S0M02UGE

Date: 07<sup>th</sup> December 2020

Our Ref : CS4/ASM20012219/Nsd3e2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Cynthia Loh

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBQ 4513Y  
ACCIDENT ON 19/09/2020**

Instruction was received to inspect the vehicle Reg. No. FBQ 4513Y. The inspection was conducted on 09/11/2020 at the premises of M/s Wing Fuat Trading Co, Blk 3020A Ubi Road 1 #01-37, Singapore 408714 .

The following vehicle information was recorded:

Registration Number	: FBQ 4513Y
Make/Model	: Honda CB400SF Manual
Year of Registration	: 2017
Body Colour	: Red
Chassis Number	: NC421803869
Engine Capacity	: 399 cc
Speedometer Reading	: Nil

The vehicle sustained damages at the front, rear portion, n/s and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value	S\$ 16,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,082.00)
Nett Liability	S\$ 11,918.00
	=====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.