

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012220/ATF3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant: DEBETS FRANK JOZEF CHRISTIAAN Policy No: 1800152156
Date of Loss: 06/10/2020 Nature of Claim: OD Claim No: 1870351062SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG8340A**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK073246
Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: WAUZZZF58KA010127
Colour: Red Odometer: 9478 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,287.00	6,643.44	13,643.56	67.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,972.00	2,772.00	2,200.00	44.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,259.00	9,415.44	15,843.56	62.72
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	23,659.00	7,815.44	15,843.56	66.97
+ GST 7.00/7.00% (S\$)	1,656.13	547.08	1,109.05	66.97
Nett Amount (S\$)	25,315.13	8,362.52	16,952.61	66.97

INSPECTION

Date of Assignment: 09/11/2020
Date Inspected: 06/11/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	225.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	529.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	62.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	2,300.00 FS	*1,840.00 FS
9	2		*ULTRASOUND SENSOR SUPPORT - LH / RH	Necessary	102.00 FS	*80.80 FS
10	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	187.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	468.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	123.00 FS	*98.40 FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
16	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
17	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
18	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
19	1		*FRONT PARKING AID SENSOR - INNER	Not Necessary	242.00 FS	*- FS
20	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*HORN - LH HIGH TONE	Not Necessary	124.00 FS	*- FS
22	1		*SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
23	1		*LED HEADLIGHT - LH	Not Necessary	7,812.00 FS	*- FS
24	1		*LIFT CYLINDER - LH	Not Necessary	196.00 FS	*- FS
25	1		*RADIATOR AIR GUIDE - INNER	Deformed	31.00 FS	*24.64 FS
26	1		*RADIATOR AIR GUIDE - OUTER	Not Necessary	16.00 FS	*- FS
27	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
28	1		*SUNDRIES	Necessary	300.00 FS	*8.96 FS
29	1		*BONNET (Supplementary)	Buckled	3,312.00 FS	*2,649.60 FS
30	1		*BONNET IMPACT PROTECTION - CENTER (Supplementary)	Necessary	28.00 FS	*22.00 FS
31	2		*BONNET IMPACT PROTECTION - LH / RH (Supplementary)	Necessary	56.00 FS	*43.68 FS
32	1		*OUTER TEMPERATURE SENSOR BRACKET (Supplementary)	Cracked	19.00 FS	*14.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,287.00 6,643.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISMANTLE AND RENEW BONNET (Supplementary)	New	800.00	500.00
7	TO RESPRAY BONNET (Supplementary)	New	900.00	550.00
Gross Labour Cost (\$\$)			4,972.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >