

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012221/KQF3E2

Date: 06/09/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/19-407757-CA
Claimant Vehicle No: EU4802G Insured Vehicle No: FBD2539E
Date of Loss: 25/10/2020 Nature of Claim: TP Claim No: MSC/V/20-000784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EU4802G**
Make & Model: AUSTIN MINI, 998cc (A) Engine No: 9DBUL2378
Reg. Date: 31/12/1961 (Man. Year: 1961) Chassis No: AA2S810127
Colour: Metallic Silver Odometer: 79282 km
Engine Capacity: 948 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/70 R13 Rear Tyre Size: 175/70 R13
Front Left Side: Falken 6 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,914.00	1,915.20	3,998.80	67.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	610.00	970.00	61.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,494.00	2,525.20	4,968.80	66.30
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	7,494.00	2,000.00	5,494.00	73.31

INSPECTION

Date of Assignment: 09/11/2020
Date Inspected: 13/11/2020 Inspected At: Heng Yap Seng Auto Services
160 Sin Ming Auto City, #08-13
Singapore 575722
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2021)	
Parts:	N/A	AUSTIN MINI 998cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EU4802G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,920.00 F	*1,920.00 FL
2	1		*REAR BUMPER BRACKETS	N/S Distorted	416.00 F	*208.00 FL
3	1		*SET REAR BUMPER CLIPS	Not Necessary	40.00 F	*- FL
4	1		*REAR FENDER LH	Repair	1,760.00 F	*- FL
5	1		*TAILLAMP LH	Serviceable	458.00 F	*- FL
6	1		*REAR END PANEL	Repair	1,320.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,914.00	2,128.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	212.80
Total Parts (\$)	5,914.00	1,915.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	600.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	600.00	200.00
3	TO REMOVE, REPLACE REAR FENDER TO FACILITATE REPAIR	New	300.00	0.00
4	TO CHECK WIRING AND LIGHTINGS	New	80.00	10.00
			Gross Labour Cost (\$)	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >