

# HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722  
Hp : 9183 3008 Fax : 6873 2017

Vehicle No : EU4802G  
Vehicle Model : Austin 1000

Date : 02.02.2021

## Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Rear bumper
2	2	Rear bumper brackets
3	1 set	Rear bumper clips
4	1	Rear fender LH
5	1	Taillamp LH
6	1	Rear end panel

*Not Authorised  
61 Day @ 2000k  
Resurvey After Paint 3 days*

Bu	\$	1,920.00	✓
als	\$	416.00	✓
	\$	40.00	✓
n	\$	1,760.00	✓
	\$	458.00	✓
	\$	1,320.00	✓
Total	\$	5,914.00	

10%

## Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	600.00	400
2	To putty and respray painting on affected areas.	\$	600.00	200
3	To remove, replace rear fender to facilitate repair.	\$	300.00	✓
4	To check wiring and lightings.	\$	80.00	100

Total Labour \$ 1,580.00

Total Parts and Labour \$ 7,494.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: