



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TRC 9397S (XD 3722A)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	TRAILER SUSPENSION AXLE ASSY (USED) NO.1 & 2 @ \$4500.00 (SN)	REPLACED	9,000.00	8,000.00
2	SETS TRAILER SUSPENSION LEAF SPRINGS - NO.1 @ \$850.00 (SN)	REPLACED	1,700.00	1,700.00
2	SETS TRAILER SUSPENSION LEAF SPRINGS - NO.2 @ \$850.00 (SN)	NOT NECESSARY	1,700.00	-
2	LEAF SPRING SUPPORT BRACKET RH @\$450.00 (SN)	REPLACED (1PC ONLY)	900.00	450.00
2	LEAF SPRING SUPPORT BRACKET LH @\$450.00 (SN)	REPLACED (1PC ONLY)	900.00	450.00
2	LEAF SPRING BRACKET CROSSMEMBER @\$550.00 (SN)	REPLACED (1PC ONLY)	1,100.00	550.00
4	LEAF SPRING BRACKET LOCK NUTS @\$280.00 (SN)	REPLACED (2PCS ONLY)	1,120.00	560.00
8	LEAF SPRING 'U' BOLT @\$45.00 (SN)	REPLACED (4PCS ONLY)	360.00	180.00
4	LEAF SPRING 'U' BOLT BRACKET @\$65.00 (SN)	REPLACED (2PCS ONLY)	260.00	130.00
4	AXLE ADJUSTABLE CONTROL ARM @\$350.00 (SN)	REPLACED (2PCS ONLY)	1,400.00	700.00
8	AXLE ADJUSTABLE CONTROL ARM BOLT @\$45.00 (SN)	REPLACED (4PCS ONLY)	360.00	180.00
16	AXLE ADJUSTABLE CONTROL ARM BUSH @\$35.00 (SN)	REPLACED (8PCS ONLY)	560.00	280.00
4	BRAKE AIR CHAMBERS @\$350.00 (SN)	REPLACED (2PCS ONLY)	1,400.00	700.00
4	BRAKE AIR CHAMBER HOSE @\$60.00 (SN)	REPLACED (2PCS ONLY)	240.00	120.00
3	REAR WHEEL GUARD RH @\$220.00 (SN)	REPLACED	660.00	660.00
1	REAR WHEEL GUARD LH (SN)	NOT NECESSARY	220.00	-
4	REAR WHEEL GUARD SUPPORT @\$60.00 (SN)	REPLACED (2PCS ONLY)	240.00	120.00
3	REAR WHEEL RIM RH @\$800.00 (SN)	REPLACED (1PC ONLY)	2,400.00	800.00
2	REAR TYRE LH @\$550.00 (SN)	NOT NECESSARY	1,100.00	-
1	SIDE PROTECTION RAILING ASSY RH (SN)	REPAIRED SEE LABOUR	1,200.00	-

Report Ref No. CS/LAW20012228/Dqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
4	REAR TYRE RH @\$550.00 (SN)  <u>LABOUR</u>  TO RESPRAY PAINTING & ETC.  PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF SIDE PROTECTION RAILING ASSY RH.	REPLACED (1PC ONLY)(60%)	2,200.00	330.00
			29,020.00	15,910.00
			1,200.00	400.00
			1,800.00	1,200.00
			3,000.00	1,600.00
GRAND TOTAL			32,020.00	17,510.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,000.00

Report Ref No. CS/LAW20012228/Dqf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.