

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012238/QBS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900263801

Claimant
Vehicle No : SLB5907Z **Insured Vehicle No :** SMS8823K

Date of Loss: 07/11/2020 Nature of Claim: TP Claim No: 6701228596SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5907Z		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	L15B3534705
Reg. Date:	14/04/2016 (Man. Year: 2015)	Chassis No:	GK81003966
Colour:	Silver	Odometer:	359089 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,038.48	10,847.92	8,190.56	43.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,140.00	3,170.00	2,970.00	48.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,178.48	14,017.92	11,160.56	44.33
Approved Total (Overridden) (S\$)		11,200.00		
(S\$)	25,178.48	11,200.00	13,978.48	55.52
+ GST 7.00/7.00% (S\$)	1,762.49	784.00	978.49	55.52
Nett Amount (S\$)	26,940.97	11,984.00	14,956.97	55.52
+ Loss of Use (11.0 x S\$70.00/day) (S\$)		770.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,756.00		
Global Sum Settlement (S\$)		12,700.00		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 09/11/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 9.0 days

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE BACK TRIM COVER	Serviceable	580.00 FL	*- FL
3	1		*REAR TAILGATE LOCK	Jammed	550.00 FL	*278.00 FL
4	1		*REAR TAILGATE LOCK CATCH	Serviceable	158.00 FL	*- FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*140.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Broken	255.00 FL	*255.00 FL
7	1		*REAR TAILGATE HOLDER COVER	Crumpled	80.00 FL	*60.00 FL
8	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL
9	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL
10	1		*R/R TAILLAMP ASSY	Scratched	850.00 FL	*520.00 FL
11	1		*R/R TAILLAMP REFLECTOR	Scratched	720.00 FL	*485.00 FL
12	1		*L/R TAILLAMP ASSY	Serviceable	850.00 FL	*- FL
13	1		*L/R TAILLAMP REFLECTOR	Serviceable	720.00 FL	*- FL
14	1		*REAR WIPER MOTOR ASSY	Serviceable	680.40 FL	*- FL
15	1		*REAR WIPER LINKAGE	Serviceable	280.50 FL	*- FL
16	1		*REAR WIPER ARM	Serviceable	150.00 FL	*- FL
17	1		*REAR WIPER BLADE	Serviceable	120.50 FL	*- FL
18	1		*REAR TAILGATE SPARE TYRE COMPARTMENT	Crumpled	950.00 FL	*950.00 FL
19	1		*REAR BUMPER	Crumpled	1,350.00 FL	*1,050.00 FL
20	1		*REAR BUMPER LH SIDE RETAINER	Necessary	128.00 FL	*128.00 FL
21	1		*REAR BUMPER RH SIDE RETAINER	Necessary	128.00 FL	*128.00 FL
22	1		*REAR BUMPER LH REFLECTOR GARNISH COVER	Serviceable	178.00 FL	*- FL
23	1		*REAR BUMPER LH REFLECTOR	Serviceable	250.00 FL	*- FL
24	1		*REAR BUMPER SPONGE	Serviceable	150.00 FL	*- FL
25	1		*REAR END PANEL	Dented	1,200.00 FL	*790.00 FL
26	1		*REAR END PANEL TOP COVER	Crumpled	300.00 FL	*200.00 FL
27	1		*REAR BUMPER TOW COVER	Missing	30.00 FL	*30.00 FL
28	1		*REAR ANTENNA SENSOR	Serviceable	200.00 FL	*- FL
29	1		*FRONT BUMPER	Crumpled	1,350.00 FL	*850.00 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	660.00 FL	*425.00 FL
31	1		*RADIATOR GRILLE BASE	Serviceable	500.00 FL	*- FL
32	1		*RADIATOR GRILLE MOULDING	Serviceable	390.00 FL	*- FL
33	1		*F/R HEADLAMP ASSY	Scratched	2,100.00 FL	*2,100.00 FL
34	1		*F/L HEADLAMP ASSY	Cracked	2,100.00 FL	*2,100.00 FL
35	1		*FRONT GRILLE CENTER BRACKET	Serviceable	130.00 FL	*- FL
36	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
37	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
38	1		*SET BODY SEALANT	Necessary	300.00 FS	*40.00 FS
39	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
40	1		*SET END PANEL TO GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS
41	1		*SET FRONT & REAR NUMBER PLATE	Necessary	100.00 FS	*60.00 FS
42	1		*REAR RH TAILLAMP PANEL	Crumpled	680.00 FL	*420.00 FL
43	2		*FRONT HEADLAMP BRACKET	Cracked	240.00 FL	*240.00 FL
44	1		*FRONT BONNET	Dented	1,350.00 FL	*642.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,553.10	13,462.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,514.62	2,614.48
Total Parts (\$\$)	19,038.48	10,847.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REAR TAILGATE ,REAR BUMPER ,END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPARE TYRE PANEL INCLUDE CUTTING /WELDING OF DAMAGED PARTS	New	2,000.00	1,250.00
2	TO RESPRAY BOTH REAR FENDERS ,REAR TAILGATE ,REAR BUMPER,END PANEL AND SPARE TYRE PANEL (INNER/OUTER)	New	1,800.00	800.00
3	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPAIRS AND BONNET	New	800.00	500.00
4	TO RESPRAY FRONT BONNET AND FRONT BUMPER	New	600.00	400.00
5	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
6	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	40.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTIONS	New	300.00	0.00
9	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS AREQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,140.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >