

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20012239/UPA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKX3227L	Insured Vehicle No :	SHD6594Y
Date of Loss:	06/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX3227L	Engine No:	L15B4025073
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11105075
Reg. Date:	04/12/2015 (Man. Year: 2015)	Odometer:	101634 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,029.50	3,924.64	5,104.86	56.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,080.00	1,530.00	58.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,639.50	5,004.64	6,634.86	57.00
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,639.50	4,000.00	7,639.50	65.63
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,400.00		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment:	09/11/2020	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Date Inspected:	09/11/2020 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX3227L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	988.20 F	*762.30 FL
2	1		*FRONT BUMPER FOG LAMP O/S	Cracked	485.50 F	*380.50 FL
3	1		*FRONT BUMPER FOG LAMP COVER O/S	Twisted	166.30 F	*165.20 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	391.20 F	*371.30 FL
5	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	65.50 F	*41.50 FL
6	1		*FRONT BUMPER LOWER SPOILER	Distorted	650.50 F	*488.20 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*FRONT GRILLE	Cracked	615.20 F	*542.20 FL
9	1		*HEADLAMP O/S	Cracked	1,939.20 F	*1,859.10 FL
10	1		*FRONT FENDER O/S	Repair	671.10 F	*- FL
11	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	215.30 F	*- FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	50.00 F	*- FL
13	1		*FRONT FENDER OUTER PROTECTOR O/S	Distorted	282.30 F	*245.50 FL
14	1		*FRONT SPORT RIM O/S	Repair	850.00 F	*- FL
15	1		*FRONT LOWER ARM O/S	Not Necessary	488.20 F	*- FL
16	1		*FRONT KNUCKLE ARM O/S	Not Necessary	455.30 F	*- FL
17	1		*FRONT KNUCKLE ARK BEARING O/S	Not Necessary	250.50 F	*- FL
18	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	415.20 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,029.50	4,905.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	981.16
Total Parts (\$\$)	9,029.50	3,924.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	New	180.00	0.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	400.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,610.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >