

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012241/UBA3Q2
Date: 28/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100426412
Claimant Vehicle No :	SGR3721E	Insured Vehicle No :	SKU9858S
Date of Loss:	08/11/2020	Nature of Claim:	TP
		Claim No:	3181012955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR3721E	Engine No:	1NZX506325
Make & Model:	TOYOTA VIOS, 1.5 E (M)	Chassis No:	MR053HY4204213146
Reg. Date:	07/02/2007 (Man. Year: 2006)	Odometer:	206122 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,466.00	2,097.12	11,368.88	84.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,070.00	2,300.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,836.00	4,167.12	13,668.88	76.64
Approved Total (Overridden) (S\$)		3,300.00		

(S\$)	17,836.00	3,300.00	14,536.00	81.50
+ GST 7.00/7.00% (S\$)	1,248.52	231.00	1,017.52	81.50
Nett Amount (S\$)	19,084.52	3,531.00	15,553.52	81.50
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,733.00		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 09/11/2020

Estimated Period of Repair: 4.0 days

 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	766.50 F	*- FL
2	1		*BOOTLID OUTER HANDLE	Not Necessary	198.10 F	*- FL
3	1		*BOOTLID REAR LOGO	Necessary	60.80 F	*60.80 FL
4	1		*BOOTLID VIOS EMBLEM	Necessary	55.20 F	*55.20 FL
5	1		*BOOTLID E EMBLEM	Not fitted	48.80 F	*- FL
6	1		*BOOTLID TRD EMBLEM	Necessary	65.00 F	*65.00 FL
7	1		*BOOTLID INNER LOCK	Not Necessary	199.40 F	*- FL
8	1		*BOOTLID LOCK STRIKER	Not Necessary	89.90 F	*- FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	266.50 F	*245.50 FL
10	2		*BOOTLID HINGES	Not Necessary	300.00 F	*- FL
11	1		*REAR BUMPER	Deformed	655.10 F	*366.30 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	153.00 F	*- FL
13	2		*REAR BUMPER BRACKETS	Not Necessary	198.20 F	*- FL
14	1		*REAR BUMPER LOWER SKIRTING	Not fitted	850.00 F	*- FL
15	2		*REAR BUMPER REFLECTORS	Not fitted	390.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*REAR EXHAUST	Not Necessary	588.10 F	*- FL
18	2		*REAR EXHAUST MOUNTINGS	Not Necessary	130.00 F	*- FL
19	1		*REAR END PANEL	Dented	655.20 F	*581.23 FL
20	1		*REAR END PANEL GARNISH	Twisted	315.10 F	*188.20 FL
21	2		*TAILLAMPS	Cracked	1,040.20 F	*850.60 FL
22	2		*TAILLAMPS HOUSING PANELS	Repair	399.00 F	*- FL
23	1		*REAR FLOOR PANEL	Not Necessary	911.20 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	422.50 F	*- FL
25	2		*REAR FLOOR PANEL SIDE TOOLS SPONGES	Not Necessary	778.20 F	*- FL
26	2		*REAR FENDERS	Not Necessary	1,690.20 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Not Necessary	573.00 F	*- FL
28	2		*REAR FENDER INNER SPLASH SHIELD	Not Necessary	210.00 F	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	66.80 F	*- FL
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
34	1		*REAR EXHAUST CHROME	Not Necessary	80.00 FS	*- FS
35	1		*BOOTLID TOP SPOILER	Not Necessary	680.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					13,466.00	2,712.83
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	615.71
Total Parts (S\$)					13,466.00	2,097.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	0.00
4	TO SPRAY RUST PROOFING	New	120.00	30.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	180.00	80.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,680.00	1,080.00
Gross Labour Cost (S\$)			4,370.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >