

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012242/ERS3Q2

Date: 16/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070011076

Claimant
Vehicle No : GBC1890B **Insured Vehicle No :** GBE7377S

Date of Loss: 06/11/2020 Nature of Claim: TP Claim No: 3833664333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1890B		
Make & Model:	CITROEN BERLINGO, 1.6 D (M)	Engine No:	10JBCB0186010
Reg. Date:	15/07/2011 (Man. Year: 2011)	Chassis No:	VF77B9HXCBJ547074
Colour:	Silver	Odometer:	171993 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,174.01	1,477.22	1,696.79	53.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	630.00	1,750.00	73.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,554.01	2,107.22	3,446.79	62.06
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	5,554.01	1,700.00	3,854.01	69.39
+ GST 7.00/7.00% (S\$)	388.78	119.00	269.78	69.39
Nett Amount (S\$)	5,942.79	1,819.00	4,123.79	69.39
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
Nett Liability (S\$)		2,169.00		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 09/11/2020 Inspected At:

Ryder Auto Workshop LLP (HQ)
1 Kaki Bukit Ave 6, #01-56, Autobay
@ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	631.80 FL	*631.80 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
4	2		*REAR BUMPER O/S & N/S RETAINER	Broken	166.20 FL	*166.20 FL
5	1		*REAR BUMPER ENFORCEMENT	Bent	347.10 FL	*347.10 FL
6	1		*REAR END PANEL	Repair	1,283.10 FL	*- FL
7	2		*REAR REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
8	2		*REAR REVERSE SENSOR WIRE HARNESS	Not Necessary	180.00 FS	*- FS
9	1		*REAR O/S & N/S DOOR (REPAIR) (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR DOOR WEATHERSTRIP	Not Necessary	180.00 FL	*- FL
11	1		*REAR DOOR CITROEN EMBLEM	Necessary	86.50 FL	*86.50 FL
12	1		*REAR DOOR BERLINGO EMBLEM	Necessary	88.60 FL	*88.60 FL
13	1		*REAR DOOR C&C EMBLEM	Necessary	65.60 FL	*65.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,458.90	1,615.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	284.89	138.58
Total Parts (\$\$)	3,174.01	1,477.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,200.00	300.00
2	TO SPRAY PAINTING	New	1,000.00	300.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO RE-SEAL ANTI-RUST	New	80.00	0.00
Gross Labour Cost (\$\$)			2,380.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >