



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2101008

INV Date 17/02/2021

Reference CC4/LPC20012246/Gba3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKT 2281G
Insured Veh. GBB 8332E
Claim No. 20/20/20/VC05/023875
Policy No. Z20VC05005997
Accident Date 07/11/2020
Inspection Date 09/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20012246/Gba3q2	
			Date: 17/02/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 8332E	Veh. Inspected	SKT 2281G
	Policy No.	Z20VC05005997	Coverage (\$)	0.00
	Claim No.	20/20/20/VC05/023875	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	09/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI OUTLANDER 2.4	c.c	2360
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JMYXTGF3WFZ002036	Colour	RED
	Odometer	71231 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/11/2020	Inspection Date	09/11/2020
	Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2281G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	C&C LOGO (SN)	NECESSARY	50.00	50.00
1	MIVEC EMBLEM (SN)	NECESSARY	50.00	50.00
1	REAR AND FRONT NUMBER PLATE WITH CASING (SN)	BENT	100.00	100.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	280.00
1	TAIL GATE PANEL ASSY (SN)	BUCKLED	1,130.00	1,130.00
1	TAILGATE GARNISH (SN)	DEFORMED	759.00	759.00
1	MARK ,THREE-DIA (SN)	NECESSARY	63.00	63.00
1	MARK,OUT HANDER (SN)	NECESSARY	95.00	95.00
1	GLASS ,TAILGATE WINDO (SN)	NECESSARY	751.00	751.00
2	SIDE DAM ,TAILGATE (SN)	NECESSARY	54.00	54.00
1	UPR DAM ,TAILGATE (SN)	NECESSARY	13.00	13.00
1	LATCH ,TAILGATE (SN)	BENT	475.00	475.00
1	MOTOR ,POWER TAILGATE (SN)	NOT NECESSARY	1,986.00	-
1	LH SENSOR ,TAILGATE L (SN)	NOT NECESSARY	426.00	-
1	RH SENSOR ,TAILGATE L (SN)	NOT NECESSARY	426.00	-
1	LH GAS SPRING ,TAILGA (SN)	NOT NECESSARY	192.00	-
1	RH GAS SPRING ,TAILGA (SN)	NOT NECESSARY	192.00	-
1	SWITCH ,POWER TAILGAT (SN)	NOT NECESSARY	72.00	-
1	BUZZER ,WARNING (SN)	NOT NECESSARY	41.00	-
1	LABEL ,TAILGATE CAUTI (SN)	NECESSARY	10.00	10.00
1	WEATHERSTRIP ,TAILGAT (SN)	TWISTED	213.00	213.00
1	TRIM ,TAILGATE (SN)	DEFORMED	329.00	329.00
1	RR LH LAMP ASSY ,COM (SN)	CRACKED	590.00	590.00
1	RR RH LAMP ASSY ,COMB (SN)	NOT NECESSARY	590.00	-
1	LH REFLECTOR ,TAIL L (SN)	CRACKED	171.00	171.00
1	RH REFLECTOR ,TAIL L (SN)	NOT NECESSARY	171.00	-
1	FACE ,RR BUMPER (SN)	DEFORMED	1,063.00	1,063.00
2	CLIP ,RR BUMPER (SN)	NECESSARY	4.00	4.00
2	CLIP ,RR BUMPER (SN)	NECESSARY	8.00	8.00
1	BRACKET ,RR BUMPER F (SN)	DEFORMED	12.00	12.00
1	BRACKET ,RR BUMPER F (SN)	NOT NECESSARY	12.00	-

Report Ref No. CC4/LPC20012246/Gba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH REINFORCEMENT ,RR (SN)	BENT	79.00	79.00
1	LH SIDE GARNISH ,RR (SN)	DEFORMED	64.00	64.00
1	RH SIDE GARNISH ,RR (SN)	NOT NECESSARY	63.00	-
1	EXTENSION ,RR BUMPER (SN)	CUT	516.00	516.00
2	CLIP ,RR BUMPER (SN)	NECESSARY	4.00	4.00
8	RIVET ,RR BUMPER (SN)	NECESSARY	32.00	32.00
7	CLIP ,RR BUMPER (SN)	NECESSARY	42.00	42.00
1	LH MOULDING ,RR BUMP (SN)	DEFORMED	106.00	106.00
1	RH MOULDING ,RR BUMP (SN)	NOT NECESSARY	106.00	-
1	LH MOULDING ,RR WHEE (SN)	DEFORMED	199.00	199.00
1	RH MOULDING ,RR WHEE (SN)	NOT NECESSARY	199.00	-
1	TRIM,RR END (SN)	DEFORMED	123.00	123.00
1	BOX ,CARGO FLOOR (SN)	DEFORMED	204.00	204.00
1	BUZZER ,KEYLESS OPER (SN)	DAMAGED	91.00	91.00
1	ANTENNA ,KEYLESS OPE (SN)	NOT NECESSARY	96.00	-
1	HARNESS ,RR BUMPER (SN)	NOT NECESSARY	66.00	-
1	HARNESS ,RR END (SN)	NOT NECESSARY	82.00	-
1	FACE ,FR BUMPER (SN)	DEFORMED	1,036.00	1,036.00
1	EXTENSION ,FR BUMPER (SN)	CUT	380.00	380.00
1	GRILLE ,FR BUMPER (SN)	NOT NECESSARY	182.00	-
5	CLIP ,FR BUMPER (SN)	NECESSARY	10.00	10.00
4	CLIP ,FR BUMPER (SN)	NECESSARY	12.00	12.00
2	CLIP ,FR BUMPER (SN)	NECESSARY	6.00	6.00
1	LH SIDE BRACKET ,FR (SN)	DEFORMED	24.00	24.00
1	RH SIDE BRACKET ,FR B (SN)	DEFORMED	24.00	24.00
8	RIVET ,FR BUMPER (SN)	NECESSARY	32.00	32.00
1	LH REINFORCEMENT ,FR (SN)	NOT NECESSARY	7.00	-
1	RH REINFORCEMENT ,FR (SN)	NOT NECESSARY	7.00	-
1	REINFORCEMENT ,FR BU (SN)	BENT	503.00	503.00
1	REINFORCEMENT ,FR BUM (SN)	NOT NECESSARY	134.00	-
1	LH SIDE REINFORCEMENT (SN)	NOT NECESSARY	60.00	-
1	RH SIDE REINFORCEMENT (SN)	NOT NECESSARY	69.00	-
2	SIDE REINFORCEMENT ,F (SN)	NOT NECESSARY	44.00	-

Report Ref No. CC4/LPC20012246/Gba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GRILLE ,RADIATOR (SN)	NOT NECESSARY	383.00	-
12	CLIP ,RADIATOR GRILLE (SN)	NECESSARY	36.00	36.00
2	CLIP ,RADIATOR ,GRILL (SN)	NECESSARY	8.00	8.00
1	COVER ,HEADLAMP SUPP (SN)	NOT NECESSARY	50.00	-
5	CLIP ,RADIATOR GRILLE (SN)	NECESSARY	25.00	25.00
1	MARK ,THREE-DIA (SN)	NOT NECESSARY	69.00	-
1	UPR HEADLAMP SUPPORT (SN)	BENT	229.00	229.00
1	UPR RH HEADLAMP SUPP (SN)	NOT NECESSARY	58.00	-
1	UPR LH HEADLAMP SUPP (SN)	BENT	58.00	58.00
1	LATCH ,HOOD (SN)	NOT NECESSARY	76.00	-
1	LH MOULDING ,FR BUMP (SN)	DEFORMED	116.00	116.00
1	RH MOULDING ,FR BUMP (SN)	DEFORMED	116.00	116.00
1	LH HEADLAMP (SN)	NOT NECESSARY	1,852.00	-
1	RH HEADLAMP (SN)	NOT NECESSARY	1,852.00	-
4	COOLANT (SN)	NECESSARY	104.00	104.00
1	RADIATOR ASSY (SN)	NOT NECESSARY	1,091.00	-
			21,053.00	10,399.00
	LABOUR			
	DIAGNOSTIC /SCANNING.		250.00	250.00
	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT & REAR ACCIDENT AFFECTED AREAS.		100.00	100.00
	TO REPLACE TAILGATE GLASS .		300.00	300.00
	SEALANT KIT ON TAILGATE GLASS .		100.00	100.00
	TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS.		600.00	320.00
	TO REMOVE AND REINSTALL TRIMMING AND CARPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		600.00	320.00
	TO REMOVE AND REINSTALL FUEL LINING & PIPING TO GIVE WAY ACCESS REPAIR LHR OTR QTR PANEL .		600.00	320.00
	TO REPLACE TAILGATE PNL ,REAR BUMPER ,ETC.TO CUT & RE-WELD END PANEL .TO REPAIR REAR FLOORING AND LHR OTR QTR PANEL STRAIGHTEN ,PERFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS.		4,200.00	3,200.00
	TO APPLY SEALANT KIT ON NEW PANEL.		300.00	200.00

Report Ref No. CC4/LPC20012246/Gba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,940.00	2,750.00
	TO REPLACE FRONT BUMPER ,REINFORCEMENT ,ETC. CUT & RE-WELD UPR HEADLAMP SUPPORT PANEL STRAIGHTEN ,PERFORM ,ALIGN ON FRONT ACCIDENT AFFECTED AREAS.		2,400.00	1,920.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS.		1,680.00	1,650.00
			14,070.00	11,430.00
GRAND TOTAL			35,123.00	21,829.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,000.00

Report Ref No. CC4/LPC20012246/Gba3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 2281G

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 2281G

RE-INSPECTION

