



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name /Mr You Tao Reg No/Reg Date SKT2281G / 28/05/2015 Date In/Mileage 09/11/2020/ 71231 Chassis No JMYXTGF3WFZ002036 Engine No 4B12PM3947 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars Ler	56071		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SUNDRY						50.00
	C & C LOGO						50.00
M	SUNDRY						100.00
	MIVEC EMBLEM						280.00
S	MIPNT88088						250.00
	REAR AND FRONT NUMBER PLATE WITH CASING						100.00
S	MIPNT88088						250.00
	REVERSE SENSOR SET						100.00
S	MIPNT88088						100.00
	DIAGNOSTIC / SCANNING						100.00
S	MIPNT88088						300.00
	TO CHECK LIGHTING AND WIRIN SYSTEM ON FRONT & REAR ACCIDENT AFFECTED AREAS						100.00
S	MIPNT88088						600.00
	TO REPLACE TAILGATE GLASS						600.00
M	SUNDRY						600.00
	SEALANT KIT ON TAILGATE GLASS						4200.00
S	MIPNT88088						4200.00
	TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS						600.00
S	MIPNT88088						600.00
	TO REMOVE AND RE-INSTALL TRIMMING AND CARPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						600.00
S	MIPNT88088						4200.00
	TO REMOVE AND RE-INSTALL FUEL LINING & PIPING TO GIVE WAY ACCESS REPAIR LHR OTR QTR PANEL						4200.00
S	MIPNT88088						300.00
	TO REPLACE TAILGATE PNL, REAR BUMPER, ETC						2940.00
	-TO CUT & RE-WELD REAR END PANEL						
	-TO REPAIR REAR FLOORING AND LHR OTR QTR PANEL						
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						
S	MIPNT88088						300.00
	TO APPLY SEALANT KIT ON NEW PANEL						2940.00
S	MIPNT98088						2940.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MITSUBISHI
MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name	/Mr You Tao
Contact No	Reg No/Reg Date	SKT2281G / 28/05/2015
	Date In/Mileage	09/11/2020/ 71231
	Chassis No	JMYXTGF3WFZ002036
	Engine No	4B12PM3947
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars Ler	56071				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								1920 2400.00	
S	MIPNT88088	TO REPLACE FRONT BUMPER.REINFORCEMENT,ETC							
		-CUT & RE-WELD UPR HEADLAMP SUPPORT PANEL							
STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS								1650 1680.00	
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS							
M	JJ5801B351	TAIL GATE PANEL ASSY	Buc	1.00	1130.00	0.00	1130.00		
M	JJ5817A292WA	TAILGATE GARNISH	Re	1.00	759.00	0.00	759.00		
M	JJ7415A096	MARK,THREE-DIA	Lmc	1.00	63.00	0.00	63.00		
P	JJ7415A401	MARK,OUTLANDER	Lmc	1.00	95.00	0.00	95.00		
P	JJ5805A306	GLASS,TAILGATE WINDO	Lmc	1.00	751.00	0.00	751.00		
P	JJ5805A315	SIDE DAM,TAILGATE	Lmc	2.00	27.00	0.00	54.00		
P	JJ5805A316	UPR DAM,TAILGATE	Lmc	1.00	13.00	0.00	13.00		
M	JJ5808A135	LATCH, TAILGATE	BT	1.00	475.00	0.00	475.00		
M	JJ5813A285	MOTOR,POWER TAILGATE	X NN	1.00	1986.00	0.00	1986.00		
M	JJ5813A079	LH SENSOR,TAILGATE L	?	1.00	426.00	0.00	426.00		
M	JJ5813A078	RH SENSOR,TAILGATE L	?	1.00	426.00	0.00	426.00		
M	JJ5802A797	LH GAS SPRING,TAILGA	?	1.00	192.00	0.00	192.00		
M	JJ5802A798	RH GAS SPRING,TAILGA	?	1.00	192.00	0.00	192.00		
M	JJMN170754	SWITCH,POWER TAILGAT	?	1.00	72.00	0.00	72.00		
M	JJ8637A114	BUZZER,WARNING	?	1.00	41.00	0.00	41.00		
M	JJ5813A094	LABEL,TAILGATE CAUTI	Lmc	1.00	10.00	0.00	10.00		
P	JJ5815A067	WEATHERSTRIP, TAILGA	Lmc	1.00	213.00	0.00	213.00		
M	JJ7224A350XA	TRIM,TAILGATE	Re	1.00	329.00	0.00	329.00		
M	JJ8330B103	RR LH LAMP ASSY, COM	CPA	1.00	590.00	0.00	590.00		
M	JJ8330B104	RR RH LAMP ASSY,COMB	?	1.00	590.00	0.00	590.00		
M	JJ8336A101	LH REFLECTOR, TAIL L	CPA	1.00	171.00	0.00	171.00		
M	JJ8336A102	RH REFLECTOR, TAIL L	?	1.00	171.00	0.00	171.00		
M	JJ6410C886	FACE,RR BUMPER	Re	1.00	1063.00	0.00	1063.00		
M	JJMU488006	CLIP,RR BUMPER	Lmc	2.00	2.00	0.00	4.00		
M	JJMR200300	CLIP, RR BUMPER	Lmc	2.00	4.00	0.00	8.00		
M	JJ6410D336	BRACKET, RR BUMPER F	Re	1.00	12.00	0.00	12.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name /Mr You Tao Reg No/Reg Date SKT2281G / 28/05/2015 Date In/Mileage 09/11/2020/ 71231 Chassis No JMYXTGF3WFZ002036 Engine No 4B12PM3947 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars Ler	56071
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M JJ6410D337	BRACKET, RR BUMPER F	1.00	12.00	0.00	12.00
M JJ6410B895	LH REINFORCEMENT, RR	1.00	79.00	0.00	79.00
M JJ6410C817WA	LH SIDE GARNISH, RR	1.00	64.00	0.00	64.00
M JJ6410C818WA	RH SIDE GARNISH, RR	1.00	63.00	0.00	63.00
M JJ6410C863	EXTENSION, RR BUMPER	1.00	516.00	0.00	516.00
M JJMU488006	CLIP, RR BUMPER	2.00	2.00	0.00	4.00
M JJMR473000	RIVET, RR BUMPER	8.00	4.00	0.00	32.00
P JJ6512A681	CLIP, RR BUMPER	7.00	6.00	0.00	42.00
M JJ7407A317	LH MOULDING, RR BUMP	1.00	106.00	0.00	106.00
M JJ7407A318	RH MOULDING, RR BUMP	1.00	106.00	0.00	106.00
M JJ7407A303	LH MOULDING, RR WHEE	1.00	199.00	0.00	199.00
M JJ7407A304	RH MOULDING, RR WHEE	1.00	199.00	0.00	199.00
M JJ7240A135XA	TRIM, RR END	1.00	123.00	0.00	123.00
M JJ7646A187	BOX, CARGO FLOOR	1.00	204.00	0.00	204.00
M JJ8637A176	BUZZER, KEYLESS OPER	1.00	91.00	0.00	91.00
P JJ8637B115	ANTENNA, KEYLESS OPE	1.00	96.00	0.00	96.00
M JJ8518B065	HARNESS, RR BUMPER	1.00	66.00	0.00	66.00
M JJ8510J298	HARNESS, RR END	1.00	82.00	0.00	82.00
M JJ6400G281	FACE, FR BUMPER	1.00	1036.00	0.00	1036.00
P JJ6405A194	EXTENSION, FR BUMPER	1.00	380.00	0.00	380.00
M JJ6402A233	GRILLE, FR BUMPER	1.00	182.00	0.00	182.00
M JJMU488006	CLIP, FR BUMPER	5.00	2.00	0.00	10.00
P JJMR590000HB	CLIP, FR BUMPER	4.00	3.00	0.00	12.00
P JJMR288150	CLIP, FR BUMPER	2.00	3.00	0.00	6.00
M JJ6400F879	LH SIDE BRACKET, FR	1.00	24.00	0.00	24.00
P JJ6400F880	RH SIDE BRACKET, FR B	1.00	24.00	0.00	24.00
M JJMR473000	RIVET, FR BUMPER	8.00	4.00	0.00	32.00
M JJ6400D919	LH REINFORCEMENT, FR	1.00	7.00	0.00	7.00
M JJ6400D920	RH REINFORCEMENT, FR	1.00	7.00	0.00	7.00
M JJ6400H568	REINFORCEMENT, FR BU	1.00	503.00	0.00	503.00
M JJ6400G576	REINFORCEMENT, FR BUM	1.00	134.00	0.00	134.00
M JJ6400D581	LH SIDE REINFORCEMEN	1.00	60.00	0.00	60.00
M JJ6400D582	RH SIDE REINFORCEMEN	1.00	69.00	0.00	69.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name /Mr You Tao Reg No/Reg Date SKT2281G / 28/05/2015 Date In/Mileage 09/11/2020/ 71231 Chassis No JMYXTGF3WFZ002036 Engine No 4B12PM3947 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars Ler	56071

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ6400D977 SIDE REINFORCEMENT, F ?	2.00	22.00	0.00	44.00
M JJ7450A959 GRILLE, RADIATOR ?	1.00	383.00	0.00	383.00
P JJMR288150 CLIP, RADIATOR GRILLE ? / McC.	12.00	3.00	0.00	36.00
M JJMR200300 CLIP, RADIATOR GRILL	2.00	4.00	0.00	8.00
M JJ7450A753 COVER, HEADLAMP SUPP X NN	1.00	50.00	0.00	50.00
M JJMU000504 CLIP, RADIATOR GRILLE / McC	5.00	5.00	0.00	25.00
P JJ7415A603 MARK, THREE-DIA ?	1.00	69.00	0.00	69.00
M JJ5256B735 UPR HEADLAMP SUPPORT ? / BT.	1.00	229.00	0.00	229.00
M JJ5256C260 UPR RH HEADLAMP SUPP ?	1.00	58.00	0.00	58.00
M JJ5256C259 UPR LH HEADLAMP SUPP ? / DT	1.00	58.00	0.00	58.00
P JJ5908A108 LATCH, HOOD ?	1.00	76.00	0.00	76.00
M JJ7407A315 LH MOULDING, FR BUMP ? / McC	1.00	116.00	0.00	116.00
M JJ7407A316 RH MOULDING, FR BUMP ?	1.00	116.00	0.00	116.00
M JJ8301C205 LH HEADLAMP ?	1.00	1852.00	0.00	1852.00
M JJ8301C206 RH HEADLAMP ?	1.00	1852.00	0.00	1852.00
P JJMZ313950 COOLANT / McC	4.00	26.00	0.00	104.00
M JJ1350A601 RADIATOR ASSY ?	1.00	1091.00	0.00	1091.00

Z NOTES

ACCIDENT ON 07/11/2020 ALONG STILL ROAD (JUNCTION OF JOO CHIAT TERRACE)

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # GBB8332E TP INS : LONPAC

14 Days.
Lumpsum Repair.
After repair photos.
Cano Riamp - 82880282
09/11/2020.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	20,573.00
Labour	0.00
Standard Menu	0.00
Specialist Job	14,050.00
Others (Lub, etc)	0.00
Sundry	200.00
Total (w/o GST)	34,823.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.