

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE



Invoice Name & Address	Owner Name & Vehicle Info				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name	/Mr You Tao			
	Reg No/Reg Date	SKT2281G / 28/05/2015			
	Date In/Mileage	09/11/2020/ 71231			
	Chassis No	JMYXTGF3WFZ002036			
122.02902700	Engine No	4B12PM3947			
Contact No	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)			
	Colour/Trim	P02 / BK			

Ac	count No	Terms	Date/Time Pr	inted	CSE	Operator	为 实现的。原	WIP No	Charles from the
F00	000040	Credit	09/11/2020/	12:23	DS	218 / Mars Ler		56071	
			Description	of Good	ls / Service	S	Qty	Unit Price Disc%	Amount
М	SUNDRY								50.00
٠	C & C LOG	0							
М	SUNDRY						i		50.00
S	MIVEC EMB								/
3			UMBER PLATE W	ITU CAS	TNC				100.00
Ś	MIPNT8808		UNDER PERIE W	IIII CAS	ING				280.00
	REVERSE S		ET						280.00
S	MIPNT8808								250.00
	DIAGNOSTI	C / SCA	NNING				1		/ = = = =
S	MIPNT8808	8	Γ		П		п		100.00
	TO CHECK	LIGHTIN	G AND WIRIN S	YSTEM O	NEERON 18	REARTACCYDENT	ነና 2 🦳	\	
	AFFECTED	AREAS			2011	REAR VACCYDENI		_	5
2	MIPNT8808	E TATIC	ATE CLASS		9				1300
м	SUNDRY	E IAILU	AIE GLASS						100.00
11		IT ON T	AILGATE GLASS						7 100.00
S	MIPNT8808								320 600.00
	TO TRANSF	ER TAIL	GATE COMPONEN	T & MEC	HANISM PA	RTS			
S	MIPNT8808	-							320600.00
						ING TO GIVE WAY			
_			REAR ACCIDEN	T AFFEC	TED AREAS				22 - 600 00
S	MIPNT8808		TNCTALL FUEL	LINITALC	9 DIDING	TO CIVE MAY			320 600.00
			-INSTALL FUEL R OTR QTR PAN		a PIPING	TO GIVE WAT			
c	MIPNT8808		K OIK QIK FAN	LL	/_	(D			3200 4200.00
3			ATE PNL,REAR	BUMPER.	ETC Ø	40			1200.00
			D REAR END PA						
	-TO REPAI	R REAR	FLOORING AND	LHR OTR					
	STRAIGHTE	N, REFOR	M,ALIGN ON RE	AR ACCI	DENT AFFE	CTED AREAS			
S	MIPNT8808								200 300.00
			KIT ON NEW P.	ANEL	550				775 mm ==
S	MIPNT9808	8			コフロ				2940.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info				
LONDAC THEUDANCE BUD	Cust No/Name	/Mr You Tao			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07	Reg No/Reg Date	SKT2281G / 28/05/2015			
THE CONCOURSE	Date In/Mileage 09/11/2020/ 71231				
SINGAPORE 199555	Chassis No	JMYXTGF3WFZ002036			
TEL:62962706	Engine No	4B12PM3947			
Contact No	Make/Mode1	MIT/OUTLANDER 2.4 CVT AWD (F27)			
	Colour/Trim	P02 / BK			

Account No	Terms	Date/Time Printed	CSE	Operator			WIP No		FALL 2 多世 A.好
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars	Ler		56071		
		Description of Goods	/ Servic	08		Qty	Unit Price	Disc%	Amount
SPRAY PA	INTING ON	N REAR ACCIDENT AFFEC	TED AREA	\S					(0)
S MIPNT880	88								(92° 2400.00
TO REPLA	CE FRONT	BUMPER.REINFORCEMENT	,ETC						
		PR HEADLAMP SUPPORT F							
STRAIGHT	EN, REFORM	A,ALIGN ON FRONT ACCI	DENT AFF	FECTED AREAS			11910		1650 1680.00
S MIPNT980							11910		1680.00
SPRAY PA	INTING ON	N FRONT ACCIDENT AFFE					1100 00	0 00	1120 00
M JJ5801B3		TAIL GATE PA				1.00	1130.00	0.00	1130.00
M JJ5817A2	92WA	TAILGATE GAR		- re		1.00	759.00	0.00	759.00
M JJ7415A0		MARK, THREE-D		GMC.		1.00	63.00	0.00	63.00
P JJ7415A40	01	MARK, OUTHAND				$\int_{0.00}^{1.00}$	95.00	0.00	95.00 751.00
P JJ5805A30	06	GLASS.TAJLGA		1700	(2)	5 7.29	751.00	0.00	
P JJ5805A3	15	SIDE DAM, TAI		11 1 4901	(6)	15.66	27.00	0.00	54.00 13.00
P JJ5805A3		UPR DAM, TAIL		i n n n n		4.00	13.00	0.00	475.00
M JJ5808A13		LATCH, TAILS	GATE /	BT NN		1.00	475.00	0.00	× 1986.00
M JJ5813A28		MOTOR, POWER				1.00	1986.00	0.00	× 426.00
M JJ5813A07		LH SENSOR, TA				1.00	426.00	0.00	× 426.00
M JJ5813A07		RH SENSOR, TA		27 A IA I		1.00	426.00 192.00	0.00	× 192.00
M JJ5802A79	97	LH GAS SPRIM		, XI NINI		1.00		0.00	× 192.00
M JJ5802A79	98	RH GAS SPRIM		` ^		1.00	192.00	0.00	× 72.00
M JJMN17075	54	SWITCH, POWER				1.00	72.00	0.00	× 41.00
M JJ8637A11	14	BUZZER, WARNI	NG X NI	1 MC		1.00	41.00		10.00
M JJ5813A09	94	LABEL, TAILGA	TE CAUTI	Thi		1.00	10.00	0.00	213.00
P JJ5815A06	57	WEATHERSTRIP	, TAILGA	, ,			213.00	0.00	329.00
M JJ7224A35	OXA	TRIM, TAILGAT	E	CPA		1.00	329.00	0.00	590.00
M JJ8330B10)3	RR LH LAMP A		Q NINI		1.00	590.00	0.00	× 590.00
M JJ8330B10	14	RR RH LAMP A		' · · · · · · · · · · · · · · · · · · ·		1.00	590.00	0.00	171.00
M JJ8336A10	1	LH REFLECTOR				1.00	171.00		× 171.00
M JJ8336A10	2	RH REFLECTOR				1.00	171.00	0.00	1063.00
M JJ6410C88	6	FACE, RR BUMP		ne		1.00	1063.00	0.00	
M JJMU48800	6	CLIP, RR BUMP		SMC		2.00	2.00	0.00	4.00
M JJMR20030	0	CLIP, RR BUM		, , , ,		2.00	4.00	0.00	8.00
M JJ6410D33	6	BRACKET, RR	BUMPER F	/12		1.00	12.00	0.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	+483	Owner Name & Vehicle Info
LONPAC INSURANCE BHD	Cust No/Name	/Mr You Tao
300 BEACH ROAD #17-04/07	Reg No/Reg Date	SKT2281G / 28/05/2015
THE CONCOURSE	Date In/Mileage	09/11/2020/ 71231
SINGAPORE 199555 TEL:62962706	Chassis No	JMYXTGF3WFZ002036
121:02902700	Engine No	4B12PM3947
Contact No	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	No.	en july building	WIP No		1969/
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Ma	rs Ler		56071		
	200	Description of Goods	Service	s		Qty	Unit Price	Disc%	Amount
M JJ6410D3	37	BRACKET, RR B	UMPER F	XNN		1.00	12.00	0.00	× 12.00
M JJ6410B8	395	LH REINFORCEM	ENT,RR	/ BT		1.00	79.00	0.00	79.00
M JJ6410C8	317WA	LH SIDE GARNI	SH, RR	/ NC		1.00	64.00	0.00	64.00
M JJ6410C8	318WA	RH SIDE GARNI	SH, RR	ĆγX NN		1.00	63.00	0.00	63.00
M JJ6410C8	863	EXTENSION, RR	BUMPER /	- Cut.		1.00	516.00	0.00	516.00
M JJMU4880	06	CLIP,RR BUMPE	R /	1		2.00	2.00	0.00	4.00
M JJMR4730	00	RIVET, RR BUMP	ER /	Snoc		8.00	4.00	0.00	32.00
P JJ6512A6	81	CLIP, RR BUMP	ER /	/ u		7.00	6.00	0.00	42.00
M JJ7407A3	17	LH MOULDING,	RR BUMP	-		1.00	106.00	0.00	106.00
M JJ7407A3	18	RH MOULDING, I	RR BUMP	₹NN		1.00	106.00	0.00	$\times 106.00$
M JJ7407A3	03	LH MOULDING, I	RR WHEE	or re		$\Box^{1.00}$	199.00	0.00	199.00
M JJ7407A3	04	RH MOULDĮ NĢ	R WHEN		(0)	ረ ክ.ዖያ	199.00	0.00	$\times 199.00$
M JJ7240A1	35XA	TRÍM, RR ÉND	5 PK			1.00	123.00	0.00	123.00
M JJ7646A1	87	BOX, CARGO FLOG	砂区	re		(4.W)	204.00	0.00	204.00
M JJ8637A1	76	BUZZER, KEYLES		1000		1.00	91.00	0.00	91.00
P JJ8637B1	15	ANTENNA, KEYLE		∕¥ NN		1.00	96.00	0.00	× 96.00
M JJ8518B0	65	HARNESS, RR BUM	IPER XN	IN		1.00	66.00	0.00	×66.00
M JJ8510J2	98	HARNESS, RR END		08-		1.00	82.00	0.00	× 82.00
M JJ6400G28	81	FACE, FR BUMPE		pat.		1.00	1036.00	0.00	1036.00
P JJ6405A19	94	EXTENSION, FR				1.00	380.00	0.00	380.00
M JJ6402A23	33	GRILLE, FR BUM		NN		1.00	182.00	0.00	× 182.00
M JJMU48800	06	CLIP,FR BUMPER		(M		5.00	2.00	0.00	10.00
P JJMR59000	ОНВ	CLIP, FR BUMPE		7,00		4.00	3.00	0.00	12.00 6.00
P JJMR28815	50	CLIP,FR BUMPER		SMC.		2.00	3.00	0.00	24.00
M JJ6400F87	'9	LH SIDE BRACKE		1/2		1.00	24.00	0.00	24.00
P JJ6400F88	80	RH SIDE BRACKE		11		1.00	24.00	0.00	32.00
M JJMR47300	0	RIVET,FR BUMPE		MC		8.00	4.00	0.00	× 7.00
M JJ6400D91	9	LH REINFORCEME		X NN		1.00	7.00	0.00	× 7.00
M JJ6400D92	0	RH REINFORCEME		スNN ダンBT		1.00	7.00	0.00	503.00
м ЈЈ6400Н56	8	REINFORCEMENT,		• •		1.00	503.00	0.00	× 134.00
M JJ6400G57	6	REINFORCEMENT,		 ØNN		1.00	134.00	0.00	
4 JJ6400D58	1	LH SIDE REINFO		ŊN		1.00	60.00	0.00	× 60.00 × 69.00
1 JJ6400D58		RH SIDE REINFOR	RCEMEN	∕2 NN		1.00	69.00	0.00	V 03.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement in the event of inadvertent breakage in the course of renewing cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name	/Mr You Tao			
	Reg No/Reg Date	SKT2281G / 28/05/2015			
	Date In/Mileage 09/11/2020/ 71231				
	Chassis No	JMYXTGF3WFZ002036			
TEL:02902/00	Engine No	4B12PM3947			
Contact No	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)			
	Colour/Trim	P02 / BK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
F0000040	Credit	09/11/2020/ 12:23	DS	218 / Mars Ler		56071			
Light of the state of	Service of the service of	Description of Goo	ds / Services		Qty	Unit Price	Disc%	Am	ount
M JJ6400D9		SIDE REINF	ORCEMENT,F	*NN	2.00	22.00	0.00	×	44.00
M JJ7450A9	59	GRILLE, RAD	IATOR 🕱 N		1.00	383.00	0.00	×	383.00
P JJMR2881			TOR GRILLE		12.00	3.00	0.00		36.00
M JJMR2003		CLIP, RADI	ATOR GRILL	+ ' ' ' '	2.00	4.00	0.00		8.00
M JJ7450A7			DLAMP SUPP	X NN	1.00	50.00	0.00		50.00
M JJMU0005			TOR GRILLE	1 M	5.00	5.00	0.00		25.00
P JJ7415A6		MARK, THREE		N / BT.	1.00	69.00	0.00	×	69.00
M JJ5256B7		UPR HEADLA		× NN	1.00	229.00	0.00		229.00
M JJ5256C2			DLAMP SUPP	,	1.00	58.00	0.00	>	58.00
M JJ5256C2			DLAMP SUPP	7 / W	1.00	58.00	0.00		58.00
P JJ5908A1		LATCH. HOO				76.00	0.00	,	76.00
M JJ7407A3		LH MOULDIN	GER BUMB	77380 6	??\$? ? ?\$?	116.00	0.00		116.00
M JJ7407A3			G, FR BUMP		5 1.00	116.00	0.00	~	116.00
M JJ8301C2		LH HEADLAM			7 (7)	7 1852.00	0.00		1852.00 1852.00
M JJ8301C2		RH HEADLAM	P ZNN.		1.00 4.00	1852.00 26.00	0.00	^	104.00
P JJMZ3139		COOLANT			1.00	1091.00	0.00	~	104.00
M JJ1350A6 Z NOTES		RADIATOR A	•						
Z NOTES	ON 07/1	1/2020 ALONG STILL	DOVD (HINCE	TON OF JOO CHIAT	FRACE			1	0032
UNINED CI	AIMING T	1/2020 ALONG STILL HIRD PARTY	KOAD (OUNCT	TON OF GOO CHIAN	LKK Auto Cons	ultants hence	notify		
REQUIRED					the Repairer of	the following	•		
TP # GBB		TP INS : LONPAC	2194	2	 To resurvey before 	e/after spray pai	inting		.29
			2194	12	• To display damag	ed part(s) during	resurvey		
	ULD	a. C -2	0%: 1400	0	• Parts prices are s	ubject to confirm	nation		
	14 40	ツ フ・			 Third party survey No illegal modification 	is on a "Withou	t Prejudice" I	oasis	
		Van N.			Sunniementary its	awolis ar (s)nore	d		
	lmps	m referre			 Supplementary its is subject to final a 	approval from In:	surveyed an surance Co	d pany	
	100	~ what	intar.		Acknowledged by R	enairer			
	Att	y vigirai	•	- 0 - 0 -	Signature:	cpaner			
	, 7	A	. 62	280)84	Date:				
	$\int \Delta$	no Rim	-91						
		m Repart. or rupar 1	09/11	/2020.					
Confirm & a	ccented b		1/01	/	Parts	8		-	20,573.0
contitui of a	ccepted i	-3			Labour				0.
					Standard				0.0
					Specialis				14,050.
					Others(Lu	b,etc)			0.
					Sundry				200.
	-	and company stamp			Total(w/o	GST)			34,823.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.