



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI20012250/T1td3e2	
			Date: 26/01/2021	
			Code: FCI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.		Veh. Inspected	SCQ 321Z
	Policy No.	D-20095447MFPC	Coverage (\$)	0.00
	Claim No.	D20004526MFPC/PTE/OD/FK	Excess (\$)	750.00
	Assign From	EILEEN LEE	Assign Date	04/11/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA LEXUS ES250	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTHBJ1GG902088774	Colour	GREY
	Odometer	78786 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/45 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/45 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/45 R18	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/11/2020	Inspection Date	04/11/2020
	Survey held at	50 CUSCADEN ROAD BASEMENT HPL SINGAPORE 249724		
	Repairer	RIVERVIEW AUTO SERVICES **Terminated**		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$88,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	