

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20012274/QRA3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900098958

Claimant
Vehicle No : SHB5905B **Insured Vehicle No :** SML3878Y

Date of Loss: 05/11/2020 Nature of Claim: TP Claim No: 5404693979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5905B		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F14169
Reg. Date:	12/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU203088823
Colour:	Maroon	Odometer:	75990 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Touring 6 mm	Rear Left Side:	Touring 6 mm
Front Right Side:	Touring 6 mm	Rear Right Side:	Touring 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,993.30	537.23	3,456.07	86.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,854.00	690.00	1,164.00	62.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,847.30	1,227.23	4,620.07	79.01
+ Loss of Use (3.5 x S\$60.00/day) (S\$)		210.00		
+ Car Rental (3.5 x S\$119.31/day) (S\$)		417.59		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,861.82		

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 06/11/2020 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
2	1		*PAD ,FRONT BUMPER (NO.1) (DISC 25%)	Necessary	40.70 F	*30.53 F
3	10		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	100.00 F	*75.00 F
4	1		*COVER ,FR BUMPER (DISC 25%)	Cut	521.00 F	*390.75 F
5	1		*SUPPORT ,FR BUMPER LH	Serviceable	82.30 F	*- F
6	1		*COVER ASSY ENGINE	Serviceable	241.90 F	*- F
7	1		*MOULDING FRONT BUMPER SIDE ,LH	Serviceable	95.60 F	*- F
8	1		*WHEEL DISC ,FRONT	Repair	1,879.40 F	*- F
9	1		*FENDER SUB-ASSY ,FR ,LH	Repair	977.80 F	*- F

F=Franchise part.

Total Parts (\$\$) **3,993.30** **537.23**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	936.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,854.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >