

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012281/T1RA3Q2
Date: 10/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070139621
Claimant Vehicle No :	SHA1819Z	Insured Vehicle No :	SMV4943H
Date of Loss:	08/11/2020	Nature of Claim:	TP
		Claim No:	3713163498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1819Z		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU189525
Reg. Date:	01/03/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU141145
Colour:	Blue	Odometer:	237276 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,604.76	2,111.32	493.44	18.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	740.00	560.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,904.76	2,851.32	1,053.44	26.98
+ GST 7.00/7.00% (S\$)	273.33	199.59	73.74	26.98

Nett Amount (S\$)	4,178.09	3,050.91	1,127.18	26.98
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$128.40/day) (S\$)		385.20		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,593.60		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 09/11/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Cracked	430.90 FL	*430.90 FL
2	1		*EMBLEM -BLUE DRIVE	Necessary	26.60 FL	*26.60 FL
3	1		*PANEL -FENDER LH	Repair	588.80 FL	*- FL
4	1		*LAMP ASSY -HEAD	Cut	1,993.65 FL	*1,993.65 FL
5	1		*MOULDING -FRONT	Cut	188.00 FL	*188.00 FL
6	1		*BRACKET -FR BUMPER	Not Necessary	28.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	3,255.95	2,639.15
- List Item Discount on L Items 20.00/20.00% (\$\$)	651.19		527.83
	Total Parts (\$\$)	2,604.76	2,111.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	320.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	50.00	20.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	0.00
Gross Labour Cost (S\$)			1,300.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >