

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : LONPAC INSURANCE BHD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2011/001
Policy No:	5116758158	Date of Loss:	04/11/2020
Vehicle Reg. No.:	GBK2932R	Driveable?	no
Driver Age:	13/10/1981	Third Party Vehicle No.:	YN185E
Any Injuries?	no	Contact No:	63052788
Insured/Claimant:	SEMBCORP SPECIALISED CONSTRUCTION PTE LTD	Driver:	FOO SIANG HAI (FU XIANGHAI)

Make/Model:	Toyota, Hilux	Vehicle Reg. Date:	19/03/2020
Vehicle Colour:	Silver	Engine Number:	2GDC580157
Chassis No:	MR0CB8DD100502942	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	381.93 1,460.22
Miscellaneous Items	0.00 220.00
Labour	360.00 710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total(\$\$):	741.93 2,390.22
GST 7.00%(\$\$):	167.32
Nett Amount(\$\$):	2,557.54

This claim is handled by: Lai Yee Meng

P/P \$ 741.93

(PLS CONFIRM)

P/P
\$ 741.93

2 dys

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR SIDE BUMPER STEP GARNISH LH ^{cut} CR	148.20	-10.00	133.38 ✓
2	1	REAR SIDE BUMPER LH (CHROME) ^{pb}	331.40	-25.00	248.55 ✓
3	1	REAR SIDE BUMPER BRACKET LH ^{? XSV}	154.20	-10.00	138.78
4	1	REAR BUMPER STEP GARNISH CENTER ^{CR}	287.70	-10.00	258.93
5	1	REAR BUMPER STEP GARNISH INNER PANEL ^{XSV}	756.20	-10.00	680.58
6	1	REAR SIDE BUMPER RH (CHROME) ^{XSV}	331.40	-25.00	248.55
Total Parts (S\$)					1,460.22 381.93

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER REVERSE SENSOR ^{XSV}	220.00	0.00	220.00
Sub Total (S\$)					220.00 0.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 30 ✓
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	0.00	600.00 300 ✓
Gross Labour Cost (S\$)					710.00 360.00 ✓

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
Gross Labour Cost (S\$)					0.00

< END OF ESTIMATES >

P/P

before paint phot

Repair day - 2 days.

Sun Pin CLK

12/11/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____