

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19017834/QSD3E2-1
Date: 23/12/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29135271ALM		
Claimant Vehicle No :	SLP9803P	Insured Vehicle No :	SMP1391B		
Date of Loss:	07/10/2019	Nature of Claim:	TP	Claim No:	607906

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP9803P	Engine No:	P520446486
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Chassis No:	JM6BN22A8H0154500
Reg. Date:	23/06/2017 (Man. Year: 2017)	Odometer:	51299 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,917.04	6,627.96	6,289.08	48.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,370.00	3,030.00	56.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,317.04	8,997.96	9,319.08	50.88
Approved Total (Overridden) (\$\$)		7,200.00		
Nett Amount (\$\$)	18,317.04	7,200.00	11,117.04	60.69

INSPECTION

Date of Assignment:	09/10/2019	Benefit Auto Care Pte Ltd (HQ) 11 KAKI BUKIT ROAD 1 #01-02 EUNOS TECHNOLINK Singapore 415939
Date Inspected:	09/10/2019 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2020)
Parts:	143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9803P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	767.30 FL	*- FL
2	1		*BONNET LOCK	Serviceable	197.10 FL	*- FL
3	2		*HEADLAMP R/L	Cracked	2,039.00 FL	*2,039.00 FL
4	1		*FRT GRILLE	Cracked	150.60 FL	*150.60 FL
5	1		*FRT GRILLE EMBLEM	Necessary	58.50 FL	*58.50 FL
6	2		*FRT GRILLE CHROME R/L	Cracked	365.20 FL	*242.00 FL
7	2		*FRT GRILLE CHROME BRACKET R/L	Serviceable	64.80 FL	*- FL
8	1		*FRT BUMPER	Crumpled	825.50 FL	*825.50 FL
9	1		*FRT BUMPER TOP COVER	Crumpled	313.70 FL	*285.00 FL
10	1		*FRT BUMPER NO.PLATE SUPPORT	Cracked	71.00 FL	*71.00 FL
11	2		*FRT BUMPER FOG LAMP R/L	Serviceable	292.00 FL	*- FL
12	2		*FRT BUMPER FOG LAMP GARNISH R/L	Deformed	65.20 FL	*65.20 FL
13	8		*FRT BUMPER CLIP	Necessary	25.60 FL	*25.60 FL
14	2		*FRT BUMPER RETAINER R/L	Broken	56.80 FL	*56.80 FL
15	1		*FRT BUMPER SUPPORT RAIL COVER	Serviceable	85.00 FL	*- FL
16	1		*FRT BUMPER REINFORCEMENT	Bent	478.80 FL	*478.80 FL
17	1		*FRT RADIATOR SUPPORT	Serviceable	470.00 FL	*- FL
18	1		*FRT SUPPORT PANEL TOP PLATE	Serviceable	137.10 FL	*- FL
19	1		*FRT RADIATOR SUPPORT ACCESS COVER	Serviceable	93.00 FL	*- FL
20	1		*FRT RADIATOR SUPPORT AIR DEFLECTOR	Serviceable	84.20 FL	*- FL
21	1		*RADIATOR ASSY	Serviceable	1,064.90 FL	*- FL
22	1		*A/C CONDENSER	Serviceable	1,063.00 FL	*- FL
23	1		*BOOT LID	Repair	957.40 FL	*- FL
24	2		*BOOT LID HINGE R/L	Repair	236.60 FL	*- FL
25	1		*BOOT LID EMBLEM (LOGO)	Necessary	74.40 FL	*74.40 FL
26	1		*BOOT LID EMBLEM (MAZDA 3)	Necessary	53.40 FL	*53.40 FL
27	1		*BOOT LID EMBLEM (SKYACTIV)	Necessary	63.30 FL	*63.30 FL
28	1		*BOOT LID REFLECTOR LAMP R/L	Serviceable	530.00 FL	*- FL
29	1		*BOOT LID TRIM	Serviceable	85.10 FL	*- FL
30	10		*BOOT LID TRIM CLIP	Serviceable	30.00 FL	*- FL
31	1		*BOOT LID LOCK	Serviceable	153.00 FL	*- FL
32	1		*BOOT LID LOCK STRIKER	Serviceable	33.40 FL	*- FL
33	1		*BOOT LID WEATHERSTRIP	Crumpled	107.70 FL	*107.70 FL
34	2		*TAILLAMP R/L	Cracked	1,018.80 FL	*1,018.80 FL
35	2		*TAILLAMP PANEL R/L	Repair	755.60 FL	*- FL
36	1		*RR BUMPER	Crumpled	1,074.80 FL	*1,074.80 FL
37	1		*RR BUMPER TOW COVER	Missing	38.40 FL	*38.40 FL
38	6		*RR BUMPER FASTENER	Necessary	19.20 FL	*19.20 FL
39	1		*RR BUMPER REINFORCEMENT	Bent	537.30 FL	*537.30 FL
40	2		*RR BUMPER RETAINER R/L	Necessary	72.20 FL	*72.20 FL
41	2		*RR BUMPER BRACKET R/L	Serviceable	91.20 FL	*- FL
42	1		*RR END PANEL	Dented	505.10 FL	*505.10 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RR END PANEL GARNISH	Crumpled	78.60 FL	*78.60 FL
44	1		*SPARE TYRE COVER TRIM	Serviceable	350.00 FL	*- FL
45	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
46	2		*FRT FENDER R/L (NPA)	Repair	0.00 FL	*- FL
47	2		*FRT CHASSIS MEMBER R/L (NPA)	Repair	0.00 FL	*- FL
48	2		*RR FENDER R/L (NPA)	Repair	0.00 FL	*- FL
49	1		*RR SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
50	2		*RR CHASSIS MEMBER R/L (NPA)	Repair	0.00 FL	*- FL
51	1		*FRT NO. PLATE	Crumpled	50.00 FS	*35.00 FS
52	1		*BOT RADIATOR COOLANT	Serviceable	60.00 FS	*- FS
53	1		*SET RR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
54	1		*RR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,043.80	8,216.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,126.76	1,588.24
Total Parts (\$\$)	12,917.04	6,627.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP	New	60.00	0.00
2	TO REMOVE, REPLACE AND REINSTALL A/C CONDENSER & A/C PIPING. (INCLUDE VACUUM & RECHARGE A/C GAS)	New	120.00	0.00
3	TO REMOVE, REPLACE AND REINSTALL RADIATOR & COOLING SYSTEM. (INCLUDE PRESSURE TEST COOLING SYSTEM)	New	100.00	0.00
4	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	500.00
5	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA	New	1,200.00	400.00
6	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	60.00	30.00
7	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	50.00	30.00
8	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	150.00	50.00
9	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT	New	100.00	0.00
10	TO CONDUCT CHASSIS ALIGNMENTS	New	300.00	0.00
11	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	700.00
12	TO SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA	New	1,200.00	600.00
13	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	60.00	60.00
Gross Labour Cost (\$\$)			5,400.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >