



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S:528090

Mobile: 9256 2264 Fax: 9722 0506 Email: psasvcs@himal.com

Business Reg: 201414434D

INVOICE

Mr Ong Yanzheng (Wang Yanzheng)
C/o 11 Kaki Bukit Road 1
#01-03 Eunos Technolink
Singapore 415939

Invoice No: HA/1911-77
Date: 22/11/2019

Descriptions		Amount (SGD)
Services rendered for appraiser / inspection report :-		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection fees		
Total :		SGD : \$ 731.00
SGD Dollar : Seven Hundred Thirty One Dollars Only		
Our Reference : PAS/11/0101019		
Vehicle No : SLP9803P		
Make & Model : Mazda 3		
Your Claim No. : Third Party Claim		

Notes

All cheque payment should be crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD"

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Selegie Rd #02-24 S(626891)

Mobile: 9295 2204 Fax: 6772 8500 Email: pss@prominent.com

Business Reg. ZC1404-340

VEHICLE INSPECTION REPORT

Report No : PAS/14/0101019

Date of Report : 22/11/2019

To : Mr Ong Yunzheng (Wang Yunzheng)
C/O: 11 Kaki Bukit Road 1
#01-02 Eunos Technolink
Singapore 415939

Date of Assignment : 08/10/2019
Report requested by : Mr Ong Yunzheng (Wang Yu)
Date of Accident : 07/10/2019
Date of Inspection : 08/10/2019
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLP9803P
Make & Model : Mazda 3
Date of Registration : 23/06/2017
Colour : Met. Blue

Engine Capacity (cc) : 1496cc
Mileage (km) : 51290km
Chassis / Frame No. : JM6BN23A8201545C0
Engine No. : P526445486

TYRE CONDITION

Front LH : 8 mm
Make : Yokohama

Front RH : 8 mm
Make : Yokohama

Rear LH : 8 mm
Make : Yokohama

Rear RH : 8 mm
Make : Yokohama

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Major Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Donelli's Auto Care Private Limited
11, Kaki Bukit Road 1, #01-02, Eunos Technolink, Singapore 415939

ASSESSMENT

Repairer's Estimate : \$ 18,317.04
Revised Amount : \$ 15,943.24
Less Taxes : \$ -
Recommended Reserve \$ 12,750.00 (Lump Sum)

Estimated Normal Period of Repairs : 16 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressee for estimating repair costs and vehicle condition in relation to the loss occurrence in which the damaged vehicle involved. It is confidential and may be covered by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on the report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy or in any way use this information. A certificate of this disclaimer is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei Str 3 409-24 S1529990;

Mobile: 9299 2204 Fax: 6722 9508 Email: amvcs@hotmail.com

Business Reg: 2014044340

Vehicle No: SLP9803P

Report No.: PAS/TP:0101019

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Benefits Auto Care Private Limited, 11, Kaki Bukit Road 1, #01-02, Eunus Technolink, Singapore 415939.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front support panel, front chassis members, front bumper, front fenders, headlamps, front grilles, boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, taillamps, boot reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$15,943.24.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$12,750.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby revert the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 15ime St 3 #62 24 S(528901)

Mobile: 91205 2204 Fax: 6722 8508 Email: pases@hometel.com

Business Reg: 201434434D

Vehicle No.: SLP9803P

Report No.: PAS/TP/0101019

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Bonnet	Dented/Repair	\$ 267.30	\$ -
2	1 pc	Bonnet lock	Bent	\$ 197.10	\$ 197.10
3	2 pcs	Headlamp R/L	Cracked	\$ 2,039.00	\$ 2,039.00
4	1 pc	Frt grille	Dented/Cracked	\$ 150.60	\$ 150.60
5	1 pc	Frt grille emblem	Necessary	\$ 58.50	\$ 58.50
6	2 pcs	Frt grille chrome R/L	Dented/Cracked	\$ 365.20	\$ 365.20
7	2 pcs	Frt grille chrome bracket R/L	Dented/Cracked	\$ 64.80	\$ 64.80
8	1 pc	Frt bumper	Dented	\$ 875.50	\$ 875.50
9	1 pc	Frt bumper top cover	Dented/Deformed	\$ 313.70	\$ 313.70
10	1 pc	Frt bumper top plate support	Dented/Cracked	\$ 71.00	\$ 71.00
11	2 pcs	Frt bumper fog lamp R/L	Cracked	\$ 292.60	\$ 292.60
12	2 pcs	Frt bumper fog lamp garnish R/L	Dented/Deformed	\$ 65.20	\$ 65.20
13	8 pcs	Frt bumper clip	Necessary	\$ 25.60	\$ 25.60
14	2 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 56.80	\$ 56.80
15	1 pc	Frt bumper support rail cover	Refit	\$ 85.00	\$ -
16	1 pc	Frt bumper reinforcement	Dented	\$ 478.80	\$ 478.80
17	1 pc	Frt radiator support	Dented/Cracked	\$ 470.00	\$ 470.00
18	1 pc	Frt support panel top plate	Dented	\$ 137.10	\$ 137.10
19	1 pc	Frt radiator support access cover	Dented/Cracked	\$ 93.00	\$ 93.00
20	1 pc	Frt radiator support air deflector	Refit	\$ 84.20	\$ -
21	1 pc	Radiator assy	Dented/Bent	\$ 1,064.90	\$ 1,064.90
22	1 pc	A/c condenser	Dented/Bent	\$ 1,063.00	\$ 1,063.00
23	1 pc	Boot lid	Dented/Disorted	\$ 957.40	\$ 957.40
24	2 pcs	Boot lid hinge R/L	Bent/Repair	\$ 236.60	\$ -
25	1 pc	Boot lid emblem (Jingo)	Necessary	\$ 74.40	\$ 74.40
26	1 pc	Boot lid emblem (Mercedes)	Necessary	\$ 53.40	\$ 53.40
27	1 pc	Boot lid emblem (SKYACTIV)	Necessary	\$ 63.30	\$ 63.30
28	2 pcs	Boot lid reflector lamp R/L	Cracked	\$ 530.00	\$ 530.00
29	1 pc	Boot lid trim	Refit	\$ 61.10	\$ -
30	10 pcs	Boot lid trim clip	Necessary	\$ 30.00	\$ 30.00
31	1 pc	Boot lid lock	Bent/Damaged	\$ 153.00	\$ 153.00
32	1 pc	Boot lid lock striker	Bent	\$ 23.40	\$ 23.40
33	1 pc	Boot lid weatherstrip	Torn/Deformed	\$ 107.70	\$ 107.70
34	2 pcs	Tail lamp R/L	Cracked/Broken	\$ 1,018.80	\$ 1,018.80
35	2 pcs	Tail lamp panel R/L	J.H. Dented/Disorted	\$ 377.80	\$ 377.80
36	1 pc	Rr bumper	Dented	\$ 1,074.80	\$ 1,074.80
37	1 pc	Rr bumper top cover	Broken/Dislodged/Missing	\$ 38.40	\$ 38.40
38	6 pcs	Rr bumper fastener	Necessary	\$ 19.20	\$ 19.20
39	1 pc	Rr bumper reinforcement	Dented	\$ 537.30	\$ 537.30
40	2 pcs	Rr bumper retainer R/L	Cracked/Necessary	\$ 77.20	\$ 77.20
41	2 pcs	Rr bumper bracket R/L	Dented	\$ 91.20	\$ 91.20
42	1 pc	Rr end panel	Dented	\$ 505.10	\$ 505.10
43	1 pc	Rr end panel garnish	Dented/Deformed	\$ 78.60	\$ 78.60
44	2 pc	Spare tyre cover trim	Serviceable	\$ 350.00	\$ -
				\$ 15,621.80	\$ 13,647.80



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Singapore

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: * 5imeh St 3 #02-24 S/52089C
Mobile: 9805 2304

Mobile: 9295 2204 Fax: 5722 6508 Email: paucers@comcast.com

Vehicle No. , SLP9803P

Durham Reg. 20140431D

Report No. : PAS/P/2010/01

Repairer's	Our
Estimate (\$\$)	Assessment (\$\$)

Estimate (\$)	Assessment (\$)
---------------	-----------------

\$ 13,633.80 \$ 13,647.89

(Refer to our D.O. 4 & 5)

{Reich labour no. 4 & 5}

(Refit labour no. 2, 3, 4, 5 & 10)

(References to 8, 11 & 12)

(Kaiser labor no. 8, 11 & 12)

(Refer labour no. 8, 10, 11 & 12)

$$\begin{array}{r} \overline{15.573.80} \\ \overline{15.547.80} \end{array}$$

Less Discount: 20%	\$ 3,176.76	20%	\$ 2,729.56
--------------------	-------------	-----	-------------

List Parts Sub-Total:	<u>\$ 12,507.04</u>	<u>\$ 10,918.28</u>
-----------------------	---------------------	---------------------

1	1 pc	Fri isoplate	Dented/Cracked	S/N	3	90.00	\$ 10.918.24
2	1 bot	Radiator coolant	Missing				\$ 15.00

2	1 bot	Radiator coolant	Needed/Checked	S/N	3	10 00	\$	10 00
3	1 bot	Oil	Necessary	S/N				

3	1 set Rr reverse sensor	Necessary	\$75.00	\$	15.00
4	1 set Rr reverse sensor	Delayed/Damaged?	\$60.00	\$	60.00

4	1 pc	2x end panel scalars	Needed/Damaged Necessary	500 5	250.00	\$ 60.00 \$ 250.00
---	------	----------------------	-----------------------------	----------	--------	-----------------------

Special Net; Sub-Total: $\frac{\$410.00}{\$365.00}$

Paris Total:	\$ 12,917.04	\$ 11,273.24
--------------	--------------	--------------



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(520893)

Mobile: 9985 2204 Fax: 6722 8838 Email: pases@prominent.com

Business Reg. 20140443411

Vehicle No. : SLF9803P

Report No. : PAS/TP/0101019

S/No.	Labour Descriptions	Repairer's Estimate (\$)	Our Assessment (\$)
1	To check front electrical system and calibrate focus headlamp.	\$ 60.00	\$ 50.00
2	To remove, replace and reinstall a/c condenser & a/c pipings (include vacuum & recharge a/c gas)	\$ 120.00	\$ 120.00
2	To remove, replace and reinstall radiator & cooling system (include pressure test cooling system)	\$ 100.00	\$ 80.00
4	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 1,000.00	\$ 850.00
5	To spray painting, blending on front affected and adjacent area.	\$ 1,200.00	\$ 1,000.00
6	To check rear electrical wiring system.	\$ 60.00	\$ 50.00
7	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 50.00	\$ 50.00
8	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00
9	To transfer front component parts to new boat	\$ 100.00	\$ 80.00
10	To conduct chassis alignments	\$ 300.00	\$ 300.00
11	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,000.00	\$ 850.00
12	To spray painting, blending on rear affected and adjacent area	\$ 1,200.00	\$ 1,000.00
13	To spray anti-rust coating on new and affected panels.	\$ 60.00	\$ 60.00
Labour Total :		\$ 5,400.00	\$ 4,670.00
Total (Parts & Labour) :		\$ 18,317.04	\$ 15,943.24

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 12,750.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **16 Working Days**. (Exclude waiting days of PRF, Sunday, Public Holiday and awaiting of shipment for spare parts)

ISI Photographs were taken at the time of inspection.

S.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The repair estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date thereof. Otherwise this revised amount shall be deemed as valid.



























