Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012288/EVD3E2

Date: 19/11/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900072793 Claimant Vehicle SKB2359L **Insured Vehicle No:** GBD3301S

ΤP Date of Loss: 05/11/2020 Nature of Claim: Claim No: 1303390552SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB2359L

Make & Model: TOYOTA RUSH, 1.5 X (A) Engine No: 3SZ2089150 Reg. Date: 12/01/2009 (Man. Year: 2008) Chassis No: J200E0021112 Colour: Odometer: 151318 km Grey

Engine Capacity: 1495 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

205/65 R15 Front Tyre Size: 205/65 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Bridgestone 4 mm Bridgestone 4 mm Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 10/11/2020 Inspected At: Fixmate Auto Pte Ltd - Kaki Bukit (HQ)

8 KAKI BUKIT AVE 4 #04-06, PREMIER @ KB SINGAPORE 415875

Estimated Period of Repair: 8.0 days

CHEN TSUE YEE Manager: VERON CHEN Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
7	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
8	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
9	1		*TAILGATE	Dented	0.00 F	*- F
10	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE WIPER MOTOR	Bent	0.00 F	*- F
13	1		*TAILGATE GLASS	Broken	0.00 F	*- F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Bent	0.00 F	*- F
17	1		*TAILGATE RUBBER	Crushed	0.00 F	*- F
18	1		*TAILGATE HINGE	Bent	0.00 F	*- F
19	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
20	1		*SPARE TYRE PANEL	* Check	0.00 F	*- F
21	1		*SPARE TYRE WHEEL COVER	Broken	0.00 F	*- F
22	1		*REAR LH FENDER	Repair	0.00 F	*- F
23	1		*REAR LH FENDER INNER TRIM	* Check	0.00 F	*- F
24	1		*REAR RH FENDER	Repair	0.00 F	*- F
25	1		*REAR RH FENDER INNER TRIM	* Check	0.00 F	*- F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >