Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012289/UYF3E2

Date: 18/11/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00045542000

Claimant Vehicle SKW1164C

Insured Vehicle No:

SGB233B

Date of Loss:

No:

29/10/2020

Nature of TP Claim:

Claim No:

Engine No:

Odometer:

SNM20D204209/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW1164C

Make & Model: TOYOTA WISH, 1.8 CVT (A)

19/10/2015 (Man. Year: 2015)

Chassis No:

2ZR1605878 JTDGG20W00J002903

116522 km

Reg. Date: Colour:

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

195/65R15 Front Tyre Size: 195/65R15 Rear Tyre Size: Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm Rear Right Side: Kumho 6 mm Front Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,169.50	1,520.47	3,649.03	70.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,730.00	1,170.00	40.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,069.50	3,250.47	4,819.03	59.72
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	8,069.50	2,600.00	5,469.50	67.78

INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 10/11/2020 Inspected At:

15 Kaki Bukit Road 4 #01-05/53 Bartley

Biz Centre

Repairer: Asia Motorsports Solution Pte

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)		
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	t Code: (Unsubmitted, no print-code for SKW1164C)			
Validity:	lity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts No. Oty. Part No. Particulars

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	1,272.00 FL	*- FL
2	1		*TAIL GATE CENTRE BADGE	Not Necessary	85.50 FL	*- FL
3	1		*TAIL GATE CENTRE CHROME GARNISH	Not Necessary	328.00 FL	*- FL
4	1		*TAIL GATE INNER LOCK	Not Necessary	238.00 FL	*- FL
5	2		*REAR WINDSCREEN INNER MOULDING	Not Necessary	150.00 FL	*- FL
6	1		*REAR BUMPER	Dented/Deformed	1,122.00 FL	*581.10 FL
7	2		*REAR BUMPER REFLECTORS	Not Necessary	150.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	180.00 FL	*- FL
9	2		*REAR BUMPER EXTENSION BRACKET	Not Necessary	356.00 FL	*- FL
10	1		*REAR BOOT EDGE WEATHERSTRIP	Twisted	287.50 FL	*281.10 FL
11	1		*REAR END PANEL LOCK CATCH	Not Necessary	66.00 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	289.00 FL	*- FL
13	1		*REAR END PANEL	Dented/Bent	782.00 FL	*645.10 FL
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
15	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*-FS
17	1		*REAR TAILGATE ELEGANCE EMBLEM PLATE	Necessary	98.00 FS	*45.00 FS
18	1		*REAR TAILGATE VALVE MATIC EMBLEM PLATE	Necessary	112.00 FS	*45.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
20	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*-FS
21	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
F=Fra	ınchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	•	1,897.30
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,326.50	376.83	
				Total Parts (S\$)	5,169.50	1,520.47

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	750.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,000.00	800.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	20.00
4	TO REMOVE/REFIX INNER TRIMS, FITTINGS, GARNISH ETC A REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	T New	250.00	80.00
5	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	140.00	0.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND REVERSE CAMERA AND CHECK FOR PROPER FUNCTION	New	150.00	50.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	30.00
	Gross Labour Cost (S\$)		2,900.00	1,730.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >