

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012290/BSD3E2

**Date:** 29/12/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00007592002

**Claimant Vehicle  
No :** SJT1153L

**Insured Vehicle  
No :** GBE6373J

Date of Loss: 07/11/2020

Nature of Claim: TP

Claim  
No: SNM20D204275/C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT1153L**

Make & Model: MITSUBISHI LANCER, 1.5 (A)

Engine No: 4A910126026

Reg. Date: 24/09/2009 (Man. Year: 2009)

Chassis No: JMYSRCY2AAU000271

Colour: Grey

Odometer: 274711 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 225/50 R17 | Rear Tyre Size:  | 225/50 R17 |
| Front Left Side:  | CST 5 mm   | Rear Left Side:  | CST 5 mm   |
| Front Right Side: | CST 5 mm   | Rear Right Side: | CST 5 mm   |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 37,107.41         | 14,738.44         | 22,368.97         | 60.28         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 10,900.00         | 5,070.00          | 5,830.00          | 53.49         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>48,007.41</b>  | <b>19,808.44</b>  | <b>28,198.97</b>  | <b>58.74</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>15,800.00</b>  |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>48,007.41</b>  | <b>15,800.00</b>  | <b>32,207.41</b>  | <b>67.09</b>  |

### INSPECTION

Date of Assignment: 10/11/2020

Date Inspected: 10/11/2020

Inspected At:

Team Autopro Pte Ltd  
160 SIN MING DR  
#01-14 SIN MING AUTO CITY  
SINGAPORE 575722

Estimated Period of Repair: 14.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                             |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 29 Dec 2020)               |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MITSUBISHI LANCER 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                           |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJT1153L)                                                                                                                                    |                                                             |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                             |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                             |

## Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition               | Repairer's  | Amount     |
|-----|-----|----------|---------------------------------------|-------------------------|-------------|------------|
| 1   | 1   |          | *BOOTLID                              | Repair                  | 980.90 FL   | *- FL      |
| 2   | 1   |          | *BOOTLID HINGE                        | O/S Bent                | 210.00 FL   | *105.00 FL |
| 3   | 1   |          | *BOOTLID HYDROLIC DAMPER              | O/S Broken              | 300.00 FL   | *92.00 FL  |
| 4   | 1   |          | *BOOTLID SPOILER                      | Not Damaged             | 588.00 FL   | *- FL      |
| 5   | 1   |          | *BOOTLID BRAKE LAMP                   | Not Damaged             | 388.00 FL   | *- FL      |
| 6   | 1   |          | *BOOTLID LAMP                         | O/S Broken              | 831.60 FL   | *182.00 FL |
| 7   | 1   |          | *BOOTLID LOGO                         | Necessary               | 63.00 FL    | *47.00 FL  |
| 8   | 1   |          | *BOOTLID EMBLEM LANCER                | Necessary               | 58.00 FL    | *58.00 FL  |
| 9   | 1   |          | *BOOTLID EMBLEM EX                    | Necessary               | 48.00 FL    | *38.00 FL  |
| 10  | 1   |          | *BOOTLID EMBLEM MIVEC                 | Necessary               | 52.60 FL    | *52.60 FL  |
| 11  | 1   |          | *BOOTLID INNER TRIM BOARD             | Not Damaged             | 168.00 FL   | *- FL      |
| 12  | 1   |          | *BOOTLID INNER LOCK                   | Not Damaged             | 235.00 FL   | *- FL      |
| 13  | 1   |          | *BOOTLID INNER LOCK STIKER            | Not Damaged             | 40.00 FL    | *- FL      |
| 14  | 1   |          | *BOOTLID OUTER CHROME GARNISH         | Not Damaged             | 253.30 FL   | *- FL      |
| 15  | 1   |          | *BOOTLID WEATHERSTRIP                 | Not Damaged             | 210.00 FL   | *- FL      |
| 16  | 1   |          | *REAR WINDSCREEN                      | Broken                  | 1,068.00 FL | *658.00 FL |
| 17  | 1   |          | *REAR WINDSCREEN MOULDING TOP         | Necessary               | 48.00 FL    | *48.00 FL  |
| 18  | 1   |          | *REAR WINDSCREEN MOULDING BOTTOM      | Necessary               | 68.00 FL    | *68.00 FL  |
| 19  | 2   |          | *REAR WINDSCREEN MOULDING SIDE        | Necessary               | 388.00 FL   | *242.00 FL |
| 20  | 1   |          | *REAR WINDSCREEN PILLAR INNER GARNISH | O/S Broken              | 197.20 FL   | *98.60 FL  |
| 21  | 1   |          | *REAR BUMPER                          | Broken                  | 869.00 FL   | *869.00 FL |
| 22  | 1   |          | *REAR BUMPER REINFORCEMENT            | Not Damaged             | 260.00 FL   | *- FL      |
| 23  | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary               | 170.20 FL   | *128.00 FL |
| 24  | 1   |          | *REAR BUMPER REFLECTOR                | O/S Broken              | 513.60 FL   | *80.00 FL  |
| 25  | 1   |          | *REAR BUMPER TOW CAP                  | Not Damaged             | 88.60 FL    | *- FL      |
| 26  | 1   |          | *REAR BUMPER LOWER                    | Broken / Cut            | 358.00 FL   | *135.00 FL |
| 27  | 2   |          | *REAR BUMPER NUMBER PLATE LAMP        | Not Damaged             | 96.00 FL    | *- FL      |
| 28  | 1   |          | *REAR END PANEL                       | Dented                  | 605.00 FL   | *506.00 FL |
| 29  | 1   |          | *REAR END PANEL TOP GARNISH           | Broken                  | 261.00 FL   | *261.00 FL |
| 30  | 1   |          | *SPARE TYRE PANEL                     | Not Damaged             | 962.00 FL   | *- FL      |
| 31  | 1   |          | *SPARE TYRE PANEL TOP BOARD           | Not Damaged             | 255.00 FL   | *- FL      |
| 32  | 2   |          | *REAR FENDER                          | N/S Cut / O/S Distorted | 1,570.00 FL | *785.00 FL |
| 33  | 1   |          | *REAR FENDER INNER PANEL RH           | Dented                  | 520.00 FL   | *483.00 FL |
| 34  | 1   |          | *REAR FENDER INNER COWLING            | Broken                  | 95.80 FL    | *95.80 FL  |
| 35  | 1   |          | *REAR FENDER INNER TRIM BOARD         | O/S Broken              | 429.20 FL   | *214.60 FL |
| 36  | 2   |          | *REAR FENDER AIR VENTS                | No such part            | 116.00 FL   | *- FL      |
| 37  | 1   |          | *REAR SPEAKER PANEL                   | Dented                  | 586.30 FL   | *428.00 FL |
| 38  | 1   |          | *REAR SPEAKER PANEL BOARD             | Cut                     | 249.70 FL   | *180.00 FL |
| 39  | 1   |          | *REAR DOOR RH                         | Dented                  | 768.00 FL   | *768.00 FL |
| 40  | 1   |          | *REAR DOOR OUTER BLACK TAPE RH        | Necessary               | 68.00 FL    | *50.00 FL  |
| 41  | 1   |          | *REAR DOOR INNER LOCK RH              | Jammed                  | 267.50 FL   | *267.50 FL |
| 42  | 1   |          | *REAR DOOR INNER LOCK STICKER RH      | No such part            | 45.00 FL    | *- FL      |

| No. | Qty | Part No. | Particulars                         | Condition            | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------|----------------------|-------------|------------|
| 43  | 1   |          | *REAR DOOR WEATHERSTRIP RH          | Torn                 | 126.20 FL   | *126.20 FL |
| 44  | 1   |          | *REAR DOOR INNER TRIM BOARD RH      | Broken               | 312.00 FL   | *312.00 FL |
| 45  | 1   |          | *REAR DOOR OUTER HANDLE RH          | Broken               | 205.40 FL   | *205.40 FL |
| 46  | 1   |          | *REAR DOOR OUTER CHROME MOULDING RH | Not Damaged          | 141.00 FL   | *- FL      |
| 47  | 1   |          | *REAR DOOR REGULATOR RH             | Not Damaged          | 125.00 FL   | *- FL      |
| 48  | 1   |          | *REAR DOOR REGULATOR MOTOR RH       | Not Damaged          | 324.00 FL   | *- FL      |
| 49  | 1   |          | *REAR DOOR CHECKER RH               | Dislodged            | 47.80 FL    | *47.80 FL  |
| 50  | 2   |          | *REAR DOOR HINGE RH                 | Not Damaged          | 136.00 FL   | *- FL      |
| 51  | 1   |          | *TAIL LAMP                          | O/S Broken           | 997.20 FL   | *421.00 FL |
| 52  | 2   |          | *TAIL LAMP LOWER BRACKET            | No such part         | 196.00 FL   | *- FL      |
| 53  | 2   |          | *TAIL LAMP BASE PANEL               | Dented               | 828.00 FL   | *531.60 FL |
| 54  | 1   |          | *FRONT BUMPER                       | Broken               | 890.00 FL   | *890.00 FL |
| 55  | 2   |          | *FRONT BUMPER SIDE RETAINER         | Necessary            | 120.00 FL   | *90.00 FL  |
| 56  | 1   |          | *FRONT BUMPER SIDE RETAINER BEAM    | Not Damaged          | 186.50 FL   | *- FL      |
| 57  | 1   |          | *FRONT BUMPER REINFORCEMENT         | Not Damaged          | 383.00 FL   | *- FL      |
| 58  | 1   |          | *FRONT BUMPER LOWER SPOILER         | Broken               | 2,172.00 FL | *832.00 FL |
| 59  | 1   |          | *FRONT BUMPER FOG LAMP LH           | Broken               | 422.00 FL   | *350.00 FL |
| 60  | 1   |          | *FRONT BUMPER FOG LAMP GARNISH LH   | Broken               | 82.90 FL    | *48.20 FL  |
| 61  | 1   |          | *FRONT SUPPORT PANEL                | Not Damaged          | 587.00 FL   | *- FL      |
| 62  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH    | Not Damaged          | 175.00 FL   | *- FL      |
| 63  | 1   |          | *FRONT FENDER LH                    | Dented               | 634.50 FL   | *596.00 FL |
| 64  | 1   |          | *FRONT FENDER INNER COWLING LH      | Distorted            | 184.00 FL   | *130.00 FL |
| 65  | 1   |          | *FRONT FENDER SIGNAL LAMP LH        | Not Damaged          | 65.00 FL    | *- FL      |
| 66  | 1   |          | *BONNET                             | Repair               | 758.00 FL   | *- FL      |
| 67  | 1   |          | *BONNET INNER LOCK                  | Not Damaged          | 145.80 FL   | *- FL      |
| 68  | 1   |          | *HEADLAMP LH                        | Broken               | 836.50 FL   | *836.50 FL |
| 69  | 1   |          | *HEADLAMP LOWER BRACKET LH          | No such part         | 134.00 FL   | *- FL      |
| 70  | 1   |          | *HEADLAMP PANEL LH                  | Not Damaged          | 210.00 FL   | *- FL      |
| 71  | 1   |          | *REAR SHOCK ABSORBER RH             | Bent                 | 296.00 FL   | *210.00 FL |
| 72  | 1   |          | *REAR LOWER ARM RH                  | Not Damaged          | 233.00 FL   | *- FL      |
| 73  | 1   |          | *REAR UPPER ARM RH                  | Bent                 | 217.00 FL   | *217.00 FL |
| 74  | 1   |          | *REAR CONTROL ARM RH                | Dented               | 372.00 FL   | *372.00 FL |
| 75  | 1   |          | *REAR KNUCKLE ARM RH                | No such part         | 348.00 FL   | *- FL      |
| 76  | 1   |          | *REAR KNUCKLE ARM BEARING RH        | Jammed               | 279.80 FL   | *279.80 FL |
| 77  | 1   |          | *REAR CROSSMEMBER RH                | No such part         | 1,020.00 FL | *- FL      |
| 78  | 1   |          | *REAR ABS SENSOR RH                 | Not Damaged          | 210.00 FL   | *- FL      |
| 79  | 1   |          | *FRONT SHOCK ABSORBER LH            | Bent                 | 337.00 FL   | *210.00 FL |
| 80  | 1   |          | *FRONT LOWER ARM LH                 | Bent                 | 347.00 FL   | *347.00 FL |
| 81  | 1   |          | *FRONT KNUCKLE ARM LH               | Not Damaged          | 302.00 FL   | *- FL      |
| 82  | 1   |          | *FRONT KNUCKLE ARM BEARING LH       | Jammed               | 284.00 FL   | *284.00 FL |
| 83  | 1   |          | *FRONT LINKAGE LH                   | Not Damaged          | 163.00 FL   | *- FL      |
| 84  | 1   |          | *FRONT ABS SENSOR LH                | Not Damaged          | 210.00 FL   | *- FL      |
| 85  | 1   |          | *STEERING RACK                      | Not Damaged          | 1,458.60 FL | *- FL      |
| 86  | 1   |          | *BOOTLID EMBLEM C&C                 | Necessary            | 85.20 FL    | *55.00 FL  |
| 87  | 1   |          | *SUNDRIES                           | Not Necessary        | 80.00 FS    | *- FS      |
| 88  | 1   |          | *BOOTLID SEALANT                    | Not Necessary        | 100.00 FS   | *- FS      |
| 89  | 1   |          | *BOOTLID INNER TRIM BOARD CLIPS     | Necessary            | 50.00 FS    | *30.00 FS  |
| 90  | 1   |          | *BOOTLID LAMP SEAL                  | Necessary (1Pc Only) | 120.00 FS   | *60.00 FS  |
| 91  | 2   |          | *BOOTLID LAMP CLIPS                 | Necessary            | 100.00 FS   | *60.00 FS  |
| 92  | 1   |          | *BOOTLID OUTER CHROME GARNISH CLIPS | Not Necessary        | 50.00 FS    | *- FS      |
| 93  | 1   |          | *REAR WINDSCREEN CLIPS              | No such part         | 50.00 FS    | *- FS      |
| 94  | 1   |          | *REAR WINDSCREEN SEALANT            | Necessary            | 100.00 FS   | *60.00 FS  |
| 95  | 1   |          | *REAR WINDSCREEN INNER SEAL         | Necessary            | 120.00 FS   | *60.00 FS  |
| 96  | 1   |          | *REAR WINDSCREEN PRIMER AND CLEANER | Not Necessary        | 60.00 FS    | *- FS      |
| 97  | 1   |          | *REAR WINDSCREEN SOLAR FILM         | No such part         | 450.00 FS   | *- FS      |
| 98  | 1   |          | *REAR BUMPER CLIPS                  | Necessary            | 50.00 FS    | *30.00 FS  |

| No. | Qty | Part No. | Particulars                            | Condition               | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------------|-------------------------|-------------|------------|
| 99  | 1   |          | *REAR BUMPER LOWER CLIPS               | No such part            | 50.00 FS    | *- FS      |
| 100 | 1   |          | *REAR END PANEL SEALANT                | Necessary               | 100.00 FS   | *40.00 FS  |
| 101 | 1   |          | *REAR END PANEL TOP GARNISH CLIPS      | Necessary               | 50.00 FS    | *30.00 FS  |
| 102 | 1   |          | *SPARE TYRE PANEL SEALANT              | Not Necessary           | 100.00 FS   | *- FS      |
| 103 | 1   |          | *SPARE TYRE PANEL INSULATOR            | Not Necessary           | 320.00 FS   | *- FS      |
| 104 | 1   |          | *REAR FENDER SEALANT                   | O/S Necessary           | 200.00 FS   | *60.00 FS  |
| 105 | 1   |          | *REAR FENDER INNER PANEL SEALANT       | Necessary               | 100.00 FS   | *40.00 FS  |
| 106 | 1   |          | *REAR FENDER INNER COWLING CLIPS       | O/S Necessary           | 100.00 FS   | *30.00 FS  |
| 107 | 2   |          | *REAR FENDER INNER TRIM BOARD CLIPS    | Necessary               | 100.00 FS   | *30.00 FS  |
| 108 | 1   |          | *REAR SPEAKER PANEL SEALANT            | Not Necessary           | 100.00 FS   | *- FS      |
| 109 | 1   |          | *REAR SPEAKER PANEL BOARD CLIPS        | Necessary               | 50.00 FS    | *30.00 FS  |
| 110 | 1   |          | *REAR DOOR SEALANT                     | Necessary               | 100.00 FS   | *50.00 FS  |
| 111 | 1   |          | *REAR DOOR INNER TRIM BOARD CLIPS      | Necessary               | 50.00 FS    | *30.00 FS  |
| 112 | 1   |          | *TAIL LAMP CLIPS                       | O/S Necessary           | 100.00 FS   | *20.00 FS  |
| 113 | 2   |          | *TAIL LAMP SEAL                        | No such part            | 120.00 FS   | *- FS      |
| 114 | 1   |          | *TAIL LAMP BASE PANEL SEALANT          | O/S Necessary           | 160.00 FS   | *30.00 FS  |
| 115 | 2   |          | *REVERSE SENSOR                        | Short Circuit           | 500.00 FS   | *200.00 FS |
| 116 | 1   |          | *FRONT BUMPER CLIPS                    | Necessary               | 50.00 FS    | *30.00 FS  |
| 117 | 1   |          | *FRONT BUMPER LOWER SPOILER CLIPS      | No such part            | 50.00 FS    | *- FS      |
| 118 | 1   |          | *FRONT BUMPER FOG LAMP GARNISH CLIPS   | No such part            | 50.00 FS    | *- FS      |
| 119 | 1   |          | *FRONT SUPPORT PANEL SEALANT           | Not Necessary           | 100.00 FS   | *- FS      |
| 120 | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH CLIPS | Not Necessary           | 50.00 FS    | *- FS      |
| 121 | 1   |          | *FRONT FENDER SEALANT                  | Necessary               | 100.00 FS   | *40.00 FS  |
| 122 | 1   |          | *FRONT FENDER INNER COWLING CLIPS      | Necessary               | 50.00 FS    | *30.00 FS  |
| 123 | 1   |          | *BONNET SEALANT                        | Not Necessary           | 100.00 FS   | *- FS      |
| 124 | 1   |          | *REAR & FRONT ALLOY RIM                | Front Repair / Rear Cut | 1,960.00 FS | *600.00 FS |
| 125 | 1   |          | *REAR & FRONT TYRE                     | Rear Broken             | 960.00 FS   | *250.00 FS |
| 126 | 1   |          | *RADIATOR COOLANT                      | Not Necessary           | 80.00 FS    | *- FS      |
| 127 | 1   |          | *A/C FLUID                             | Not Necessary           | 80.00 FS    | *- FS      |
| 128 | 1   |          | *BRAKE FLUID                           | Not Necessary           | 80.00 FS    | *- FS      |
| 129 | 1   |          | *BOOTLID SOLENOID SWITCH               | Not Damaged             | 138.00 FL   | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>40,414.90</b> | <b>16,171.60</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 3,307.49         | 1,433.16         |
| <b>Total Parts (\$\$)</b>                                  | <b>37,107.41</b> | <b>14,738.44</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                  | Lab.Type | Repairer's       | Amount          |
|---------------------------------|------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                              |          |                  |                 |
| 1                               | R&R BOOTLID COMPONENT        | New      | 150.00           | 80.00           |
| 2                               | R&R REAR WINDSCREEN          | New      | 250.00           | 120.00          |
| 3                               | R&R REVERSE SENSOR           | New      | 100.00           | 60.00           |
| 4                               | R&R REAR DOOR COMPONENT      | New      | 150.00           | 80.00           |
| 5                               | R&R REAR UNDER CARRIAGE      | New      | 250.00           | 120.00          |
| 6                               | R&R REAR TYRE AND BALANCING  | New      | 80.00            | 60.00           |
| 7                               | WHEEL ALIGNMENT              | New      | 120.00           | 60.00           |
| 8                               | R&R SIDE SKIRT RH            | New      | 150.00           | 80.00           |
| 9                               | R&R FUEL TANK PIPE           | New      | 150.00           | 0.00            |
| 10                              | R&R REAR SEAT                | New      | 150.00           | 80.00           |
| 11                              | REAR CHECK WIRING            | New      | 100.00           | 50.00           |
| 12                              | REAR CONDUCT WATER LEAK TEST | New      | 120.00           | 0.00            |
| 13                              | REAR UPHOLSTERY              | New      | 150.00           | 0.00            |
| 14                              | REAR PANEL BEATING           | New      | 2,200.00         | 1,600.00        |
| 15                              | REAR RUST PROOFING           | New      | 200.00           | 90.00           |
| 16                              | REAR SPRAY PAINTING          | New      | 2,000.00         | 1,200.00        |
| 17                              | R&R RADIATOR                 | New      | 150.00           | 0.00            |
| 18                              | R&R A/C CONDENSER            | New      | 150.00           | 0.00            |
| 19                              | R&R FRONT UNDER CARRIAGE     | New      | 250.00           | 80.00           |
| 20                              | R&R FRONT TYRE AND BALANCING | New      | 80.00            | 30.00           |
| 21                              | R&R STEERING RACK            | New      | 150.00           | 0.00            |
| 22                              | FRONT UPHOLSTERY             | New      | 300.00           | 0.00            |
| 23                              | FRONT CHECK WIRING           | New      | 100.00           | 40.00           |
| 24                              | FRONT PANEL BEATING          | New      | 1,600.00         | 600.00          |
| 25                              | FRONT RUST PROOFING          | New      | 200.00           | 40.00           |
| 26                              | FRONT SPRAY PAINTING         | New      | 1,600.00         | 600.00          |
| <b>Gross Labour Cost (\$\$)</b> |                              |          | <b>10,900.00</b> | <b>5,070.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >