

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012294/DQF3E2

Date: 07/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00007742001
Claimant Vehicle No :	SLV6266C	Insured Vehicle No :	PC8306K
Date of Loss:	07/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204286/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6266C	Engine No:	R16B22001127
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650HT000708
Reg. Date:	05/01/2018 (Man. Year: 2017)	Odometer:	61143 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,167.40	5,800.24	3,367.16	36.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	2,730.00	2,140.00	43.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	14,037.40	8,530.24	5,507.16	39.23

INSPECTION

Date of Assignment: 10/11/2020
 Date Inspected: 10/11/2020 Inspected At:

Alfred Auto Services & Supplies (HQ)
 Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang
 Mo Kio Industrial Park 2
 Singapore 569538

Estimated Period of Repair: 11.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV6266C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL BOOT	Dented	541.20 F	*541.20 FL
2	2		*TAIL BOOT HINGE	Bent	139.80 F	*139.80 FL
3	2		*TAIL BOOT LAMP	Cracked / Broken	317.00 F	*317.00 FL
4	1		*TAIL BOOT GARNISH	Cut / Broken	133.80 F	*133.80 FL
5	2		*TAIL BOOT NO. PLATE LAMP	Not Necessary	150.00 F	*- FL
6	1		*TAIL BOOT INNER COVER	Bent	190.80 F	*190.80 FL
7	10		*TAIL BOOT INNER COVER CLIPS	Necessary	50.00 FS	*20.00 FS
8	1		*TAIL BOOT H LOGO	Cut	18.70 F	*18.70 FL
9	1		*TAIL BOOT LOCK	Damaged	99.80 F	*99.80 FL
10	2		*TAIL BOOT STOPPER	Missing	21.00 F	*21.00 FL
11	10		*TAIL BOOT GARNISH CLIPS	Necessary	45.00 FS	*20.00 FS
12	2		*TAIL LAMP ASSY	Broken	599.60 F	*599.60 FL
13	4		*TAIL LAMP BASE CLIPS	Not Necessary	24.00 FS	*12.00 FS
14	2		*TAIL LAMP PANEL	Repair	197.80 F	*- FL
15	1		*TAIL LAMP END PANEL	Dented	315.00 F	*315.00 FL
16	2		*TAIL LAMP HOLDER	Not Necessary	29.20 F	*- FL
17	1		*TAIL PANEL SEAL COVER LH	Dislodged / Missing	10.50 F	*10.50 FL
18	1		*TAIL PANEL WEATHER SLIPS	Deformed	120.00 F	*120.00 FL
19	1		*TAIL PANEL GARNISH	Bent / Deformed	60.30 F	*60.30 FL
20	1		*TAIL PANEL LOCK CATCH	Bent	27.80 F	*27.80 FL
21	1		*TAIL SPARE TYRE COVER BOARD	Not Necessary	153.90 F	*- FL
22	1		*TAIL SPARE TYRE COVER TOOLBOX SPOUGE	Not Necessary	187.50 F	*- FL
23	1		*TAIL FENDER INNER CARPET	N/S Bent / O/S Not Necessary	284.40 F	*142.20 FL
24	1		*TAIL FENDER INNER CARPET CLIPS (10PCS)	N/S Necessary/O/SNotNecessary	60.00 FS	*20.00 FS
25	1		*CIVIC EMBLEM	Not fitted	24.30 F	*- FL
26	1		*1.6 VTI EMBLEM	Not fitted	26.60 F	*- FL
27	1		*TAIL HINGER COVER LH	Dislodged / Missing	28.80 F	*28.80 FL
28	2		*TAIL HINGER COVER CLIPS	No such part	12.00 F	*- FL
29	1		*BOOTLID LOCK SENSOR	Shorted	198.00 F	*198.00 FL
30	1		*REAR BUMPER (SPORT TYPE)	Dented	980.00 F	*980.00 FL
31	1		*REAR BUMPER BEAM	Dented	199.80 F	*199.80 FL
32	1		*REAR BUMPER LOWER PAD	Cracked	258.50 F	*258.50 FL
33	2		*REAR BUMPER CORNER GARNISH	Cracked	73.00 F	*73.00 FL
34	1		*REAR BUMPER RETAINER	O/S Serviceable / N/S Broken	57.20 F	*28.60 FL
35	4		*REAR PARKING SENSOR	Damaged	679.20 F	*679.20 FL
36	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*REAR EXHAUST	Bent	859.30 F	*859.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*REAR EXHAUST CHROME	Bent	492.60 F	*492.60 FL
39	4		*REAR EXHAUST MOUNTING	Not Necessary	103.20 F	*- FL
40	1		*REAR NO. PLATE & BOX	Bent	50.00 F	*50.00 FL
41	1		*REAR WINDSCREEN MOULDING	Not Necessary	199.30 F	*- FL
42	1		*REAR WINDSCREEN SEAL	Not Necessary	58.00 F	*- FL
43	1		*REAR WINDSCREEN REPAIR KIT & SEALANT	Not Necessary	120.00 F	*- FL
44	2		*AKRAPOVIC EXHAUST TIP	Cracked / Broken	440.00 FS	*440.00 FS
45	1		*TAIL BOOT CAMERA	Serviceable	480.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,167.40	7,117.30
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,317.06

Total Parts (\$)	9,167.40	5,800.24
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK & RESETTING SRS & ABS	New	280.00	0.00
2	TO CHECK WIRING & REMOVE & REFIT	New	180.00	30.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	0.00
4	TO REMOVE & REFIT INTERIOR CARPET, GARNISH & ALL AFFECTED AREA	New	250.00	180.00
5	TO KNOCKING, WELDING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	1,800.00	1,200.00
6	TO REMOVE & REFIT, RENEW EXHAUST SYSTEM	New	220.00	80.00
7	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA. (2 COLOUR)	New	1,800.00	1,200.00
8	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	160.00	40.00
Gross Labour Cost (S\$)			4,870.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >