

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012295/KGS3Q2

**Date:** 29/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900103426

**Claimant**  
**Vehicle No :** SLS6454S **Insured Vehicle No :** SLZ7838A

Date of Loss: 06/11/2020 Nature of Claim: TP Claim No: 1882880054SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLS6454S</b>	Engine No:	LDA24017740
Make & Model:	HONDA CIVIC, 1.3 IMA CVT (A)	Chassis No:	JHMF36209S205085
Reg. Date:	14/12/2009 (Man. Year: 2008)	Odometer:	344260 km
Colour:	Metallic Grey		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,889.36	4,800.32	4,089.04	46.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	2,120.00	2,630.00	55.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,639.36</b>	<b>6,920.32</b>	<b>6,719.04</b>	<b>49.26</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,639.36</b>	<b>5,500.00</b>	<b>8,139.36</b>	<b>59.68</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 10/11/2020

Date Inspected: 16/11/2020 Inspected At:

Ngiak Motor Works - Kaki Bukit (HQ)  
NO.10 KAKI BUKIT ROAD 2, #03-36  
FIRST EAST CENTRE  
Singapore 417868

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	1,138.50 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	190.10 FL	*- FL
3	1		*REAR BUMPER	Repair	696.30 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER (RH)	Serviceable	34.90 FL	*- FL
5	1		*REAR RH DOOR	Bent	1,095.20 FL	*1,095.20 FL
6	1		*REAR RH DOOR INNER RUBBER	Serviceable	193.80 FL	*- FL
7	1		*REAR RH DOOR PROTECTOR W/MOULDING	Dented	187.50 FL	*187.50 FL
8	1		*REAR RH DOOR GLASS OUTER MOULDING	Serviceable	180.60 FL	*- FL
9	1		*REAR RH DOOR OUTER HANDLE	Dented / Cut	219.60 FL	*219.60 FL
10	1		*FRONT RH DOOR	Bent	1,226.10 FL	*1,226.10 FL
11	1		*FRONT RH DOOR INNER RUBBER	Serviceable	196.40 FL	*- FL
12	1		*FRONT RH DOOR PROTECTOR W/MOULDING	Dented	219.50 FL	*219.50 FL
13	1		*FRONT RH DOOR GLASS OUTER MOULDING	Serviceable	188.20 FL	*- FL
14	1		*FRONT RH DOOR OUTER HANDLE	Dented	238.10 FL	*238.10 FL
15	1		*FRONT RH DOOR SIDE MIRROR ASSY	Cracked	986.30 FL	*986.30 FL
16	1		*FRONT RH DOOR GLASS INNER SEAL	Serviceable	93.60 FL	*- FL
17	1		*REAR RH DOOR GLASS INNER SEAL	Serviceable	88.10 FL	*- FL
18	1		*FRONT RH FENDER	Repair	560.90 FL	*- FL
19	1		*FRONT RH HEADLAMP ASSY	Cut	1,078.10 FL	*1,078.10 FL
20	1		*FRONT BUMPER	Repair	713.50 FL	*- FL
21	1		*FRONT BUMPER SIDE RETAINER (RH)	Serviceable	36.40 FL	*- FL
22	2		*SETS RH DOOR FRAME BLACK STICKER	Necessary	180.00 FS	*180.00 FS
23	1		*SETS RH TYRE RIMS	Rear Dented	840.00 FS	*420.00 FS
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR RH FENDER SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,801.70</b>	<b>5,850.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,912.34</b>	<b>1,050.08</b>
<b>Total Parts (\$\$)</b>	<b>8,889.36</b>	<b>4,800.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO FOCUS HEADLIGHT & CHECK WIRING	New	60.00	20.00
2	COMPUTERIED WHEEL ALIGNMENT	New	100.00	0.00
3	RUSTPROOFING	New	120.00	60.00
4	REMOVE & REFIX REAR WINDSCREEN	New	160.00	0.00
5	REMOVE & REFIX CUSHION ,CARPETS,SIDE COVER & UPHOLSTERY	New	320.00	0.00
6	REMOVE & TRANSFER BOTH RH DOOR INNER ITEMS	New	200.00	120.00
7	REMOVE & REINSTAL REVERSE SENSOR	New	100.00	0.00
8	REMOVE & REFIX BOTH TYRES & WHEEL BALANCING	New	90.00	20.00
9	PANEL BEATING	New	1,600.00	700.00
10	SPRAY PAINTING	New	2,000.00	1,200.00
<b>Gross Labour Cost (\$)</b>			<b>4,750.00</b>	<b>2,120.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**