

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a Hyundai Sonata car (SKZ9085D) at Deck 2B of the MSCP.

METHOD OF EXTINGUISHMENT: By SCDF crew using two compressed air foam backpacks and a 38mm hose line jet from fire appliances.

PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment)

DAMAGE SUSTAINED: As a result of the fire, the engine compartment was damaged. The front part, windscreen, windows, and interior of the car sustained heat and smoke damage. The ceiling, walls, railing and piping in the area sustained smoke damage.

3. FATALITY/INJURY INFORMATION

NAME	PIN/FIN		DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL

REPORT CERTIFIED TRUE AND CORRECT BY:

CINDY HAN
for COMMISSIONER
SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.