

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20012301/KGA3Q2  
**Date:** 11/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900257828
<b>Claimant Vehicle No :</b>	SMD3532L	<b>Insured Vehicle No :</b>	SLF25E
Date of Loss:	06/11/2020	Nature of Claim:	TP
		Claim No:	5025651220SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMD3532L</b>	Engine No:	G4FGJU237807
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU729168
Reg. Date:	16/08/2018 (Man. Year: 2018)	Odometer:	31769 km
Colour:	Metallic Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,473.84	2,809.68	664.16	19.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,335.00	1,100.00	235.00	17.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,808.84</b>	<b>3,909.68</b>	<b>899.16</b>	<b>18.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		

(S\$)	4,808.84	3,100.00	1,708.84	35.54
<b>+ GST 7.00/7.00% (S\$)</b>	336.62	217.00	119.62	35.54
<b>Nett Amount (S\$)</b>	<b>5,145.46</b>	<b>3,317.00</b>	<b>1,828.46</b>	<b>35.54</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,719.00</b>		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 18/11/2020

Inspected At:

S & H Motor Pte Ltd (Sin Ming)  
 160 Sin Ming Drive #07-02, Sin Ming AutoCity  
 Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,782.00 FL	*1,782.00 FL
2	1		*REAR BOOT INNER LOCK	Repair	162.00 FL	*- FL
3	1		*REAR BOOT BADGE ELANTRA	Necessary	38.00 FL	*38.00 FL
4	1		*REAR BOOT BADGE ELITE	Necessary	48.00 FL	*48.00 FL
5	1		*RH REAR BOOT HINGE	Repair	94.30 FL	*- FL
6	1		*LH REAR BOOT HINGE	Repair	94.30 FL	*- FL
7	1		*REAR END PANEL	Repair	454.60 FL	*- FL
8	1		*REAR BUMPER	Buckled / Cracked	459.40 FL	*459.40 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	480.00 FL	*480.00 FL
11	1		*RH REAR BUMPER RETAINER	Distorted	44.30 FL	*44.30 FL
12	1		*LH REAR BUMPER RETAINER	Distorted	44.30 FL	*44.30 FL
13	1		*REAR BUMPER CENTRE LOWER MOULDING	Distorted	250.10 FL	*250.10 FL
14	1		*LH REAR BUMPER LOWER DUST COVER	Cracked	47.20 FL	*47.20 FL
15	1		*RH REAR BUMPER REFLECTOR	Cracked	40.80 FL	*40.80 FL
16	1		*SET REAR PARKING SENSORS	Dented	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,287.30</b>	<b>3,462.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	813.46	652.42
<b>Total Parts (\$)</b>	<b>3,473.84</b>	<b>2,809.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL ,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL ,REAR BODY PANEL ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER AND ADJUST REAR BODY AND TAILGATE ALIGNMENT	New	550.00	450.00
2	TO APPLY ANTI-CORROSION TUFF-KOTE ON REWELDED SEAMS	New	100.00	30.00
3	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	650.00	600.00
4	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	35.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,335.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >