#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### **VEHICLE DAMAGE INSPECTION REPORT**

Nature of Claim:

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CS/AIG20012302/R1QF3E2

Singapore 079120

Date:

OD

30/12/2020

**REFERENCE** 

Date of Loss:

Insured/Claimant:

Policy No:

1700051656

Engine No:

Chassis No:

Odometer:

Claim No: 4394731296SG

4B12TQ3970

67873 km

JMYXTGF3WJZ000418

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLS7712R

Make & Model: MITSUBISHI OUTLANDER, 2.4 CVT (A)

WAYNE JEROME SANDHU

Reg. Date: 04/10/2017 (Man. Year: 2017)

09/11/2020

Colour: Black
Engine Capacity: 2360 cc
Market Value/New Car Price: \$\$83,000,00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Roadstone 6 mm
Front Right Side: Roadstone 6 mm
Rear Left Side: Roadstone 6 mm
Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,753.39	7,012.96	2,740.43	28.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,610.00	5,770.00	1,840.00	24.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	17,363.39	12,782.96	4,580.43	26.38
	+ GST 7.00/7.00% (S\$)	1,215.44	894.81	320.63	26.38
	Nett Amount (S\$)	18,578.83	13,677.77	4,901.06	26.38

**INSPECTION** 

Date of Assignment: 10/11/2020

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)

Date Inspected: 10/11/2020 Inspected At: 209 Pandan Gardens

Singapore 609339

Adjuster:	MOHD RASUL	Manager:	SHIAU CHAN

Estimated Period of Repair:

10.0 days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*FACE, RR BUMPER	Deformed	807.00 FL	*807.00 FL
2 1	*BRKT, R/BMPR FACE SIDE, LH	Necessary	12.00 FL	*12.00 FL
3 1	*BRKT, R/BMPR FACE SIDE, RH	Necessary	12.00 FL	*12.00 FL
1 10	*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
5 1	*REINFORCEMENT, RR BUMPER, LH	Bent	79.00 FL	*79.00 FL
3 1	*REINFORCEMENT, RR BUMPER, RH	Bent	79.00 FL	*79.00 FL
7 1	*EXTENSION, RR BUMPER	Deformed	232.00 FL	*232.00 FL
3 1	*REFLECTOR, TAIL LAMP, LH	Serviceable	100.00 FL	*- FL
9 1	*REFLECTOR, TAIL LAMP, RH	Serviceable	95.00 FL	*-FL
10 1	*LAMP ASSY, TAIL LH	Cracked	506.00 FL	*506.00 FL
11 1	*LAMP ASSY, TAIL RH	Cracked	506.00 FL	*506.00 FL
12 1	*LAMP ASSY, COMB, RR LH	Scratched	600.00 FL	*600.00 FL
13 1	*LAMP ASSY, COMB, RR RH	Scratched	600.00 FL	*600.00 FL
14 1	*PANEL ASSY, TAILGATE	Bent	984.00 FL	*984.00 FL
15 1	*W/STRIP, TAILGATE OPENING	Serviceable	213.00 FL	*-FL
16 2	*HINGE, TAILGATE	Serviceable	92.00 FL	*-FL
17 1	*GAS SPRING, TAILGATE, LH	Serviceable	194.00 FL	*-FL
18 1	*GAS SPRING, TAILGATE, RH	Serviceable	194.00 FL	*- FL
19 1	*GARNISH, TAILGATE	Cracked	494.00 FL	*494.00 FL
20 2	*DAM, TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
21 4	*FASTENER, WINDSHIELD	Necessary	24.00 FL	*24.00 FL
22 1	*DAM, TAILGATE, UPR	Necessary	13.00 FL	*13.00 FL
23 2	*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
24 1	*DAM, TAILGATE, LWR	Necessary	41.00 FL	*41.00 FL
25 1	*LATCH, TAILGATE	Serviceable	475.00 FL	*-FL
26 1	*STRIKER, TAILGATE LATCH	Serviceable	19.00 FL	*- FL
27 1	*SENSOR, TAILGATE LOCK, LH	Serviceable	426.00 FL	*-FL
28 1	*SENSOR, TAILGATE LOCK, RH	Serviceable	426.00 FL	*-FL
29 1	*GLASS, TAILGATE WINDOW	Not Necessary	654.00 FL	*-FL
30 1	*PANEL, RR END	Bent	324.00 FL	*324.00 FL
31 1	*TRIM, RR END	Deformed	123.00 FL	*123.00 FL
32 1	*BOX, CARGO FLOOR	Serviceable	204.00 FL	*- FL
33 1	*ANT, KEYLESS OPERATION, RR	Serviceable	96.00 FL	*-FL
34 1	*BUZZER, KEYLESS OPERATIO, RR	Serviceable	91.00 FL	*- FL
35 2	*LAMP ASSY, LICENSE PLATE	Serviceable	68.00 FL	*-FL
36 1	*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
37 1	*AERO KIT - OUTLANDER	Cracked	1,554.00 FS	*1,554.00 FS
38 1	*DECAL, MIVEC	Necessary	36.00 FL	*36.00 FL
39 1	*MOULDING, RR BUMPER, LH	Serviceable	106.00 FL	*-FL
10 1	*MOULDING, RR BUMPER, RH	Serviceable	106.00 FL	*-FL
<b>1</b> 1 1	*TRIM, TAILGATE	Deformed	329.00 FL	*329.00 FL
12 1	*RR NUMBER PLATE WITH CASING	Necessary	50.00 FS	*50.00 FS

No. (	Qty Part No.	Particulars	Condition	Repairer's	Amount
43		*REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
44 1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
45 1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
46 1		*MOLDING, RR WHEEL ARCH, LH (Supplementary)	Necessary	199.00 FL	*199.00 FL
47		*MOLDING, RR WHEEL ARCH, RH (Supplementary)	Necessary	199.00 FL	*199.00 FL
48 1		*CARRIER, SPARE TIRE (Supplementary)	Bent	254.00 FL	*254.00 FL
F=Franc	chise part. S=SpcNett. L	=ListItemDisc.			
			Sub Total (S\$)	12,101.00	8,542.00
			- List Item Discount on L Items 23.00/23.00% (S\$)	2,347.61	1,529.04
			Total Parts (S\$)	9,753.39	7,012.96
			Report was unsubmitted during this print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	MOTOR, POWER TAILGATE	New	-	-
2	RENEW RR BUMPER, TAILGATE & RR END PNL REPAIR RR FLR PNL, LHR FENDER & RHR FENDER.	New	4,050.00	2,250.00
3	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, TAILGATE, LHR FENDER & RHR FENDER.	New	2,450.00	2,450.00
4	REMOVE & REFIT TAILGATE COMPONENTS.	New	120.00	120.00
5	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & TO GIVE WAY FOR REPAIR.	New	120.00	120.00
6	CHASSIS ELECTRICAL FREE TEXT.	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS.	New	80.00	40.00
9	SUPPLY BODY PNL SEALANT.	New	60.00	60.00
10	REMOVE & REFIT RR WINDSCREEN GLASS.	New	240.00	240.00
11	SUPPLY RR WINDSCREEN SEALANT.	New	80.00	80.00
12	REMOVE & REFIT REVERSE SENSOR.	New	60.00	60.00
13	CONDUCT FLOOR PULLING. (Supplementary)	New	200.00	200.00
		Gross Labour Cost (S\$)	7,610.00	5,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >