



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Wayne Jerome Sandhu
	Reg No/Reg Date	SLS7712R / 04/10/201
	Date In/Mileage	/ 67873
	Chassis No	JMYXTGF3WJZ000418
	Engine No	4B12TQ3970
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E02)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/11/2020/ 10:21	BLE	261 / Edwin Caina	59418			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								
MOTOR, POWER TAILGATE-(TBA) ?								
JJ5813A149								
E PNT88000								2250
RENEW RR BUMPER, TAILGATE & RR END PNL @ 450 X 5								4080.00
REPAIR RR FLR PNL, LHR FENDER & RHR FENDER								
E PNT98000								2450.00
RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, TAILGATE, LHR FENDER & RHR FENDER @ 350 X 7								
E PNT88000								120.00
REMOVE & REFIT TAILGATE COMPONENTS								
E PNT88000								120.00
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & TO GIVE WAY FOR REPAIR								
A 54900099								30.00
CHASSIS ELECTRICAL FREE TEXT								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								40
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								60.00
SUPPLY BODY PNL SEALANT								
E PNT88000								240.00
REMOVE & REFIT RR WINDSCREEN GLASS								
M SUNDRY								80.00
SUPPLY RR WINDSCREEN SEALANT								
M SUNDRY								50.00
SUPPLY RR NUMBER PLATE WITH CASING								
E PNT88000								60.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								220.00
SUPPLY REVERSE SENSOR								
M SUNDRY								40.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Wayne Jerome Sandhu
	Reg No/Reg Date	SLS7712R / 04/10/201
	Date In/Mileage	/ 67873
	Chassis No	JMYXTGF3WJZ000418
	Engine No	4B12TQ3970
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E02)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/11/2020/ 10:21	BLE	261 / Edwin Caina	59418

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUPPLY C&C BADGE				30.00
M SUNDRY Sundries				30.00
M FACE,RR BUMPER <i>de</i>	1.00	807.00	23.00	621.39
M BRKT,R/BMPR FACE SIDE,LH <i>nee</i>	1.00	12.00	23.00	9.24
M BRKT,R/BMPR FACE SIDE,RH <i>nee</i>	1.00	12.00	23.00	9.24
M CLIP,FR BUMPER <i>nee</i>	10.00	4.00	23.00	30.80
M REINFORCEMENT,RR BUMPER,LH <i>bt</i>	1.00	79.00	23.00	60.83
M REINFORCEMENT,RR BUMPER,RH <i>bt</i>	1.00	79.00	23.00	60.83
M EXTENSION,RR BUMPER <i>de</i>	1.00	232.00	23.00	178.64
M REFLECTOR,TAIL LAMP,LH <i>? x sue</i>	1.00	100.00	23.00	77.00
M REFLECTOR,TAIL LAMP,RH <i>? x sue</i>	1.00	95.00	23.00	73.15
M LAMP ASSY,TAIL,LH <i>can</i>	1.00	506.00	23.00	389.62
M LAMP ASSY,TAIL,RH <i>can</i>	1.00	506.00	23.00	389.62
M LAMP ASSY,COMB,RR LH <i>sue</i>	1.00	600.00	23.00	462.00
M LAMP ASSY,COMB,RR RH <i>sue</i>	1.00	600.00	23.00	462.00
M PANEL ASSY,TAILGATE <i>bt</i>	1.00	984.00	23.00	757.68
M W/STRIP,TAILGATE OPENING <i>? x sue</i>	1.00	213.00	23.00	164.01
M HINGE,TAILGATE <i>x sue</i>	2.00	46.00	23.00	70.84
M GAS SPRING,TAILGATE,LH <i>x sue</i>	1.00	194.00	23.00	149.38
M GAS SPRING,TAILGATE,RH <i>x sue</i>	1.00	194.00	23.00	149.38
M GARNISH,TAILGATE <i>? can</i>	1.00	494.00	23.00	380.38
M DAM,TAILGATE SIDE <i>nee</i>	2.00	27.00	23.00	41.58
M FASTENER,WINDSHIELD <i>nee</i>	4.00	6.00	23.00	18.48
M DAM,TAILGATE,UPR <i>nee</i>	1.00	13.00	23.00	10.01
M STOPPER,WINDSHIELD GLASS <i>nee</i>	2.00	3.00	23.00	4.62
M DAM,TAILGATE,LWR <i>nee</i>	1.00	41.00	23.00	31.57
M LATCH,TAILGATE <i>? x sue</i>	1.00	475.00	23.00	365.75
M STRIKER,TAILGATE LATCH <i>? x sue</i>	1.00	19.00	23.00	14.63
M SENSOR,TAILGATE LOCK,LH <i>? x sue</i>	1.00	426.00	23.00	328.02
M SENSOR,TAILGATE LOCK,RH <i>? x sue</i>	1.00	426.00	23.00	328.02
M GLASS,TAILGATE WINDOW <i>? x sue</i>	1.00	654.00	23.00	503.58
M PANEL,RR END <i>bt</i>	1.00	324.00	23.00	249.48

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Wayne Jerome Sandhu
	Reg No/Reg Date	SLS7712R / 04/10/201
	Date In/Mileage	/ 67873
	Chassis No	JMYXTGF3WJZ000418
	Engine No	4B12TQ3970
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E02)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/11/2020/ 10:21	BLE	261 / Edwin Caina	59418

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TRIM,RR END <i>de</i>	1.00	123.00	23.00	94.71
M BOX,CARGO FLOOR <i>? fsv</i>	1.00	204.00	23.00	157.08
M ANT,KEYLESS OPERATION,RR <i>? fsv</i>	1.00	96.00	23.00	73.92
M BUZZER,KEYLESS OPERATIO,RR <i>? fsv</i>	1.00	91.00	23.00	70.07
M LAMP ASSY,LICENSE PLATE <i>? fsv</i>	2.00	34.00	23.00	52.36
M MARK,OUTLANDER <i>ne</i>	1.00	95.00	23.00	73.15
M AERO KIT - OUTLANDER <i>ca</i>	1.00	1554.00	00.00	1554.00
M DECAL,MIVEC <i>ne</i>	1.00	36.00	23.00	27.72
M MOULDING,RR BUMPER,LH <i>? fsv</i>	1.00	106.00	23.00	81.62
M MOULDING,RR BUMPER,RH <i>? fsv</i>	1.00	106.00	23.00	81.62
M TRIM,TAILGATE <i>de</i>	1.00	329.00	23.00	253.33

Estimate

SURVEYOR NAME : Rahul - H/ 90010068

SURVEYOR SIGNATURE : [Signature]

DATE : 10/11/2020 @ 16:30

REMARKS : 10 days

EXCESS: TBA / Renewal

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

	Nett	16,661.35
7% GST on	16661.35	1166.29
Total Payable		17,827.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.