

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012304/GTF3E2
Date: 15/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00129602000
Claimant Vehicle No : SBS5050Z Insured Vehicle No : SKN1004D
Date of Loss: 31/10/2020 Nature of Claim: TP Claim No: SNM20D204145/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS5050Z
Make & Model: SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A) Engine No: 6604782
Reg. Date: 11/03/2010 (Man. Year: 2009) Chassis No: YS2K4X20001867055
Colour: Purple Odometer: 758603 km
Engine Capacity: 9290 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	950.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	950.00	950.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	66.50	66.50	0.00	0.00
Nett Amount (S\$)	1,016.50	1,016.50	0.00	0.00

INSPECTION

Date of Assignment: 10/11/2020
Date Inspected: 10/11/2020 Inspected At: SBS Transit Ltd (AMK)
15 Ang Mo Kio Street 63
Singapore 569117
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Jan 2021)	
Parts:	N/A	SCANIA KUB4X2 9.3L A/T ABS TURBO 9.3 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS5050Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REPLACE 1PC X RIGHT SIDE TAILLIGHT }	Cracked	0.00 F	*- F
2	1		*REPLACE RIGHT SIDE REAR DOME }	Cracked	0.00 F	*- F
3	1		*REPLACE RIGHT SIDE PANEL NO.9 }	Bent	0.00 F	*- F
4	1		*REPLACE REAR BUMPER }	Cracked	0.00 F	*- F
5	1		*REPAIR VERTICAL PILLAR }	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY 3 WORKERS (19 WORKING HOURS) }	New	950.00	950.00
2	SPRAY PAINTING REAR BUMPER }	New	0.00	0.00
3	SPRAY PAINTING RIGHT SIDE REAR DOME }	New	0.00	0.00
Gross Labour Cost (\$\$)			950.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >