

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012308/KPA3Q2
Date: 09/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100300243
Claimant Vehicle No :	SDN8988B	Insured Vehicle No :	SKF2868M
Date of Loss:	31/08/2020	Nature of Claim:	TP
		Claim No:	3648098162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDN8988B	Engine No:	CZC418573
Make & Model:	VOLKSWAGEN SPORTSVAN, 1.4 (A)	Chassis No:	WVWZZZAUZGW529557
Reg. Date:	14/10/2016 (Man. Year: 2015)	Odometer:	81357 km
Colour:	Metallic Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,376.65	1,115.43	2,261.22	66.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	435.00	1,045.00	70.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,856.65	1,550.43	3,306.22	68.08
Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	4,856.65	1,200.00	3,656.65	75.29
+ GST 7.00/7.00% (S\$)	339.97	84.00	255.97	75.29
Nett Amount (S\$)	5,196.62	1,284.00	3,912.62	75.29
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		1,584.00		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment: 10/11/2020

Date Inspected: 25/11/2020

Inspected At:

Yee Auto Pte Ltd (HQ)

160 SIN MING DRIVE #02-17 SIN MING AUTOCITY

Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,450.50 F	*1,124.14 FL
2	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	65.20 F	*- FL
3	1		*REAR BUMPER SIDE RETAINER -RH	Serviceable	65.20 F	*- FL
4	1		*REAR BUMPER REFLECTOR -RH	Serviceable	195.15 F	*- FL
5	1		*REAR BUMPER LOWER PAD	Serviceable	285.10 F	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	620.00 F	*- FL
8	1		*REAR BUMPER TOWING COVER	Serviceable	60.00 F	*- FL
9	1		*TAIL LAMP RH	Serviceable	585.50 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	3,376.65 1,174.14
					- List Item Discount on L Items 0.00/5.00% (\$)	0.00 58.71
					Total Parts (\$)	3,376.65 1,115.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	600.00	200.00
2	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	600.00	220.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	200.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	15.00
Gross Labour Cost (S\$)			1,480.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >