



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                        |  |           |
|--|--|------------------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |  |                        | Ref: CS/AGI20012309/Aqf3q2<br>Date: 25/01/2021 | Code: AGI |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                        |  |           |
| <b>Insured Veh.</b>  | SMA 1384B  | <b>Veh. Inspected</b>  | GBJ 126U                                       |           |
| <b>Policy No.</b>  |  | <b>Coverage (\$)</b>   | 0.00   |           |
| <b>Claim No.</b>   | C10007904/LA   | <b>Excess (\$)</b>     | 0.00   |           |
| <b>Assign From</b>   | IVY RATILLA  | <b>Assign Date</b>     | 10/11/2020                                     |           |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                        |  |           |
| <b>Make &amp; Model</b>  | TOYOTA HIACE   | <b>c.c</b>             | 2754   |           |
| <b>Engine No.</b>  | HIDDEN   | <b>Year of Reg.</b>    | 2018   |           |
| <b>Chassis No.</b>   | GDH2012001956  | <b>Colour</b>          | WHITE  |           |
| <b>Odometer</b>  | 79881 KM   | <b>Steering</b>        | IN ORDER                                       |           |
| <b>Brakes</b>  | IN ORDER   | <b>Modification</b>    | NIL  |           |
| <b>General</b>   | GOOD   |                        |  |           |
| <b>3. Conditions of Tyres</b>  |  |                        |  |           |
|  | <b>Size</b>  | <b>Make</b>            | <b>Balance</b>                                 |           |
| <b>R/H Front Tyre</b>  | 195 R15C   | DUNLOP                 | 6 mm   |           |
| <b>L/H Front Tyre</b>  | 195 R15C   | DUNLOP                 | 6 mm   |           |
| <b>R/H Rear Tyre</b>   | 195 R15C   | DUNLOP                 | 6 mm   |           |
| <b>L/H Rear Tyre</b>   | 195 R15C   | DUNLOP                 | 6 mm   |           |
| <b>4. Description of Damages</b>   |  |                        |  |           |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br>DAMAGES SEE DETAILS.  |  |                        |  |           |
| <b>5. General Information</b>  |  |                        |  |           |
| <b>Accident Date</b>   | 08/11/2020   | <b>Inspection Date</b> | 19/11/2020                                     |           |
| <b>Survey held at</b>  | SMARTONE AUTO PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                        |  |           |
| <b>5a. Remarks</b>   |  |                        |  |           |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |  |                        |  |           |
| <b>5b. Estimate Days of Repair</b>   |  |                        |  |           |
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>   |  |                        | <b>3 Working Days</b>                          |           |