

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012314/UYD3E2

Date: 18/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00002812001
Claimant Vehicle No :	GBK437S	Insured Vehicle No :	SMG8926K
Date of Loss:	08/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204284/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK437S		
Make & Model:	MITSUBISHI L200 D/CABIN, 2.5 D L 5MT TURBO D/AIRBAG 4WD (M)	Engine No:	4D56UCBA3322
Reg. Date:	21/08/2008 (Man. Year: 2007)	Chassis No:	MMBJRKB407D152792
Colour:	Black	Odometer:	239920 km
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/70R16	Rear Tyre Size:	245/70R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,993.00	1,429.90	5,563.10	79.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,400.00	350.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,743.00	2,829.90	5,913.10	67.63
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	8,743.00	2,250.00	6,493.00	74.27
+ GST 7.00/7.00% (S\$)	612.01	157.50	454.51	74.27
Nett Amount (S\$)	9,355.01	2,407.50	6,947.51	74.27

INSPECTION

Date of Assignment:	10/11/2020		
Date Inspected:	10/11/2020	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Nov 2020)	
Parts:	N/A	mitsubishi L200 D/CABIN 2.5 D L 5MT TURBO D/AIRBAG 4WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK437S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (LEFT)	Distorted	118.00 F	*118.00 FN
2	1		*REAR BUMPER (RIGHT)	Distorted	118.00 F	*118.00 FN
3	1		*REAR BUMPER (CENTRE)	Distorted	416.00 F	*416.00 FN
4	1		*LH REAR FENDER REFLECTOR	Cracked	27.00 F	*27.00 FN
5	1		*LH TAILLAMP	Not Necessary	305.00 F	*- FN
6	1		*TAILGATE	Repair	918.00 F	*- FN
7	1		*TAILGATE TRITON EMBLEM	Necessary	85.00 F	*85.00 FN
8	1		*TAILGATE 2.5VG EMBLEM	Necessary	60.00 F	*60.00 FN
9	1		*TAILGATE TURBO EMBLEM	Necessary	75.00 F	*75.00 FN
10	1		*REAR END PANEL	Badly Dented	412.00 F	*412.00 FN
11	1		*REAR FLOOR PANEL	Repair	3,539.00 F	*- FN
12	1		*LH REAR FENDER	Repair	660.00 F	*- FN
13	1		*NUMBER PLATE WITH COVER	Broken	50.00 FS	*40.00 FS
14	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
15	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,993.00	1,561.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	131.10
Total Parts (\$\$)	6,993.00	1,429.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED PARTS	New	800.00	700.00
2	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS	New	950.00	700.00
Gross Labour Cost (\$\$)			1,750.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >