

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012316/KVF3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00029502000
Claimant Vehicle No :	SMH5708M	Insured Vehicle No :	GBG2361J
Date of Loss:	29/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204160/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH5708M		Engine No:	G4FGJU044023
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)		Chassis No:	KMHD841CMKU815342
Reg. Date:	28/01/2019 (Man. Year: 2018)		Odometer:	23469 km
Colour:	Metallic Red			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,033.68	4,030.00	2,003.68	33.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,390.00	400.00	22.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,823.68	5,420.00	2,403.68	30.72
+ GST 7.00/7.00% (\$\$)	547.66	379.40	168.26	30.72
Nett Amount (\$\$)	8,371.34	5,799.40	2,571.94	30.72

INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	09/11/2020 Inspected At:	160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722 REPAIRER: K KIM HIN AUTO PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH5708M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Serviceable	56.00 FL	*- FL
2	1		*REAR BUMPER-TOP	Buckled	459.40 FL	*459.40 FL
3	1		*REAR BUMPER-LOWER	Cracked	353.30 FL	*353.30 FL
4	2		*REAR BUMPER LOWER LAMP (LH/RH)	Cracked	403.00 FL	*403.00 FL
5	10		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
7	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Cracked	157.20 FL	*157.20 FL
8	3		*REAR BUMPER LOWER BRACKET STAY	Cracked	15.00 FL	*15.00 FL
9	2		*REAR BUMPER UPPER BRACKET STAY	Cracked	10.00 FL	*10.00 FL
10	1		*REAR BUMPER SIDE RETAINER (LH/RH)	N/s Distorted	58.80 FL	*29.40 FL
11	1		*REAR BUMPER SIDE LOWER UNDERCOVER-LH	Serviceable	37.20 FL	*- FL
12	1		*REAR BUMPER SIDE LOWER UNDERCOVER-RH	Serviceable	20.00 FL	*- FL
13	1		*REAR BUMPER LOWER LAMP WIREHARNES	Serviceable	122.60 FL	*- FL
14	1		*BOOTLID	Bent	1,782.40 FL	*1,782.40 FL
15	1		*BOOTLID LOCK	Dented	116.20 FL	*116.20 FL
16	1		*BOOTLID LOCK CATCH	Repair	15.00 FL	*- FL
17	1		*BOOTLID LOGO	Necessary	196.20 FL	*158.00 FL
18	1		*BOOTLID AVANTE EMBLEM	Necessary	31.20 FL	*31.20 FL
19	1		*BOOTLID WEATHERSTRIP	Serviceable	92.50 FL	*- FL
20	1		*BOOTLID LAMP (LH/RH)	O/s Cracked/N/s Serviceable	569.80 FL	*284.90 FL
21	1		*BOOTLID INNER TRIMLINING	Serviceable	146.80 FL	*- FL
22	8		*BOOTLID INNER TRIMLINING CLIPS	Not Necessary	16.00 FL	*- FL
23	1		*BOOTLID REVERSE CAMERA	Serviceable	826.10 FL	*- FL
24	1		*REAR END PANEL	Bent	454.60 FL	*454.60 FL
25	1		*REAR END PANEL TOP GARNISH	Serviceable	59.80 FL	*- FL
26	1		*TAILLAMP ASSY (LH/RH)	O/s Cut/N/s Serviceable	870.20 FL	*435.10 FL
27	1		*REAR NUMBER BASE GARNISH	Dented	33.00 FL	*33.00 FL
28	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
29	1		*REVERSE SENSOR ASSY	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,477.10	5,037.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,443.42	1,007.50
Total Parts (\$\$)	6,033.68	4,030.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	800.00	600.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	60.00	50.00
3	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING,ROOF LINING,SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	60.00
4	TO APPLY UNDERSEALING	New	80.00	60.00
5	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION	New	50.00	20.00
6	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	680.00	600.00
Gross Labour Cost (S\$)			1,790.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >