

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD **TP** WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s MOTOR IMAGE

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:	_____		
IDAC Accident Rpt:	_____	Consistent? :	Yes or No
GIA / PR Seen:	_____	Consistent? :	Yes or No
Est. Repairs:	<u>5</u>	days	Res.: Yes or No
Lum Sum:	_____	%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: SLH 3380Z Yr Regn: 31 Oct/2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: SUBARU LEVORG 1.6 c.c 1600

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 89817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1VM4K55GG002550 *

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or _____

Brake: ☒ Order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/45ZR18

R: 225/45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or KUMHO

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>25-11-2020</u>
*Survey held at _____	W/S	<u>2:30pm</u>

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Confirmed COR \$4865.6 before GST @ 5 working days
	RED: 5340.4; 52%

Date/Time, File Pass to? ☐ : Preli. Report

1) : Final Report

Date/Time, File Return to?

29

Front Panel:

Lynn S. Allen

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

☐ Interview (\$

Tech. Invs. (3)

11/Nov/eng 18

Survey Fee:

Transportation:

5)	$S + RS.$	SI
----	-----------	----

Photos

Others

1074