

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20012327/R1GS3Q2

**Date:** 10/02/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> YN7030Y	<b>Insured Vehicle No :</b>	SHA4175C
Date of Loss: 09/11/2020	Nature of Claim: TP	Claim No: MCT20110133

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN7030Y		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Engine No:	4P10B37201
Reg. Date:	18/11/2014 (Man. Year: 2014)	Chassis No:	FEB21EA00902
Colour:	White	Odometer:	301332 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,850.00	635.00	1,215.00	65.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	470.00	840.00	64.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,160.00</b>	<b>1,105.00</b>	<b>2,055.00</b>	<b>65.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	3,160.00	900.00	2,260.00	71.52
<b>+ GST 7.00/7.00% (S\$)</b>	221.20	63.00	158.20	71.52
<b>Nett Amount (S\$)</b>	<b>3,381.20</b>	<b>963.00</b>	<b>2,418.20</b>	<b>71.52</b>
<b>+ Loss of Use (2.0 x S\$80.00/day) (S\$)</b>		160.00		
<b>Nett Liability (S\$)</b>		<b>1,123.00</b>		

### INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	30/11/2020 Inspected At:	Automotive Repair Centre Pte Ltd (HQ)
		38 Woodlands Industrial Park E1, #05-18
		Singapore 757700
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Jan 2021)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEB21ER3SDEB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YN7030Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LICENSE PLATE LAMP	Cracked	200.00 F	*200.00 FL
2	1		*REAR LICENCE BRACKET	Bent	100.00 F	*100.00 FL
3	1		*REAR TAIL LAMP RH	Cracked	300.00 F	*300.00 FL
4	1		*REAR LICENSE PLATE	Bent	40.00 FS	*35.00 FS
5	1		*TAILGATE METAL FRAME RH	Serviceable	200.00 FS	*- FS
6	1		*REAR REINFORCEMENT TOP BAR	Bent	250.00 FS	*150.00 FS
7	1		*REAR REINFORCEMENT TOP BAR BRACKET RH	Serviceable	100.00 FS	*- FS
8	10		*REAR REINFORCEMENT BOLT & LOCK NUT	Serviceable	60.00 FS	*- FS
9	1		*REAR REINFORCEMENT LOWER BAR ASSY (14FT)	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,850.00</b>	<b>785.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	150.00
<b>Total Parts (\$\$)</b>	<b>1,850.00</b>	<b>635.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	SPRAY PAINTING WHOLE REAR	New	600.00	200.00
2	REMOVE ,REFIT AND REPAIR AFFECTED ACCIDENT PARTS	New	600.00	200.00
3	ANTI-RUST TUFF COAT	New	80.00	40.00
4	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,310.00</b>	<b>470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >