

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012328/KRS3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SML1146P	Insured Vehicle No :	SHD4233C
Date of Loss: 09/11/2020	Nature of Claim: TP	Claim No: MCT20110135

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML1146P		
Make & Model:	MERCEDES-BENZ C200, 2.0 SEDAN AVG (R17 LED) (A)	Engine No:	HIDDEN
Reg. Date:	01/01/2016 (Man. Year: 2016)	Chassis No:	WDD2050422R119099
Colour:	White	Odometer:	104911 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,549.60	8,989.60	16,560.00	64.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,320.00	3,480.00	72.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,349.60	10,309.60	20,040.00	66.03
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	30,349.60	8,000.00	22,349.60	73.64
+ GST 7.00/7.00% (S\$)	2,124.47	560.00	1,564.47	73.64
Nett Amount (S\$)	32,474.07	8,560.00	23,914.07	73.64
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
Nett Liability (S\$)		9,960.00		

INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	11/11/2020 Inspected At:	Autoexcel Engineering Pte Ltd (HQ) 160 Sin Ming Drive #06-01,, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts:	143	MERCEDES-BENZ C200 2.0 SEDAN AVG (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML1146P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (NPA)	Repair	0.00 FL	*- FL
2	1		*BOOTLID CENTER LOGO	Necessary	140.00 FL	*80.00 FL
3	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
4	1		*FRONT RH SEAT BELT	Jammed	1,125.00 FL	*725.00 FL
5	1		*SEAT BELT BUCKLE RH	Serviceable	580.00 FL	*- FL
6	1		*SEAT BELT ECU	Necessary	3,250.00 FL	*1,850.00 FL
7	1		*TAILLAMP LH	Mtg Cracked	1,480.00 FL	*748.00 FL
8	1		*TAILLAMP LOWER BRACKET LH	Serviceable	385.00 FL	*- FL
9	1		*REAR BUMPER SIDE SENSOR LH	Shorted	380.00 FL	*245.00 FL
10	1		*REAR BUMPER CENTER SENSOR LH	Serviceable	380.00 FL	*- FL
11	1		*REAR DIFFUSER SENSOR LH	Serviceable	380.00 FL	*- FL
12	1		*END PANEL	Repair	850.00 FL	*- FL
13	1		*END PANEL TOP GARNISH	Serviceable	480.00 FL	*- FL
14	1		*REAR BUMPER SENSOR CABLE	Serviceable	1,125.00 FL	*- FL
15	1		*REAR BUMPER SENSOR BRACKETS	Serviceable	504.00 FL	*- FL
16	1		*REAR BUMPER LH SIDE BRACKETS	Repair	480.00 FL	*- FL
17	1		*REAR BUMPER SPONGE	Serviceable	450.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	780.00 FL	*646.00 FL
19	1		*REAR EXHAUST (LOCAL REPAIR)	Dented	2,016.00 FS	*350.00 FS
20	1		*REAR EXHAUST MOUNTING	Serviceable	385.00 FL	*- FL
21	1		*REAR BUMPER (AMG)	Cracked	4,800.00 FS	*2,850.00 FS
22	8		*REAR BUMPER CLIPS	Necessary	450.00 FS	*80.00 FS
23	1		*REAR BUMPER RIVET (15 PCS)	Necessary	45.00 FS	*45.00 FS
24	1		*REAR BUMPER CENTER DIFFUSER	Cracked	3,500.00 FS	*1,800.00 FS
25	1		*REAR BUMPER LH SIDE LOWER SPOILER	Serviceable	500.00 FS	*- FS
26	2		*REAR BUMPER SIDE FINS	Serviceable	800.00 FS	*- FS
27	2		*REAR EXHAUST CHROME END LH	Serviceable	1,600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,865.00	9,419.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,315.40	429.40
Total Parts (\$\$)	25,549.60	8,989.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO DO CUTTING ,WELDING ,REMOVE REFIX ,REPLACE REAR ACCIDENT AFFECTED AREA	New	1,400.00	400.00
2	TO REPLACE REAR EXHAUST	New	200.00	0.00
3	TO REPLACE REAR SENSOR AND CABLE ASSY	New	250.00	0.00
4	TO CHECK WIRING SYSTEM	New	150.00	20.00
5	TO REPLACE SEAT BELT AND ECU	New	250.00	150.00
6	TO REMOVE REFIX ,REPLACE GARNISH ,SIDE TRIM ,CAR SEAT ,UPHOLSTERY ETC	New	350.00	0.00
7	TO DO ANTI RUST	New	100.00	0.00
8	TO DO SEALANT ,SEAL GAP ,WATERPROOFING ON CUTTING WELDING ACCIDENT AREA	New	200.00	0.00
9	TO DELETE RESET FAULT CODE ,PROGRAMMING ECU AFTER REPAIR	New	500.00	250.00
10	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,400.00	500.00
Gross Labour Cost (\$\$)			4,800.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >