

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20012329/R1QF3Q2

**Date:** 01/02/2021

### REFERENCE

Insured/Claimant:	TAN JUE LING, CHERYL	Policy No:	2070145372
Date of Loss:	10/11/2020	Nature of Claim:	OD
		Claim No:	5103487221SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV6964J	Engine No:	4J11CQ4591
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0700761
Reg. Date:	15/10/2020 (Man. Year: 2020)	Odometer:	1003 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,351.29	7,455.16	3,896.13	34.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,755.00	5,610.00	2,145.00	27.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>19,106.29</b>	<b>13,065.16</b>	<b>6,041.13</b>	<b>31.62</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,337.44</b>	<b>914.56</b>	<b>422.88</b>	<b>31.62</b>
<b>Nett Amount (\$\$)</b>	<b>20,443.73</b>	<b>13,979.72</b>	<b>6,464.01</b>	<b>31.62</b>

### INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	10/11/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	13.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REFLECTOR, TAIL LAMP, LH	Cracked	100.00 FL	*100.00 FL
2	1		*REFLECTOR, TAIL LAMP, RH	Cracked	100.00 FL	*100.00 FL
3	1		*LAMP ASSY, LICENSE PLATE	Serviceable	34.00 FL	*- FL
4	1		*LAMP ASSY, TAIL, LH	Serviceable	506.00 FL	*- FL
5	1		*LAMP ASSY, TAIL, RH	Serviceable	506.00 FL	*- FL
6	1		*EXTENSION, RR BUMPER	Torn	292.00 FL	*292.00 FL
7	1		*FACE, RR BUMPER	Torn	807.00 FL	*807.00 FL
8	1		*BRKT, R/BMPR FACE SIDE, LH	Necessary	12.00 FL	*12.00 FL
9	1		*BRKT, R/BMPR FACE SIDE, RH	Necessary	12.00 FL	*12.00 FL
10	1		*REINFORCEMENT, RR BUMPER, LH	Bent	79.00 FL	*79.00 FL
11	1		*REINFORCEMENT, RR BUMPER, RH	Serviceable	79.00 FL	*- FL
12	1		*PANEL, RR END	Bent	324.00 FL	*324.00 FL
13	1		*SHIELD, RR WHEEL, FR LH (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*GLASS, TAILGATE WINDOW	Serviceable	654.00 FL	*- FL
15	1		*DAM, TAILGATE SIDE	Necessary	27.00 FL	*27.00 FL
16	4		*FASTENER, WINDSHIELD	Necessary	24.00 FL	*24.00 FL
17	1		*DAM, TAILGATE UPR	Necessary	13.00 FL	*13.00 FL
18	1		*GARNISH, TAILGATE	Serviceable	494.00 FL	*- FL
19	8		*STOPPER, WINDSHIELD GLASS	Necessary	24.00 FL	*24.00 FL
20	1		*DAM, TAILGATE LWR	Necessary	41.00 FL	*41.00 FL
21	1		*PANEL ASSY, TAILGATE	Bent	984.00 FL	*984.00 FL
22	1		*W/STRIP, TAILGATE OPENING	Serviceable	213.00 FL	*- FL
23	1		*STRIKER, TAILGATE LATCH	Serviceable	19.00 FL	*- FL
24	1		*LATCH, TAILGATE	Serviceable	475.00 FL	*- FL
25	1		*TRIM, TAILGATE	Serviceable	329.00 FL	*- FL
26	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
27	1		*TRIM, RR END	Serviceable	113.00 FL	*- FL
28	1		*EXTENSION, FR BUMPER	Scratched	515.00 FL	*515.00 FL
29	1		*COVER, FR BUMPER	Cracked	359.00 FL	*359.00 FL
30	1		*REINFORCEMENT, FR BUMPER	Serviceable	508.00 FL	*- FL
31	1		*MUFFLER, EXHAUST MAIN	Bent	579.00 FL	*579.00 FL
32	1		*HANGER, EXHAUST MUFFLER	Serviceable	19.00 FL	*- FL
33	1		*HANGER, EXHAUST MUFFLER	Serviceable	19.00 FL	*- FL
34	1		*GASKET, CATALYTIC CONVERTER	Necessary	11.00 FL	*11.00 FL
35	1		*HANGER, EXHAUST MUFFLER	Serviceable	17.00 FL	*- FL
36	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
37	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
38	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
39	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
40	1		*BUZZER, KEYLESS OPERATION, RR (Supplementary)	Cracked	91.00 FL	*91.00 FL
41	1		*ANT, KEYLESS OPERATION, RR (Supplementary)	Cracked	96.00 FL	*96.00 FL
42	1		*MOULDING, RR BUMPER, LH (Supplementary)	Cracked	88.00 FL	*88.00 FL
43	1		*FACE, FR BUMPER (Supplementary)	Cracked	859.00 FL	*859.00 FL
44	10		*RIVET, FR BUMPER (Supplementary)	Necessary	50.00 FL	*50.00 FL
45	1		*GARNISH, FR BUMPER SIDE (Supplementary)	Scratched	112.00 FL	*112.00 FL
46	1		*PANEL ASSY, TAILGATE (Supplementary)	Repeated	984.00 FL	-
47	1		*PIPE, EXHAUST, CTR (Supplementary)	Bent	1,814.00 FL	*1,814.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		<b>*BODY KIT, OUTLANDER</b> (Supplementary)	Necessary	1,554.00 FS	*1,554.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
<b>Sub Total (S\$)</b>					<b>14,221.00</b>	<b>9,182.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (S\$)</b>					2,869.71	1,726.84
<b>Total Parts (S\$)</b>					<b>11,351.29</b>	<b>7,455.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA. REPAIR ON REAR BOTH FENDER	New	2,700.00	1,350.00
2	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & BOTH REAR FENDER	New	1,750.00	1,400.00
3	REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR	New	120.00	100.00
4	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
5	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
6	REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR	New	120.00	120.00
7	TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL	New	120.00	80.00
8	PERFORM RUST PREVENTION ON AFFECTED AREAS	New	120.00	40.00
9	APPLY SEALANT ON AFFECTED AREA	New	80.00	0.00
10	TO REPLACE REAR EXHAUST MUFFLER	New	225.00	225.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	TO REPLACE FRONT BUMPER MIDDLE COVER	New	450.00	225.00
14	REPLACE REAR END PANEL PANEL & REPAIR REAR FLOOR PANEL (Supplementary)	New	675.00	675.00
15	SPRAY PAINT REAR FLOOR PANEL (Supplementary)	New	350.00	350.00
16	REPLACE FRONT BUMPER (Supplementary)	New	225.00	225.00
17	SPRAY PAINT FRONT BUMPER (Supplementary)	New	350.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,755.00</b>	<b>5,610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >