

Reg No : 197701469G

## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

Page 1 of 3

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE** 

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV16151/TAN JUE LING, CHERYL	
Ltd.	Reg No/Reg Date	SMV6964J / 15/10/202	
MOTOR CLAIM DEPT	Date In/Mileage	10/11/2020/ 0	
78 SHENTON WAY #08-16	Chassis No	GF7W0700761	
AIG BUILDING SINGAPORE 079120	Engine No 4J11CQ4591		
SINGAPORE 0/9120 Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)	
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	10/11/2020/ 15:30	QUK	282 / Kevin Leong		59420		
		Description of Good	ds / Service	S	Qty	Unit Price		Amount ,
		PER, TAILGATE, END F	PANEL & AFI	FECTED AREA @YSU X3			1	350 2700.00
E PNT98000		/ /		LH				[YOU1750.00
E PNT88000				_ & BOTH REAR FENDER				Low 120.00
REMOVE &	INSTALL	REAR PARKING ASSIST	TO FACIL	ITATE REPAIR				
E PNT88000	INSTALL	REAR WINDSCREEN GLA	SS EOD EN	TILITATE DEDAID				240.00
1 SUNDRY			133 FUR FAI	CICITATE REPAIR				80.00
TO APPLY PNT88000	WINDSCRE	EN SEALANT	$\sim$ $\Lambda$		١ _			120.00
	INSTALL	REAR BOOT COMPARTME	WIS TO FACE	HITATE REPAIR 211	[(8	7)	1	120.00
PNT88000	-CD TAIL C	ATE ATTACHMENT TO			$\mathcal{U}$	フ	1	80 120.00
SUNDRY	EK TAILG	ATE ATTACHMENT TO N	IEW PANEL				1	\$ 120.00
PERFORM R	UST PREV	ENTION ON AFFECTED	AREAS					( )
SUNDRY							1	X 80.00
15900099	LANT ON	AFFECTED AREA						×225.00
	F RFAR F	XHAUST MUFFLER					1	/ \223.00
54900099	L KLIK LI	All Hollice					1	30.00
CHECK WIR	ING & CHA	ASSIS ELECTRICAL SY	STEM					Market Base
10028901			UT COAN DO	00 TECT			1	120.00
USING HI-		NOSTIC CHECK USING	HI-SCAN PH	(0 IE31			- 1	
SUNDRY	SCAN PRO	1531					- 1	40.00
SUPPLY C	& C EMBLE	EM					7	
SUNDRY								50.00
TO REPLAC	E FRONT N	NUMBER PLATE WITH F	RAME 🗡					X 50 00
SUNDRY	C 0540 M	IMPED DIATE MITTI FO	AME					225 450.00
PNT88000	E KEAK NO	JMBER PLATE WITH FR	AME				1	225 450 00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info		
2000	Cust No/Name	KCV16151/TAN JUE LING, CHERYL		
AIG Asia Pacific Insurance Pte. Ltd.	Reg No/Reg Date	SMV6964J / 15/10/202		
MOTOR CLAIM DEPT	Date In/Mileage	10/11/2020/ 0		
78 SHENTON WAY #08-16	Chassis No	GF7W0700761		
AIG BUILDING	Engine No	4J11CQ4591		
SINGAPORE 079120 Contact No 6419 1892	Make/Model MIT/20MY OUTLANDER 2.0 STYLE (			
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

Account No	Terms	Date/Time Pr	inted	CSE	Opera	tor		WIP No		
KAX00008	Credit	10/11/2020/	DATE OF THE PARTY	QUK	282 /	Kevin Leong		59420		
Кихоооо	0.00.0	Description			s		Qty	<b>Unit Price</b>	Disc%	Amount
TO REPLAC	E FRONT	BUMPER MIDDL								/
M SUNDRY SUNDRIES			2,62627,226							30 50.0
M DEFLECTOR	TATI IA	AMP, LHCA					1.00	100.00	23.00	77.0
M REFLECTOR	TATLLA	AMP RH 7					1.00	100.00		77.0
M LAMP ASSY	LICENSE	PLATE 7					1.00	34.00	23.00	26.1
M LAMP ASSY							1.00	506.00	23.00	389.6
M LAMP ASS							1.00	506.00		389.6
		ER torn -					1.00	292.00	23.00	224.8
M FACE, RR E							1.00	807.00	23.00	621.3
		SIDE, LH MEY					1.00	12.00	23.00	9.2
		SIDE, RH AL		257	TI CO	na	Z.00	12.00	23.00	9.2
		BUMPER, LH 3	<b>—</b> (	211	$\Pi\Pi$	1121	1.00	79.00	23.00	60.8
		BUMPER, RH 1	7	J) (	$\Pi\Pi\Pi$	111(31	(4.60-)	7 79.00	23.00	60.8
PANEL, RR				$\cup$			1.00	324.00	23.00	249.4
SHIELD, RE							1.00		23.00	
GLASS, TAI							1.00	654.00	23.00	503.5
DAM, TAILG							1.00		23.00	20.7
FASTENER,							4.00		23.00	18.4
DAM, TAILG	ATE UPR	ne/					1.00	13.00	23.00	10.0
GARNISH, T	AILGATE	?					1.00	494.00	23.00	380.3
STOPPER.W	INDSHIEL	D GLASS W-					8.00	3.00	23.00	18.4
DAM, TAILG							1.00	41.00	23.00	31.5
		TE by					1.00	984.00	23.00	757.6
W/STRIP,T							1.00	213.00	23.00	164.0
STRIKER,T							1.00	19.00	23.00	14.6
LATCH, TAI							1.00	475.00		365.7
TRIM, TAIL							1.00	329.00		253.3
MARK, OUTL							1.00	95.00	23.00	73.1
TRIM, RR E	ND Z						1.00	113.00	23.00	87.0
EXTENSION		FR SCE					1.00	515.00		396.5
1 COVER, FR							1.00	359.00	23.00	276.4
M REINFORCE							1.00	508.00	23.00	391.1

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Tyra Sizar

Page 2 of 3

23+112010



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Reg No : 197701469G

Authorized signatory and company stamp

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV16151/TAN JUE LING, CHERYL		
Ltd.	Reg No/Reg Date	SMV6964J / 15/10/202		
MOTOR CLAIM DEPT	Date In/Mileage	10/11/2020/ 0		
78 SHENTON WAY #08-16	Chassis No	GF7W0700761		
AIG BUILDING SINGAPORE 079120	Engine No 4J11CQ4591			
Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)		
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	10/11/2020/ 15:30	QUK	282 / Kevin Leong		59420		
		Description of Goods	s / Services	k .	Qty	Unit Price	Disc%	Amount
MUFFLER,					1.00	579.00		445.8
		UFFLER X			1.00		23.00	14.6
		UFFLER ×			1.00		23.00	14.6
		CONVERTER X			1.00		23.00	8.4 13.0
•		, ,						
			<b>3</b> 亿	imat	J	1		
			511		( KK	Nuto Consulta	ints hence r	notify
			96		U The	Repairer of the resurvey before/af	following:	loo.
					• To	display damaged p	art(s) during r	esurvev
					• Pa	rts prices are subje	ect to confirmat	tion
					• Thi	ird party survey is o	on a "Without F	Prejudice" basis
						illegal modification		
					• Su is s	subject to final app	s) must be rest roval from last	urveyed and
			$\overline{}$		is s	subject to final app	roval from lasu	urveyed and urance Company
		(	Porul	LLO 9volos68	is s Ackr	subject to final appropriet	roval from lasu	urveyed and irance Company
		CURVEYOR NAME: _	Rosul -	4 900 LOSG 8	is s Ackr Sign	subject to final appl nowledged by Repa ature:	roval from lasu	urveyed and wance Company
			' (L	4 90010068	is s Ackr	subject to final appl nowledged by Repa ature:	roval from lasu	urveyed and trance Company
		SURVEYOR SIGNATUR	RE:	۸	is s Ackr Sign	subject to final appl nowledged by Repa ature:	roval from lasu	urveyed and urance Company
		SURVEYOR SIGNATUR	RE:	4 900 10068 1	is s Ackr Sign	subject to final appl nowledged by Repa ature:	roval from lasu	urveyed and trance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and trance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and trance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and wance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and wance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and urance Company
		SURVEYOR SIGNATUR	RE: The Reduced to	ハ' ハン	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and trance Company
Confirm & ac	cepted by	CURVEYOR SIGNATUR  DATE:	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	roval from lasu	urveyed and wance Company
onfirm & ac	cepted by	CURVEYOR SIGNATUR  DATE:	RE: The Reduced to	ハ <u>ハ</u> ハル	is s Ackr Sign	subject to final appl nowledged by Repa ature;	oval from lasu	12,799.S
onfirm & ac	cepted by	CURVEYOR SIGNATUR  DATE:	RE: The Reduced to	nov ys Revers for print	is s Ackr Sign	nowledged by Repa ature:	oval from lasu	arance Company

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.