



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|--|---------------------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name | KCV16151/TAN JUE LING, CHERYL |
| | Reg No/Reg Date | SMV6964J / 15/10/202 |
| | Date In/Mileage | 10/11/2020/ 0 |
| | Chassis No | GF7W0700761 |
| | Engine No | 4J11CQ4591 |
| | Make/Model | MIT/20MY OUTLANDER 2.0 STYLE (999) |
| | Colour/Trim | U01 TITANIUM GREY M/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|--------|-------------------|-----|-------------------|-----------------------------|
| KAX00008 | Credit | 10/11/2020/ 15:30 | QUK | 282 / Kevin Leong | 59420 |
| Description of Goods / Services | | | | | Qty Unit Price Disc% Amount |
| E PNT88000 | | | | | 1350 2700.00 |
| REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA @450 X3 | | | | | |
| REPAIR ON REAR BOTH FENDER | | | | | |
| E PNT98000 | | | | | 1400 1750.00 |
| PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & BOTH REAR FENDER | | | | | |
| E PNT88000 | | | | | 100 120.00 |
| REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR | | | | | |
| E PNT88000 | | | | | 240.00 |
| REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR | | | | | |
| M SUNDRY | | | | | 80.00 |
| TO APPLY WINDSCREEN SEALANT | | | | | |
| E PNT88000 | | | | | 120.00 |
| REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR | | | | | |
| E PNT88000 | | | | | 80 120.00 |
| TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL | | | | | |
| M SUNDRY | | | | | 40 120.00 |
| PERFORM RUST PREVENTION ON AFFECTED AREAS | | | | | |
| M SUNDRY | | | | | 11 X 80.00 |
| APPLY SEALANT ON AFFECTED AREA | | | | | |
| A 15900099 | | | | | 225.00 |
| TO REPLACE REAR EXHAUST MUFFLER | | | | | |
| A 54900099 | | | | | 30.00 |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | |
| A 10028901 | | | | | 120.00 |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | |
| USING HI-SCAN PRO TEST | | | | | |
| M SUNDRY | | | | | 40.00 |
| SUPPLY C & C EMBLEM | | | | | |
| M SUNDRY | | | | | 50.00 |
| TO REPLACE FRONT NUMBER PLATE WITH FRAME | | | | | |
| M SUNDRY | | | | | 11 X 50.00 |
| TO REPLACE REAR NUMBER PLATE WITH FRAME | | | | | |
| E PNT88000 | | | | | 225 450.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

| Invoice Name & Address | Owner Name & Vehicle Info | | | | | | | | | | | | | | |
|---|--|--------------|-------------------------------|-----------------|----------------------|-----------------|---------------|------------|-------------|-----------|------------|------------|------------------------------------|-------------|-------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | <tr> <td>Cust No/Name</td><td>KCV16151/TAN JUE LING, CHERYL</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMV6964J / 15/10/202</td></tr> <tr> <td>Date In/Mileage</td><td>10/11/2020/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0700761</td></tr> <tr> <td>Engine No</td><td>4J11CQ4591</td></tr> <tr> <td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 STYLE (999)</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> | Cust No/Name | KCV16151/TAN JUE LING, CHERYL | Reg No/Reg Date | SMV6964J / 15/10/202 | Date In/Mileage | 10/11/2020/ 0 | Chassis No | GF7W0700761 | Engine No | 4J11CQ4591 | Make/Model | MIT/20MY OUTLANDER 2.0 STYLE (999) | Colour/Trim | U01 TITANIUM GREY M/ BK BLACK |
| Cust No/Name | KCV16151/TAN JUE LING, CHERYL | | | | | | | | | | | | | | |
| Reg No/Reg Date | SMV6964J / 15/10/202 | | | | | | | | | | | | | | |
| Date In/Mileage | 10/11/2020/ 0 | | | | | | | | | | | | | | |
| Chassis No | GF7W0700761 | | | | | | | | | | | | | | |
| Engine No | 4J11CQ4591 | | | | | | | | | | | | | | |
| Make/Model | MIT/20MY OUTLANDER 2.0 STYLE (999) | | | | | | | | | | | | | | |
| Colour/Trim | U01 TITANIUM GREY M/ BK BLACK | | | | | | | | | | | | | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|--|--------|-------------------|------------|-------------------|----------|
| KAX00008 | Credit | 10/11/2020/ 15:30 | QUK | 282 / Kevin Leong | 59420 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| TO REPLACE FRONT BUMPER MIDDLE COVER | | | | | 30 50.00 |
| M SUNDRY | | | | | |
| SUNDRIES | | | | | |
| M REFLECTOR, TAIL LAMP, LH <i>cm</i> | | 1.00 | 100.00 | 23.00 | 77.00 |
| M REFLECTOR, TAIL LAMP, RH <i>cm</i> | | 1.00 | 100.00 | 23.00 | 77.00 |
| M LAMP ASSY, LICENSE PLATE <i>? xsvl</i> | | 1.00 | 34.00 | 23.00 | 26.18 |
| M LAMP ASSY, TAIL, LH <i>x svl</i> | | 1.00 | 506.00 | 23.00 | 389.62 |
| M LAMP ASSY, TAIL, RH <i>x svl</i> | | 1.00 | 506.00 | 23.00 | 389.62 |
| M EXTENSION, RR BUMPER <i>turn</i> | | 1.00 | 292.00 | 23.00 | 224.84 |
| M FACE, RR BUMPER <i>turn</i> | | 1.00 | 807.00 | 23.00 | 621.39 |
| M BRKT, R/BMPR FACE SIDE, LH <i>new</i> | | 1.00 | 12.00 | 23.00 | 9.24 |
| M BRKT, R/BMPR FACE SIDE, RH <i>new</i> | | 1.00 | 12.00 | 23.00 | 9.24 |
| M REINFORCEMENT, RR BUMPER, LH <i>? Bt</i> | | 1.00 | 79.00 | 23.00 | 60.83 |
| M REINFORCEMENT, RR BUMPER, RH <i>? xsvl</i> | | 1.00 | 79.00 | 23.00 | 60.83 |
| M PANEL, RR END <i>repair</i> | | 1.00 | 324.00 | 23.00 | 249.48 |
| M SHIELD, RR WHEEL, FR LH <i>x svl</i> | | 1.00 | 0.00 | 23.00 | |
| M GLASS, TAILGATE WINDOW <i>? xsvl</i> | | 1.00 | 654.00 | 23.00 | 503.58 |
| M DAM, TAILGATE SIDE <i>new</i> | | 1.00 | 27.00 | 23.00 | 20.79 |
| M FASTENER, WINDSHIELD <i>new</i> | | 4.00 | 6.00 | 23.00 | 18.48 |
| M DAM, TAILGATE, UPR <i>new</i> | | 1.00 | 13.00 | 23.00 | 10.01 |
| M GARNISH, TAILGATE <i>? xsvl</i> | | 1.00 | 494.00 | 23.00 | 380.38 |
| M STOPPER, WINDSHIELD GLASS <i>new</i> | | 8.00 | 3.00 | 23.00 | 18.48 |
| M DAM, TAILGATE, LWR <i>new</i> | | 1.00 | 41.00 | 23.00 | 31.57 |
| M PANEL ASSY, TAILGATE <i>bt</i> | | 1.00 | 984.00 | 23.00 | 757.68 |
| M W/STRIP, TAILGATE OPENING <i>? xsvl</i> | | 1.00 | 213.00 | 23.00 | 164.01 |
| M STRIKER, TAILGATE LATCH <i>x svl</i> | | 1.00 | 19.00 | 23.00 | 14.63 |
| M LATCH, TAILGATE <i>x svl</i> | | 1.00 | 475.00 | 23.00 | 365.75 |
| M TRIM, TAILGATE <i>x svl</i> | | 1.00 | 329.00 | 23.00 | 253.33 |
| M MARK, OUTLANDER <i>new</i> | | 1.00 | 95.00 | 23.00 | 73.15 |
| M TRIM, RR END <i>? xsvl</i> | | 1.00 | 113.00 | 23.00 | 87.01 |
| M EXTENSION, FR BUMPER <i>new</i> | | 1.00 | 515.00 | 23.00 | 396.55 |
| M COVER, FR BUMPER <i>? cm</i> | | 1.00 | 359.00 | 23.00 | 276.43 |
| M REINFORCEMENT, FR BUMPER <i>x svl</i> | | 1.00 | 508.00 | 23.00 | 391.16 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name KCV16151/TAN JUE LING, CHERYL Reg No/Reg Date SMV6964J / 15/10/202 Date In/Mileage 10/11/2020/ 0 Chassis No GF7W0700761 Engine No 4J11CQ4591 Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999) Colour/Trim U01 TITANIUM GREY M/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|--------|-------------------|-------|-------------------|--------|
| KAX00008 | Credit | 10/11/2020/ 15:30 | QUK | 282 / Kevin Leong | 59420 |
| Description of Goods / Services | | | | | |
| | Qty | Unit Price | Disc% | Amount | |
| M MUFFLER, EXHAUST MAIN 2 <i>1</i> | 1.00 | 579.00 | 23.00 | 445.83 | |
| M HANGER, EXHAUST MUFFLER X <i>SVL</i> | 1.00 | 19.00 | 23.00 | 14.63 | |
| M HANGER, EXHAUST MUFFLER X <i>SVL</i> | 1.00 | 19.00 | 23.00 | 14.63 | |
| M GASKET, CATALYTIC CONVERTER 2 <i>1</i> | 1.00 | 11.00 | 23.00 | 8.47 | |
| M HANGER, EXHAUST MUFFLER X <i>SVL</i> | 1.00 | 17.00 | 23.00 | 13.09 | |

Estimate

LK/Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Rekul - Hp 9000068*SURVEYOR SIGNATURE: *Ph*DATE: *10/11/2020 @ 1700*REMARKS: *8 days**Excess: TBA / REPAIR**Resurvey before print*

Confirm & accepted by

Nett 12,799.91
7% GST on 12799.91 895.99
Total Payable 13,695.90

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Survey Fee:

Days of Repair
Resurvey No. of Trip:Days of Repair
Final Report