

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20012334/KQF3Q2

**Date:** 30/11/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001551640

**Claimant**  
**Vehicle No :** GBD5666B

**Insured Vehicle No :** SLX5784U

Date of Loss: 09/11/2020

Nature of Claim: TP

Claim No: 249594

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD5666B**

Make & Model: TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)

Engine No: 1KD2453745

Reg. Date: 16/12/2014 (Man. Year: 2014)

Chassis No: KDY2318017576

Colour: Silver

Odometer: 162832 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195R15X8

Rear Tyre Size: 145R12X8(D)

Front Left Side: Michelin 5 mm

Rear Left Side: Yokohama 2/2 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Yokohama 2/2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,819.92	1,588.08	231.84	12.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	970.00	340.00	25.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,129.92</b>	<b>2,558.08</b>	<b>571.84</b>	<b>18.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	3,129.92	2,000.00	1,129.92	36.10
<b>+ GST 7.00/7.00% (S\$)</b>	219.09	140.00	79.09	36.10
<b>Nett Amount (S\$)</b>	<b>3,349.01</b>	<b>2,140.00</b>	<b>1,209.01</b>	<b>36.10</b>

### INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 11/11/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A

Singapore 768761

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Nov 2020)	
<b>Parts:</b>	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD5666B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,349.97 FL	*1,349.97 FL
2	1		*FRONT RH DOOR LAMP	Missing	56.90 FL	*56.90 FL
3	1		*FRONT RH DOOR LOWER INNER RUBBER	Serviceable	83.58 FL	*- FL
4	1		*FRONT RH DOOR INNER RUBBER	Serviceable	186.34 FL	*- FL
5	1		*FRONT RH WHEEL ARP RUBBER	Serviceable	39.20 FL	*- FL
6	1		*FRONT BUMPER	Dented/Cut	683.90 FL	*683.90 FL
7	1		*FRONT RH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
					<b>Sub Total (\$\$)</b>	<b>2,419.89 2,110.77</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>599.97 522.69</b>
					<b>Total Parts (\$\$)</b>	<b>1,819.92 1,588.08</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE & REFIX FRT RH DOOR.TRANSFER LOCK ASSY,SIDE MIRROR,STEP TRAY & REALIGN THE SAME	New	450.00	360.00
2	REMOVE & REFIX FRT RH DOOR GLASS	New	60.00	60.00
3	PUTTY & RESPRAY FRT RH DOOR,WHEEL ARP PANEL,FRT BUMPER	New	600.00	400.00
4	TO REWRITE ADVERTISEMENT	New	200.00	150.00
<b>Gross Labour Cost (\$)</b>			<b>1,310.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**