

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012339/T1GS3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SLK3063Z	Insured Vehicle No :	YQ1456B
Date of Loss:	06/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3063Z	Engine No:	L15B4405878
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11205877
Reg. Date:	12/01/2017 (Man. Year: 2016)	Odometer:	54708 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,169.20	2,247.60	921.60	29.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,210.00	1,200.00	35.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,579.20	4,457.60	2,121.60	32.25
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	6,579.20	3,550.00	3,029.20	46.04
+ GST 7.00/7.00% (S\$)	460.54	248.50	212.04	46.04
Nett Amount (S\$)	7,039.74	3,798.50	3,241.24	46.04
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,727.50		

INSPECTION

Date of Assignment: 10/11/2020

Date Inspected: 17/11/2020 Inspected At:

Wah Hong Motors & Credit Pte Ltd
(HQ)
38 Toh Guan Road East, #01-57,
Enterprise Hub
Singapore 608581

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3063Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	950.00 FL	*950.00 FL
2	1		*FRONT BUMPER	Repair	802.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER LH/RH	Necessary	36.00 FL	*36.00 FL
4	1		*FRONT FENDER RH	Bent	580.00 FL	*580.00 FL
5	1		*FRONT FENDER SHIELD	Deformed	130.00 FL	*130.00 FL
6	1		*REAR WHEEL ARCH GARNISH RH	Deformed	153.00 FL	*153.00 FL
7	1		*FRONT ROCKER PANEL LOWER SIDE GARNISH	Distorted	378.00 FL	*378.00 FL
8	1		*REAR DOOR HINGE UPPER RH	Bent	45.00 FL	*45.00 FL
9	1		*REAR DOOR HINGE LOWER RH	Bent	45.00 FL	*45.00 FL
10	1		*FRONT BONNET (REPAIR REFER TO LABOUR AND PAINT) (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT FENDER LH (REPAIR REFER TO LABOUR AND PAINT) (NPA)	Repair	0.00 FL	*- FL
12	1		*FRONT FENDER SHIELD CLIPS	Necessary	35.00 FS	*20.00 FS
13	1		*FRONT BUMPER CLIPS	Not Necessary	35.00 FS	*- FS
14	1		*FRONT RIM RH	Cut	580.00 FS	*350.00 FS
15	1		*FRONT FENDER INNER AIR GUIDE RH	Deformed	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,799.00	2,717.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	629.80	469.40
Total Parts (\$\$)	3,169.20	2,247.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	700.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,200.00	1,000.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	60.00
4	TO REMOVE AND REFIT WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	150.00	30.00
5	CHECK AND ADJUST WHEEL ALIGNMENT	New	100.00	80.00
6	TO REMOVE AND REFIX /REPLACE FRONT LH DOOR FITTINGS ,TRIMMINGS ,GARNISH ,GLASS WINDOW AND ETC	New	120.00	60.00
7	RESEALING OF OFF PEAK CAR LICENSE PLATE AT LTA INCLUDING INSPECTION FEES	New	100.00	60.00
8	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS (RHS ROCKER PANEL)	New	200.00	100.00
9	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED (RHS ROCKER PANEL)	New	200.00	100.00
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS (RHS ROCKER PANEL)	New	20.00	20.00
Gross Labour Cost (\$\$)			3,410.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >