

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20012341/R1CD3E2

**Date:** 14/04/2021

### REFERENCE

Insured/Claimant:	CHAN PERRY M	Policy No:	1800072304		
Date of Loss:	08/11/2020	Nature of Claim:	OD	Claim No:	1484677098SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMA9335R</b>				
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)		Engine No:	CHZ933727	
Reg. Date:	22/06/2018 (Man. Year: 2018)		Chassis No:	WAUZZZ8V5JA110102	
Colour:	White		Odometer:	46813 km	
Engine Capacity:	999 cc				
Market Value/New Car Price:	S\$86,000.00				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	29,150.00	14,285.04	14,864.96	50.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,452.00	7,222.00	7,230.00	50.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>43,602.00</b>	<b>21,507.04</b>	<b>22,094.96</b>	<b>50.67</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	43,002.00	20,907.04	22,094.96	51.38
<b>+ GST 7.00/7.00% (S\$)</b>	3,010.14	1,463.49	1,546.65	51.38
<b>Nett Amount (S\$)</b>	<b>46,012.14</b>	<b>22,370.53</b>	<b>23,641.61</b>	<b>51.38</b>

### INSPECTION

Date of Assignment:	11/11/2020		
Date Inspected:	10/11/2020	Inspected At:	24 Benoi Sector Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days		

**Adjuster:** MOHD RASUL

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,842.00 FS	*1,473.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Serviceable	76.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	159.00 FS	*126.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	293.00 FS	*234.40 FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Serviceable	586.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	189.00 FS	*150.80 FS
9	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
10	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Serviceable	372.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Bent	715.00 FS	*571.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
14	1		*FOAM FILLER PIECE COVER	Deformed	121.00 FS	*96.40 FS
15	1		*SIGNAL HORN RETAINER - LH HIGH TONE	Serviceable	197.00 FS	*- FS
16	1		*SIGNAL HORN RETAINER - RH LOW TONE	Serviceable	197.00 FS	*- FS
17	1		*FRONT FENDER - LH / RH	N/S Bent / O/S Repair	1,682.00 FS	*672.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
19	2		*FRONT FENDER BRACKET - LH / RH	Serviceable	94.00 FS	*- FS
20	2		*FRONT FENDER BRACE - LH / RH	Serviceable	190.00 FS	*- FS
21	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Serviceable	122.00 FS	*- FS
22	2		*WHEEL HOUSING LINER - LH / RH	Serviceable	334.00 FS	*- FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Serviceable	57.00 FS	*- FS
24	1		*BONNET	Bent	2,709.00 FS	*2,167.20 FS
25	1		*BONNET ATTACHMENT PARTS	Serviceable	163.00 FS	*- FS
26	2		*BONNET LID HINGE - LH / RH	Bent	122.00 FS	*96.48 FS
27	1		*BONNET EDGE PROTECTION - FRONT	Necessary	28.00 FS	*21.84 FS
28	1		*BONNET SAFETY CATCH	Serviceable	89.00 FS	*- FS
29	2		*BONNET STRIKER - LH / RH	Serviceable	218.00 FS	*- FS
30	1		*BONNET CATCH HOOK	Serviceable	63.00 FS	*- FS
31	2		*BONNET LID LOCK	Serviceable	423.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE - CENTRE	Serviceable	57.00 FS	*- FS
33	1		*BONNET LID LOCK CABLE	Serviceable	73.00 FS	*- FS
34	1		*BONNET SOUND ABSORBER	Serviceable	217.00 FS	*- FS
35	1		*PLENUM CHAMBER COVER	Cracked	177.00 FS	*141.60 FS
36	1		*BONNET GAS FILLED STRUT	Serviceable	118.00 FS	*- FS
37	1		*LED HEADLIGHT - LH / RH	N/S Cracked	10,910.00 FS	*4,364.00 FS
38	2		*LIFT CYLINDER - LH / RH	Serviceable	282.00 FS	*- FS
39	1		*LIFT CYLINDER HOSE	Serviceable	67.00 FS	*- FS
40	1		*WATER DEFLECTOR STRIP - LH / RH	O/S Scratched	132.00 FS	*52.80 FS
41	1		*LOCK CARRIER	Cracked	719.00 FS	*575.20 FS
42	1		*AIRCON CONDENSER	Dented	517.00 FS	*413.20 FS
43	1		*ADDITIONAL RADIATOR	Bent	859.00 FS	*687.20 FS
44	1		*RADIATOR	Bent	941.00 FS	*752.80 FS
45	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
46	2		*RADIATOR BRACKET	Damaged	79.00 FS	*62.88 FS
47	2		*RADIATOR BUSH - LOWER	Serviceable	19.00 FS	*- FS
48	1		*TEMPERATURE SENSOR BRACKET	Serviceable	18.00 FS	*- FS
49	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	48.00 FS	*38.40 FS
50	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Cracked	12.00 FS	*9.36 FS
51	1		*AIR INTAKE AIR DUCT COVER	Cracked	28.00 FS	*22.00 FS
52	1		*AIR INTAKE AIR GUIDE - FRONT	Cracked	54.00 FS	*43.20 FS
53	1		*AIR INTAKE AIR GUIDE	Serviceable	64.00 FS	*- FS
54	1		*AIR INTAKE AIR GUIDE SEAL	Serviceable	13.00 FS	*- FS
55	1		*AIR INTAKE AIR DUCT	Serviceable	19.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*WATER DRAINAGE HOSE	Serviceable	32.00 FS	*- FS
57	1		*AIR INTAKE AIR FILTER	Serviceable	269.00 FS	*- FS
58	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
59	1		*SUNDRIES	Necessary	300.00 FS	*37.52 FS
60	1		*FRONT CATCH HOOK	Bent	63.00 F	*49.76 F
			(Supplementary)			

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** 29,150.00 14,285.04

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	700.00	500.00
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS	New	700.00	0.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS	New	5,500.00	2,300.00
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,452.00</b>	<b>7,222.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >