

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20012342/ABA3Q2
Date: 19/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SKT7338U	Insured Vehicle No :	SHD2074H
Date of Loss:	03/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7338U		
Make & Model:	CHEVROLET CAPTIVA, 2.4 Premium (A)	Engine No:	LE9142820037
Reg. Date:	22/06/2015 (Man. Year: 2014)	Chassis No:	KL1CA26UJFB014288
Colour:	Bronze	Odometer:	88269 km
Engine Capacity:	2384 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R17	Rear Tyre Size:	235/60 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,481.50	6,939.20	9,542.30	57.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,880.00	2,360.00	4,520.00	65.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,361.50	9,299.20	14,062.30	60.19
Approved Total (Overridden) (S\$)		7,400.00		

(S\$)	23,361.50	7,400.00	15,961.50	68.32
+ GST 7.00/7.00% (S\$)	1,635.31	518.00	1,117.31	68.32
Nett Amount (S\$)	24,996.81	7,918.00	17,078.81	68.32
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Medical Costs (S\$)		115.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,440.45		
Global Sum Settlement (S\$)		8,400.00		

INSPECTION

Date of Assignment: 10/11/2020

Date Inspected: 11/11/2020

Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2021)
Parts:	M1-SUV	CHEVROLET CAPTIVA 2.4 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7338U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,860.00 FL	*2,860.00 FL
2	1		*CHVEROLET LETTERING	Necessary	56.00 FL	*56.00 FL
3	1		*CAPTIVA LETTERING WITH LT	Necessary	57.00 FL	*57.00 FL
4	1		*LT LETTERING	Necessary	20.00 FL	*20.00 FL
5	1		*REAR TAILGATE WINDSCREEN WITH MOULDING	Not Necessary	1,053.00 FL	*- FL
6	1		*LH TAILGATE HINGE	Not Necessary	86.00 FL	*- FL
7	1		*RH TAILGATE HINGE	Not Necessary	86.00 FL	*- FL
8	1		*REAR TAILGATE INNER TRIM	Not Necessary	283.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Cut	145.00 FL	*145.00 FL
10	1		*REAR TAILGATE LATCH	Not Necessary	180.00 FL	*- FL
11	1		*REAR TAILGATE STRIKER	Not Necessary	60.00 FL	*- FL
12	1		*LHR TAILLAMP	Not Necessary	1,475.00 FL	*- FL
13	1		*RHR TAILLAMP	Not Necessary	1,475.00 FL	*- FL
14	1		*LHR UPPER BUMPER	Not Necessary	328.00 FL	*- FL
15	1		*RHR UPPER BUMPER	Not Necessary	328.00 FL	*- FL
16	1		*LHR BUMPER BRACKET	Not Necessary	65.00 FL	*- FL
17	1		*RHR BUMPER BRACKET	Not Necessary	65.00 FL	*- FL
18	1		*REAR BUMPER LOWER	Deformed	885.00 FL	*885.00 FL
19	1		*LHR CENTRE BUMPER GUIDE	Not Necessary	65.00 FL	*- FL
20	1		*RHR CENTRE BUMPER GUIDE	Not Necessary	65.00 FL	*- FL
21	1		*LHR BUMPER REFLECTOR	Cracked	662.00 FL	*662.00 FL
22	1		*RHR BUMPER REFLECTOR	Cracked	662.00 FL	*662.00 FL
23	1		*REAR BUMPER LOWER MOULDING SILL PLATE	Deformed	570.00 FL	*570.00 FL
24	1		*REAR BUMPER TOWING COVER	Not Necessary	45.00 FL	*- FL
25	1		*REAR BUMPER REINFORCEMENT BAR	Bent	566.00 FL	*566.00 FL
26	1		*REAR END PANEL	Repair	458.00 FL	*- FL
27	1		*REAR END PANEL TRIM	Not Necessary	190.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*EXHAUST RH -MUFFLER ,TAIL PIPE	Not Necessary	1,885.00 FL	*- FL
29	1		*EXHAUST LH -MUFFLER ,TAIL PIPE	Not Necessary	1,885.00 FL	*- FL
30	1		*EXHAUST MOUNTING RH	Not Necessary	60.00 FL	*- FL
31	1		*EXHAUST MOUNTING LH	Not Necessary	60.00 FL	*- FL
32	1		*REVERSE SENSOR (3 POINTS)	Damaged	440.00 FL	*440.00 FL
33	1		*REVERSE SENSOR WIRING HARNESS	Cracked	330.00 FL	*330.00 FL
34	10		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	65.00 FS	*- FS
35	10		*REAR BUMPER LOWER CLIPS	Necessary	65.00 FS	*50.00 FS
36	10		*REAR END PANEL TRIM CLIPS	Not Necessary	65.00 FS	*- FS
37	1		*REAR TAILGATE WINDSCREEN THERMAL FILM	Not Necessary	190.00 FS	*- FS
38	1		*REAR WINDSCREEN SEALANT	Necessary	90.00 FS	*60.00 FS
39	1		*KEYLESS RECEIVER SENSOR	Cracked	335.00 FL	*335.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,260.00	7,698.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,778.50	758.80
Total Parts (S\$)	16,481.50	6,939.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,300.00	1,100.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	2,700.00	900.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT ,AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	110.00	30.00
4	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	110.00	60.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	110.00	50.00
6	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	110.00	110.00
7	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	110.00	0.00
8	TO REMOVE AND REPLACE EXHAUST PIPE	New	110.00	0.00
9	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR	New	110.00	0.00
10	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	110.00	110.00
Gross Labour Cost (\$\$)			6,880.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >