

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012343/KEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119351
Claimant Vehicle No :	SJU3210L	Insured Vehicle No :	SMU5722C
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	1250288169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU3210L		
Make & Model:	MINI COOPER, 1.6 CONVERTIBLE AT ABS D/AB 2DR (A)	Engine No:	B342I587
Reg. Date:	30/11/2009 (Man. Year: 2009)	Chassis No:	WMWMR32030TL36422
Colour:	Metallic Silver	Odometer:	90489 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	540.00	210.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	750.00	540.00	210.00	28.00
+ GST 7.00/7.00% (S\$)	52.50	37.80	14.70	28.00
Nett Amount (S\$)	802.50	577.80	224.70	28.00
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		705.80		

INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	16/08/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR BUMPER ASSY ,REFLECTORS ,REPAIR ,REALIGN REAR BUMPER	New	300.00	180.00
2	PUTTY AND RESPRAY ON REAR BUMPER	New	300.00	220.00
3	REMOVE AND REFIT REVERSE SENSOR & RESET SYSTEM	New	50.00	40.00
4	PAINT PROTECTION	New	100.00	100.00
Gross Labour Cost (\$\$)			750.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >