

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20012348/T1GS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800070455
Claimant		
Vehicle No : SMG7084X	Insured Vehicle No :	SMC6600J
Date of Loss: 09/11/2020	Nature of Claim: TP	Claim No: 6054790566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7084X	Engine No:	CYV629283
Make & Model:	VOLKSWAGEN BEETLE, 1.2 TSI (A)	Chassis No:	WVWZZZ16ZKM700992
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	29506 km
Colour:	Red		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R18	Rear Tyre Size:	235/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,024.25	1,535.30	1,488.95	49.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,400.00	3,280.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,704.25	3,935.30	4,768.95	54.79
+ GST 7.00/7.00% (\$\$)	609.30	275.47	333.83	54.79
Nett Amount (\$\$)	9,313.55	4,210.77	5,102.78	54.79
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,392.77		

INSPECTION

Date of Assignment:	13/11/2020	
Date Inspected:	13/11/2020	Inspected At:
		Volkswagen Centre Singapore (HQ)
		247 Alexandra Road
		Singapore 159934
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPE PRIMED (REAR)	Deformed	1,355.17 FS	*1,355.17 FS
2	1		*BUMPER (BUMPER REINFORCEMENT)	Not Necessary	496.43 FS	*- FS
3	1		*ATTACHMENT STRIP	Necessary	80.13 FS	*80.13 FS
4	1		*GUIDE PIECE (BUMPE GUIDE LH)	Not Necessary	118.81 FS	*- FS
5	1		*GUIDE PIECE (BUMPE GUIDE RH)	Not Necessary	118.81 FS	*- FS
6	1		*BRACKET (BUMPER BRACKET LH)	Not Necessary	45.11 FS	*- FS
7	1		*BRACKET (BUMPER BRACKET RH)	Not Necessary	45.11 FS	*- FS
8	1		*AIR VENT SATIN BLACK	Not Necessary	430.26 FS	*- FS
9	1		*DECORATIVE MOULDING CHROM (RH LOWER CHROME MOULDING)	Not Necessary	117.21 FS	*- FS
10	1		*DECORATIVE MOULDING CHROM (RH CHROME MOULDING)	Not Necessary	117.21 FS	*- FS
11	1		*REAR NUMBER PLATE	Cracked	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,024.25	1,535.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,680.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >