

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012352/KES3Q2
Date: 04/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100359171
Claimant Vehicle No :	SLV7000X	Insured Vehicle No :	SKL6794J
Date of Loss:	05/11/2020	Nature of Claim:	TP
		Claim No:	9379978571SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7000X		
Make & Model:	HYUNDAI ELANTRA, 1.6 Elite (MD) (A)	Engine No:	G4FGHU690248
Reg. Date:	21/12/2017 (Man. Year: 2017)	Chassis No:	KMHD841CMJU590044
Colour:	Metallic Grey	Odometer:	30448 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,148.80	1,405.60	743.20	34.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	640.00	340.00	300.00	46.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,788.80	1,745.60	1,043.20	37.41
+ GST 7.00/7.00% (S\$)	195.22	122.19	73.03	37.41

Nett Amount (S\$)	2,984.02	1,867.79	1,116.23	37.41
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,989.79		

INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 12/11/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	1,757.00 FL	*1,757.00 FL
2	1		*HEADLAMP LOWER BEAM LH	Serviceable	24.00 FL	*- FL
3	1		*FRONT BUMPER	Repair	475.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	28.00 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Not Necessary	20.00 FL	*- FL
6	1		*FOGLAMP LH	Serviceable	266.00 FL	*- FL
7	1		*FOGLAMP COVER LH	Serviceable	116.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,686.00	1,757.00
- List Item Discount on L Items 20.00/20.00% (\$)	537.20	351.40
Total Parts (\$)	2,148.80	1,405.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL ALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	300.00	120.00
3	TO SPRAY FRONT BUMPER	New	300.00	200.00
Gross Labour Cost (\$\$)			640.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >