

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012355/ABA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLJ8458R	Insured Vehicle No :	SHD4571B
Date of Loss: 07/11/2020	Nature of Claim: TP	Claim No: MCT20110124

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8458R		
Make & Model:	NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A)	Engine No:	MR20434239W
Reg. Date:	28/12/2016 (Man. Year: 2016)	Chassis No:	SJNFBAJ11U1796315
Colour:	Bronze	Odometer:	80024 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,488.50	8,143.19	9,345.31	53.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,620.00	2,680.00	62.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,788.50	9,763.19	12,025.31	55.19
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	21,788.50	7,800.00	13,988.50	64.20
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,607.45		
Global Sum Settlement (S\$)		8,600.00		

INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	10/11/2020 Inspected At:	Cn Motors Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 BLK C #01- 41 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2021)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8458R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,934.50 F	*614.60 FL
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
3	1		*FRONT R/H BUMPER SIDE RETAINER	Damaged	29.60 F	*29.60 FL
4	1		*FRONT R/H BUMPER FOG LAMP	Not Necessary	323.70 F	*- FL
5	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	130.10 F	*- FL
6	1		*FRONT R/H BUMPER FOG LAMP REAR COVER	Not Necessary	130.10 F	*- FL
7	1		*FRONT R/H HEAD LAMP	Cut	3,243.00 F	*2,961.00 FL
8	1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	28.10 F	*- FL
9	1		*FRONT R/H FENDER	Dented	753.60 F	*683.00 FL
10	1		*FRONT R/H FENDER COWLING	Not Necessary	128.30 F	*- FL
11	10		*FRONT R/H FENDER COWLING CLIP	Not Necessary	65.00 F	*- FL
12	1		*FRONT R/H FENDER ARCH PROTECTION	Deformed	654.00 F	*483.00 FL
13	8		*FRONT R/H FENDER ARCH PROTECTION CLIP	Necessary	52.00 F	*20.00 FL
14	1		*FRONT R/H DOOR	Repair	1,666.20 F	*- FL
15	2		*FRONT R/H DOOR HINGE	Not Necessary	138.20 F	*- FL
16	1		*FRONT R/H RIM	Cut	1,681.50 FS	*800.00 FS
17	1		*FRONT R/H TYRE	Not Necessary	450.00 F	*- FL
18	1		*FRONT R/H KNUCKLE ARM	Damaged	557.00 F	*557.00 FL
19	1		*FRONT R/H KNUCKLE ARM BEARING	Necessary	348.60 F	*218.00 FL
20	1		*FRONT R/H LOWER ARM	Bent	345.50 F	*224.00 FL
21	1		*FRONT R/H SHOCK ABSORBER	Bent	563.30 F	*421.00 FL
22	1		*FRONT R/H SHOCK ABSORBER MOUNTING	Not Necessary	256.80 F	*- FL
23	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,625.30 F	*- FL
24	1		*FRONT STEERING RACK	Bent	1,917.90 F	*1,917.90 FL
25	1		*FRONT STABILIZER BAR	Not Necessary	401.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,488.50	8,959.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	815.91
Total Parts (\$)	17,488.50	8,143.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT UNDERCARRIAGE ,DRIVE SHAFT & STEERING RACK	New	450.00	350.00
2	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
3	TO CHECK WIRING	New	200.00	30.00
4	TOWING FEE	New	150.00	60.00
5	TUFF KOTE	New	150.00	0.00
6	PANEL BEATING	New	1,600.00	500.00
7	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$)			4,300.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >