

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012357/T1VD3Q2

Date: 07/12/2020

REFERENCE

Insured/Claimant:	LAU CHER SONG VICTOR	Policy No:	1900006985
Date of Loss:	10/11/2020	Nature of Claim:	OD Claim No: 2958185565SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH4039S	Engine No:	G4FGJH716024
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5027492
Reg. Date:	22/01/2019 (Man. Year: 2018)	Odometer:	159800 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,124.00	8,316.40	807.60	8.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	4,570.00	840.00	15.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,534.00	12,886.40	1,647.60	11.34
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	13,534.00	11,886.40	1,647.60	12.17
+ GST 7.00/7.00% (S\$)	947.38	832.05	115.33	12.17
Nett Amount (S\$)	14,481.38	12,718.45	1,762.93	12.17

INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 11/11/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,LH	Cracked	1,219.00 FL	*1,219.00 FL
2	1		*LAMP ASSY-HEAD,RH	Cracked	1,219.00 FL	*1,219.00 FL
3	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	146.00 FL	*- FL
4	1		*HORN ASSY-LOW PITCH	Cracked	74.00 FL	*74.00 FL
5	1		*PANEL ASSY-HOOD	Bent	1,502.00 FL	*1,502.00 FL
6	1		*PANEL-FENDER,LH	Bent	430.00 FL	*430.00 FL
7	1		*PANEL-FENDER,RH	Bent	430.00 FL	*430.00 FL
8	1		*INSULATOR-FENDER LH	Not Necessary	27.00 FL	*- FL
9	1		*HINGE ASSY-HOOD,RH	Bent	43.00 FL	*43.00 FL
10	1		*HINGE ASSY-HOOD,LH	Bent	43.00 FL	*43.00 FL
11	1		*CARRIER ASSY-FRONT END MODULE	Cracked	675.00 FL	*675.00 FL
12	1		*BEAM COMPLETE-FR BUMPER	Bent	497.00 FL	*497.00 FL
13	1		*PAD-HOOD INSULATING	Deformed	156.00 FL	*156.00 FL
14	1		*LATCH ASSY-HOOD	Bent	103.00 FL	*103.00 FL
15	1		*COVER-FR BUMPER	Cracked	633.00 FL	*633.00 FL
16	1		*GRILLE-FRONT BUMPER	Cracked	262.00 FL	*262.00 FL
17	1		*GRILLE ASSY-RADIATOR	Cracked	328.00 FL	*328.00 FL
18	1		*GARNISH-RADIATOR GRILLE	Cracked	38.00 FL	*38.00 FL
19	1		*ABSORBER-FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
20	1		*LAMP ASSY-SIDE REPEATER-LH	Not Necessary	143.00 FL	*- FL
21	1		*LAMP ASSY-SIDE REPEATER-RH	Not Necessary	143.00 FL	*- FL
22	1		*MOULDING-FRONT BUMPER,LH	Cut	36.00 FL	*36.00 FL
23	1		*MOULDING-FRONT BUMPER,RH	Not Necessary	36.00 FL	*- FL
24	1		*STIFFER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
25	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
26	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
27	1		*AIR DUCT-FR BUMPER,LH	Deformed	14.00 FL	*14.00 FL
28	1		*AIR DUCT-FR BUMPER,RH	Not Necessary	14.00 FL	*- FL
29	1		*GUARD ASSY-FRONT WHEEL,LH	Not Necessary	95.00 FL	*- FL
30	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	95.00 FL	*- FL
31	1		*BLOWER ASSY	Cracked	656.00 FL	*656.00 FL
32	1		*CONDENSER ASSY-COOLER	Bent	687.00 FL	*687.00 FL
33	1		*GUARD AIR,RH	Cracked	28.00 FL	*28.00 FL
34	1		*GUARD AIR,LH	Deformed	28.00 FL	*28.00 FL
35	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
36	1		*DUCT ASSY-AIR	Cracked	55.00 FL	*55.00 FL
37	1		*DUCT ASSY-EXTENSION	Not Necessary	115.00 FL	*- FL
38	1		*CLEANER ASSY-AIR	Cracked	174.00 FL	*174.00 FL
39	1		*ORNAMENT-KIA NO 115	Necessary	32.00 FL	*32.00 FL
40	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
41	1		*FRONT NUMBER PLATE WITH FRAME	Missing	50.00 FS	*50.00 FS
42	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
43	1		*CAP-FRONT HOOK	Deformed	9.00 FL	*9.00 FL
44	1		*BUZZER ASSY-PIEZO	Cracked	68.00 FL	*68.00 FL
45	1		*DUCT-EXTENSION	Deformed	5.00 FL	*5.00 FL
46	1		*SENSOR ASSY-KNOCK	Distorted	108.00 FL	*108.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,380.00	10,378.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,256.00	2,061.60
Total Parts (\$\$)	9,124.00	8,316.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BONNET,SUPPORT,FRT LH FENDER & AFFECTED AREA.REPAIR ON FRT RH FENDER,BOTH FRT DOOR	New	2,400.00	1,800.00
2	PAINT WORK FRT BUMPER,BONNET,BOTH FRT FENDER & BOTH FRT DOOR	New	2,100.00	2,100.00
3	REMOVE & INSTALL RADIATOR,AIRCON CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	PERFORM RUST PREVENTION	New	160.00	120.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	TO REPLACE ENGINE COMPARTMENTS	New	200.00	0.00
9	RENEW KNOCK SENSOR AND ENGINE WIRE CONTROL HARNESS	New	200.00	200.00
Gross Labour Cost (\$\$)			5,410.00	4,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >